cc: H.J. Richardson [redacted]

Monsanto

MONSANTO INDUSTRIAL CHEMICALS CO.
1114 Avenue of the Americas
New York, New York 10036
Phone: (212) 764-5000

August 22, 1975

Mr. James Kennedy
Sanders Associates
95 Canal Street
Nashua, N.H. 03060

Non PCB chip

Dear Mr. Kennedy:

It was a pleasure to talk with you regarding capacitor fluids. We are sorry to hear you found Aroclor too "touchy" to use, but we do have some potential replacement fluids.

Our best candidate for capacitor fluids with a high DK is MCS 1238 which is being tested by several manufacturers. It is a non-PCB product.

A gallon sample is being sent to your attention and a data sheet is attached. The other products listed are experimental and not recommended at this time.

We appreciate your offer to include MCS 1238 in your fluid test program, and if you need more data on the product, please advise.

Regards,

Philip L. Slayton/bs

P. L. Slayton
Regional Sales Manager
Specialty Products Group

PLS/bs
Attachment 1
cc: Robert Despathy - Sanders

0439499



TOWOLDMON0057863