


FILE NAME: Friction Materials Standards Institute (FMS)

DATE: 1973 Feb 19

DOC#: FMS025

DOCUMENT DESCRIPTION: Letter to Raybestos from Maremont Corp.



MAREMONT CORPORATION

GRIZZLY/LELAND DIVISION

700 WEST CAROLINE ST. - PAULDING, OHIO 45879 - TELEPHONE (419) 399-3015

February 19, 1973

I. H. Weaver
Raybestos Manhattan
123 E. Stiegel Street
Manheim, Pennsylvania 17545

Dear Mr. Weaver:

It was a pleasure to meet you at the FMSI Asbestos Meeting on February 16, 1973.

Enclosed are samples of the Caution Label that we are now using. The larger label imprinted on the carton by the carton manufacturer is much less conspicuous to the customer.

I will look forward to seeing you again at a future meeting in Paramus.

Sincerely,

MAREMONT CORPORATION

Ralph C. Wyatt
Administration Manager

RCW:et
Encl.

CAUTION
CONTAINS ASBESTOS FIBERS
AVOID CREATING DUST
BREATHING ASBESTOS DUST MAY
CAUSE SERIOUS BODILY HARM

CAUTION
Contains Asbestos Fibers
Avoid Breathing Dust
Breathing Asbestos Dust May
Cause Serious Bodily Harm