PLAINTIFF'S EXHIBIT

UC-3622

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

June 3, 1987

TO: S. J. Chanley
L. C. Stewart

CC: B. D. Mollohan*
G. F. Painter*
M. J. Shoger*
W. N. Stratton*

Re: SHARE Inspection Results

Dear Sara and Larry:

You will find attached a copy of the findings from the SHARE inspection held June 3, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve Kovach
S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

| | 30 Days (July 3, 1987) | 60 Days (Aug. 3, 1987) | 90 Days (Sep. 3, 1987) |
|---|---|---|---|
| % Complete | 60 90 | | |
| Signature | L.C. Stewart S. J. Chanley for | | |

Send copy of update to: B. D. Mollohan - Bldg. 82-3
G. F. Painter - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBH/yc
1658A

Attachment

*Copy of letter only

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT



Department Title: Distribution Misc
Dept. No.: 228/068
Location: Upper Island Misc
Date of Inspection: 6/3/87
Inspector Submitting Report: H. H. Price
Phone No.: 2953
Inspection Responsibility: Insulation
Date of Report: 6/3/87

| Item No. | Description of Substandard Condition | Item Tagged (✓) | Corrective Action Plan: Action Steps or Explanation | Date Correct | Shop Orc Number |
|---|---|---|---|---|---|
| IN 1 | 2 Insulated Lines in #127 | | Take Samples. Remove if Asbestos Facility out of service | Complete | |
| IN 2 | Exposed Ins North of 934 Tank & South 925 Tank overhead East #127 | ✓ | Test Remove if Asbestos Facility out of service | Complete | |
| IN 3 | Exposed Insulation in Rack So. Bldg 128 | ✓ | Check Strip | | |
| IN 4 | ~~Exposed~~ Ins. East #104 & North | | Seal + Strip | | |
| IN 5 | 3 Rooms Ins. on 1st Floor #142 has Canvas #142; Transite 1st Floor #142 | ✓ | Test & Remove | | |

UCC 008449

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT



Department Title: Distribution Misc | Dept. No.: 228/064 | Location: Upper Island Misc | Date of Inspection: 6/3/87

Inspector Submitting Report: HH Price | Phone No.: 3953 | Inspection Responsibility: Insulation | Date of Report: 6/3/87

| Item No. | Description of Substandard Condition | Item Tagged (✓) | Corrective Action Plan: Action Steps or Explanation | Corrective Action Plan: Date Correct | Corrective Action Plan: Shop Ord Number |
|---|---|---|---|---|---|
| IN 6 | Seal Insulation in RACK So West Corner #122 | | | | |
| IN 7 | 4-3" Pipe Insulated Up in ceiling Painted Blue 18' of Each 3 2" lines in same Area So. of Bldg 1st Floor | | Check for Asbeto | | |

UCC 008450