

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
3-3-02	5988	GC#5		Found nothing.	0	NO	William Williams			
20:50	KC	3	8.7	WR.						
3/3/02	5989	GC#5	10.0	#77 spot Liquid Line	10	NO	Tightened snappy Joe	3/3	TC	TC
1:15	65	3	7.7							
3-3-02	5990	GC#3		NO Ring Seal Pac	15	NO	Replaced O Ring on Ring Seal Filler Pac	3-3-02	50R	30R
2:45	RC	10	10.6	50R						
3/4/02	5991	GC#5	8.4 10	Number 2 spot liquid unloading pipe wind pipe (SW)	5	NO	removed nipple, replaced tetraon tape	3/4/02	WR	WR
18:52	GS	4	4.6							
3-4-02	5992	GC#1	8.2 8.1	Found nothing	0	NO	William Williams			
20:45	Bal	3		30R						
3-7-02	5993	GC#1								
1740	B	#7#8	5.1 5.5	P. Williams	NO		nothing found			
							Detected then			

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.

This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.