

Occupational Health and
Safety Products Division/3M

3M Center
St. Paul, Minnesota 55144-1000
612/733 1110

cc: R. E. King
R. M. Pieper

3M

January 15, 1986

Mr. Roger Kane
ROKAN Corp.
103A Industrial Blvd.
Corona, CA 91720

Dear Mr. Kane:

I have enclosed one #3520 Organic Vapor Monitor to replace the #3510 Monitor which was overloaded with methylene chloride.

After you have exposed this monitor, please return it, along with a copy of this letter to Mr. R. M. Pieper, OH&SP/3M, 230-BE-07, 3M Center, St. Paul, MN 55144.

We will analyze the monitor and advise you of the results.

For future monitoring of methylene chloride, I would recommend the use of the #3520 Monitor, which has a much greater capacity for methylene chloride than does the #3500.

Thank you for your interest in our products.

Very truly yours,



J. A. Kvikstad
Senior Technical Service Representative

JAK:smt

Enclosure

3M 010793