

Abex

An IC Industries Company

Memorandum

Date: June 27, 1979

Subject: Horst Becker Visit to Genaut Morganfield Kentucky

From: E. F. Potts

To: L. E. Keenan

Mr. Becker arrived at the Morganfield Kentucky Plant on 6/25/79. The plant was closed for vacation, but Mr. Becker was able to contact a Mr. W. Warlen. He was unaware that Mr. Becker was going to be in Morganfield on Monday.

Mr. Becker conducted a sample audit of all riveted disc brake assemblies on hand. Five (5) different part numbers were checked and loose pucks were found in one shipment of one part number (728AD). The sample indicated that there were approximately 10% of the pieces checked that were loose. The material was date coded KE which stands for May 1979.

Mr. Becker authorized Mr. Warlen to return the 6,000 pieces identified with this date code to the Winchester Plant for credit. He also instructed Mr. Warlen to obtain replacement parts by contacting the Customer Service Department at Winchester.

During the visit, Mr. Warlen contacted Mr. W. Devoe at Mr. Becker's request. Mr. Warlen indicated that Mr. Devoe had found some loose 728AD pucks in the Stephensville Plant, but could not be more specific.


The sample inspection of the 55 part numbers in finished goods and in the in-process pool revealed some loose rivets in 9 of the 55 part numbers. However, no loose pucks were found in this inspection. The 9 part numbers are being reworked 100%.

Mr. Becker has investigated the Quality Controls for the operation and is satisfied that corrective measures are now in effect to control this operation.

BT
NO ADDITIONAL INFO ON STEPHENSVILLE
SITUATION. BECKER WAS TOLD BY
WARLEN THAT DEVOE WOULD HANDLE
THAT DIRECTLY WITH YOU:

EFP/dh

cc: H. Becker



E. F. Potts

SCF-ABEX-2258