PLAINTIFF'S EXHIBIT

DOW-2064

BID PACKAGE GUIDE

May 30, 1979

BY

J. W. FEATHERHOFF

ST0416187

ST0416187

BID PACKAGE GUIDE

INDEX

SECTION	TITLE	PAGES
1	INTRODUCTION	1
2	BID PACKAGES	1-2
3	JOB SPECIFICATIONS	3-6
4	DRAWINGS	6-10
5	MISCELLANEOUS	10-11

ST0416188

ST0416188

APPENDIXES

APPENDIX	TITLE	PAGES
A	BID PACKAGE POLICY AND PROCEDURES	12-20
B	PENCIL JOB SPECIFICATION FORM	21
C	PENCIL JOB SPECIFICATION EXAMPLE	22
D	TYPED BRIEF JOB SPECIFICATION EXAMPLE	23-26
E	LONG JOB SPECIFICATION EXAMPLE	27-70
F	BID INFORMATION	71-73
G	SPECIAL CONDITIONS	74-77
H	SCOPE OF WORK	78
J	WORK DONE BY OTHERS	79
K	OWNER FURNISHED MATERIALS	80-81
L	EQUIPMENT	82-85
M	PAINTING	86
N	INSULATION	87
P	DEMOLITION	88
Q	DISPOSAL	89-90
R	BID PACKAGE REVIEW FORM	91
S	LABOR REQUISITION FORM	92-94
T	SITE VISIT REPORT FORM	95
U	CONTRACT SUMMARY REPORT FORM	96
Y	PROCESS SECURITY	97-99
Z	BID PACKAGE CHECK LIST	100-104
AA	CFI CONTRACT FORM	105-113
BB	DFI CONTRACT FORM	114-123
CC	COST PLUS CAPITAL PROCEDURES	124-125
DD	INSTRUCTIONS TO BIDDERS	126

ST0416189

ST0416189

Concrete and Rubble

All contracts which will result in large amounts of rubble should contact Environmental Services, phone 2471, prior to job site visit.

Metal & Plant Equipment

All contracts which will result in large amounts of scrap metal and used equipment should contact Material Recovery, phone 3127, prior to job site visit.

Lumber

Lumber must first be segregated and sized.

1. Acid bar lumber must be kept separated from normal lumber.

2. No pieces over 4' x 8' will be accepted.

   a. Cribbing, heavy packing boxes and the big shipping supports should be broken down to a reasonable size that can be handled easily.

3. All lumber must have a burning permit from the Material Recovery group, B-8701.

Trash

Trash must not contain metal, lumber, asbestos or foam plastics (styrofoam, urethane foam, etc.).

1. The dump ground operator or the operator at B-5102 must be contacted before dumping.

Asbestos

Asbestos should be contained in plastic bags marked to indicate that they contain asbestos product. Asbestos is never to be mixed with any other trash.

1. The dump ground operator or the operator at B-5102 must be contacted before dumping.

Foam, Plastics, Polyethylene

These are to be dumped at B-5103, in the area of the closed incinerator It must not contain trash.

1. Before dumping, the operator at B-5103 or B-5102 must be contacted.

ST0416190

ST0416190

DISPOSAL

Liquid Waste

Liquid waste requires a disposal tag. This tag is available only from Envrionmental Services, phone 2691. It is vital that these tags be filled out completely and accurately with all known substances listed. This is the only way the safety of the operators may be maintained.

If there are any questions, please contact:

E. A. Campbell	2228
Harry Allison	2471
Ed Allison	2471
Environmental Svcs	2691

ST0416191

ST0416191