FILE NAME: .dzŦŦl·fƨ tdzƳLJă ó. t{ú

DATE: мфпо Wl·y

DOC#: . t{лло

DOCUMENT DESCRIPTION: ¢Nl·ŘŜ Wƨdz№yl·t !NjűλŎfŜ π {l·ŦŜűè λy l l·yŘfλyヨ !fdzYλydzY t2øŘŜNjă

CHEMICAL & METALLURGICAL ENGINEERING

In this Issue

Volume 68 JANUARY, 1943 Number 1

Our Year II of World War II..... 75
EDITORIAL FOREWORD

Waste Disposal Problems in Wartime..... 76
By P. W. MOHNKEN

Safety in Handling Aluminum Powders..... 82
By G. M. BABCOCK and F. D. RETHWISCH

Progress Report of the Rubber Director..... 85

Selection of Pumps for Oleum and Strong Sulphuric Acid.... 86
By WARD E. PRATT

Effect of the Kinetic Energy Term in Gas Flow Calculations.. 90
By BENJAMIN MILLER

Nylon Research Wins its War Wings..... 92
EDITORIAL STAFF REPORT

Manufacture of Butadiene From Ethyl Alcohol—II..... 94
By J. A. CARMER and T. ROUVE

Labor Relations and Collective Bargaining in Chemical Industry..... 99
A CHEM. & MET. REPORT

Chrome Tanning Leather..... 112
A CHEM. & MET. PICTURED FLOWSHEET

Chem. & Met. Plant Notebook . . 98
Process Equipment News . . . 107
Chemical Engineering News . . 119
News From Washington 121
Interpreting Washington 124
New Products and Materials . . 126
From the Log of Experience . . 134
Personalities 137
Meetings and Conventions . . . 145
News From Abroad 153
Chem. & Met. Bookshelf 167
Chemical Economics and Markets 175
Current Prices 187
New Construction 190

An index to advertisers will be found on page 28A

E. D. KIRKPATRICK . . . . . Editor
JAMES A. LEE..... Managing Editor
THEODORE R. OLIVE.....Associate Editor
RETHY M. BATTERS.....Market Editor
JOHN R. CALLAHAN .... Assistant Editor
NORMAN G. FARQUHAR .Assistant Editor
LESTER B. POPE .... ..Assistant Editor

EDITORIAL REPRESENTATIVES
E. E. STATELER.. .. .. .. .Chicago
R. S. McBRIDE.. .. .. .. .Washington
EARLE MAULDIN. .. .. .Atlanta

M. R. WILLIAMSON . . Publisher

DISTRICT MANAGERS
E. H. BEDELL .. .. .New York
R. G. FREDERICK.. .. .. .. .New York
FRED GRANT. . .. . .Cleveland
L. A. CUNNINGHAM... .. .. .Chicago
W. D. BOYD. . .. . .Boston
J. R. VAN ARSDALE.. . . Philadelphia

Published monthly. Price 35 cents per copy. Address communications about subscriptions to Director of Circulation, Chem. & Met., 330 West 42 St., New York, N. Y. Subscription rates: United States, Mexico, Central and South American countries, $3 a year, $5 for two years, $7 for three years. Canada, $3.50 a year, $5 for two years, $7 for three years (payable in Canadian funds). Great Britain and British Possessions, 25 shillings a year, 40 shillings for three years. All other countries, $5 a year, $10 for three years. Entered as second class matter, September 2, 1938, at Post Office at Albany, N. Y., U. S. A., under act of March 3, 1879. Contents copyrighted, 1943, by McGraw-Hill Publishing Company, Inc. Branch offices: 520 North Michigan Avenue, Chicago; 68 Post Street, San Francisco; Aldwych House, Aldwych, London W. C. 2; Washington; Philadelphia; Cleveland; Detroit; St. Louis; Burlant Ind. Angeles; Atlanta.

McGRAW-HILL PUBLISHING CO., INC.
JAMES H. McGRAW
Founder and Honorary Chairman

Publication Office
99-129 North Broadway, Albany, N. Y.

Editorial and Executive Offices
330 West 42 Street, New York, N. Y.

JAMES H. McGRAW, Jr ....President
HOWARD EHRLICH, Executive Vice-President
MASON BRITTON.....Vice-President
B. R. PUTNAM.. .. .. .Treasurer
J. A. GERARDI.. .. .. .Secretary
J. E. BLACKBURN, Jr., Director of Circulation

Member A.B.P. Member A.B.C.

Cable address McGRAWHILL, New York



A McGRAW-HILL PUBLICATION

McGRAW-HILL PUBLISHING COMPANY
330 West 42nd Street, New York, N. Y.

Director of Circulation:
Please change my address on Chemical & Metallurgical Engineering

From .....

.....

To .....

Safety in Handling Aluminum Powders

G. M. BABCOCK and F. B. RETHWISCH Reynolds Metals Co., Louisville, Ky.

Chem. & Met. INTERPRETATION

Except for those people who work constantly with aluminum powders, sufficient respect for the explosibility of this material does not appear to exist. With the present widespread use of aluminum powders for the manufacture of military pyrotechnics, need has developed for the more widespread dissemination of information on safe practices in their handling and in manufacturing pyrotechnics. The article which follows is based on the experience gained by the Reynolds Metals Co. in many years of producing and handling metallic powders and is offered as a starting point in the development of safety programs for concerns engaged in or beginning operations in pyrotechnic work. Certain fundamental precautions are discussed by the authors as a service to the industry, but neither they nor their company assume liability of any kind in presenting this information.—Editor.

FLAKE ALUMINUM POWDER, somewhat similar to the material commonly used in aluminum paint under the rather misleading name of "aluminum - bronze powder," is a valuable component of pyrotechnic mixtures used for flares and signals. The high surface area of a given weight of aluminum flake powder makes it easily ignitible when in the presence of oxygen or air. Burning, it evolves a tremendous amount of heat and light. Owing to its low apparent density, fine particles of the material tend to float in air with the attendant danger of violent explosion upon ignition, when a proper ratio of aluminum to oxygen is reached.

A somewhat different aluminum powder, the grained variety, consists of spheres, sausage shapes or irregular grains of aluminum, which are relatively hard to ignite. When mixed with oxygen-producing compounds, the grained powder will burn with the evolution of much heat and light. This material, however, has a high apparent density and low surface area which tends to keep it from suspension in air so that the danger of explosion or fire from aluminum "fog" is almost nil.

Both flake and grained aluminum are shipped in sealed drums with fully removable heads. Those drums should be stored unopened in a separate area wherever possible, since if they are stored along with such chemicals as sulphur, nitrates and others of similar character, a fire from any cause would present a most serious problem. Whenever a drum of aluminum powder is opened for loading or inspection, it should be closed and re-sealed as soon as possible. This not only insures greater safety against fire from external causes but also limits the likelihood of tramp material getting into the powder, or of the powder absorbing water from the air. In one instance a sealed drum of flake aluminum withstood an aluminum dust explosion and subsequent fire without ignition of the drum contents.

There are few practical means of extinguishing fires involving aluminum powder or mixtures containing this powder. Anything which tends to disturb the burning mass may throw the aluminum into the air and result in a violent explosion of tremendous destructive power. It is true that dry sand, carefully placed over a pile of burning aluminum, will smother the flame, but in the excitement attending such a fire, there is danger that the sand will be thrown or shoveled on to the mass, and that the powder will be thrown into the air. There have been several cases where relatively harmless fires have been changed to serious and fatal explosions from this cause.

Consequently, the safer and more prudent rule is to instruct employees to walk out of the building in the case of an aluminum fire, shutting the door securely but as gently as possible to avoid disturbing the burning mass.

All employees should be instructed in procedures to avoid. They should understand thoroughly that water, carbon tetrachloride, fire foam, carbon dioxide and similar extinguishing agents should not be used on aluminum fires. Use of such materials will cause explosions. Night watchman should be instructed to convey this information to any regular or volunteer group which attempts to extinguish an aluminum fire. Furthermore, the use of a fine spray of water from a stirrup pump, such as is used by civilian defense workers on incendiary bombs, should never be used on aluminum powder fires.

It is of utmost importance that local fire departments be informed of these precautions. The department should be provided with complete information and charts regarding those warehouses which contain aluminum, as well as those containing other chemicals. These charts should also be readily available to the watchmen and to the plant's own protection division at all times.

AVOIDING HAZARDS

A source of great danger in the handling of aluminum powder is the presence of foreign substances, particularly hard or metallic materials. Care should be taken to see that closing bolts, nails and similar bits of metal cannot contaminate aluminum powder or pyrotechnic mixtures.

Good plant housekeeping is one of the most effective methods in achieving plant safety and care must be taken particularly in the weighing, mixing and pressing rooms. As little material as is practical should be kept in one place at one time. Scoops for handling powders should be of non-sparking material and the handling should be slow and deli-

berate to reduce dusting to a minimum. Rooms in which powder is handled should be cleaned at frequent intervals, but never during weighing, mixing or pressing operations. All material should be kept in closed containers while cleaning is in progress. If oil is used in the pyrotechnic mixture, special care must be taken to insure that all oily rags or waste are deposited in closed safety cans away from the storage or loading areas. These rags must be disposed of daily. In cleaning, care must be taken particularly to keep all corners, window ledges beams, building steel and other resting places free from dust.

BUILDING PROTECTION

The buildings used for weighing, mixing and loading operations should, wherever possible, be so spaced and protected that fires or explosions in one unit cannot be communicated to other units. Construction should be adapted to the venting of explosions, using either a "soft" wall or roof, or a blow-out panel. All equipment should be located so that the operator has a free path to an outside door, without a mixing bench, press or mixer between him and the door.

All metal in the buildings should be grounded. This not only includes the equipment itself, but also metal window and door frames and other building elements. Clips connected to flexible grounded leads should be placed on all metal drums or other movable equipment. Only explosion-proof motors should be permitted, and for these the controls should be fully inclosed and non-arcing, located outside the workroom so that no worker need be in the mixing or pressing room from the time of starting these operations until they are completed.

All lights should be of a type approved for explosive operations and conditions. Particular care must be taken when automatic or manual tools are to be used in buildings for repairs or changes. When such work is to be carried out, the rooms must first be emptied of all ignitible material and thoroughly cleaned. Fatal explosions have been caused in dust-filled rooms by an arc from the switch of an ordinary flashlight. Therefore, only flash lights, electric lighting and power equipment carrying Underwriters' approval for use in explosive areas and where explosive vapors are encountered should be used.

Wherever possible, both the shoes of workers and the floors should be of a conductive but non-sparking type. Electrical discharges produced by static or lightning are the most difficult safety hazards to control. The danger from static charges produced by friction is greatest in cold, dry weather. Even walking on concrete or composition flooring in non-conducting shoes may produce sparks capable of igniting pyrotechnic mixtures or fine aluminum particles suspended in the air. Even the friction caused by aluminum powder poured from a scoop to a container can create high static charges on the aluminum particles. Particularly in the case of flake aluminum powder, considerable time is required to dissipate this charge.

Several types of non-sparking, conductive floors have been employed successfully.* Three types may be described briefly here, including (1) Magnesite flooring installed over a wood or concrete base, with conductive metal grids placed beneath the surface of the floor and properly grounded; (2) crudsified asphalt composition flooring with a conductive aggregate which also is laid over grounded metal grids, and (3) industrial graphite tile made of a conductive mastic, the edges of the tile being melted together with a hot iron on installation to provide a continuous surface. With this last mentioned type no metal grid is necessary, the tile itself being grounded at various points.



These views, from photos by the U. S. Army Signal Corps, show a thermite bomb demonstration at the Army War College, Washington, D. C.; the upper view shows the bomb beginning to explode, while the lower shows the climax of the explosion where the bomb, having reached a temperature of about 4,000 deg. F., is melting through the slab of steel on which it rests

* Further information on these floors can be obtained from Armstrong Cork Co., Building Products Div., Lancaster, Pa.; the Flintkote Co., Industrial Emulsions Div., 30 Rockefeller Plaza, New York, N. Y.; and the Mastipave Co., 111 Clay St., Brooklyn, N. Y.

The causes of static should be explained to employees, using simple illustrations such as the rubbing of silk in cold weather, or the combing of hair. Belt drives should not be used on machines in the mixing, pressing or loading rooms. Special care should be taken in screen rooms, since the friction of the particles passing over the screens and their temporary suspension and separation in air can build up high static charges. All metal in processing and storage rooms should be grounded and every possibility of a spark from machinery, from broken electric light bulbs, or from the dropping of steel tools should be guarded against. Properly grounded metal containers or spark-proof conductive flooring will permit more rapid dissipation of static charges than wooden containers. Mixes should be allowed to remain at rest for a short time before the mixtures is removed, thus permitting any static charge induced in the metal particles in the mix to be conducted to ground. Simple electroscopes can be made to determine when a mixture is free of static charge.

Adequate lightning protection is an important requirement for the plant handling aluminum powders. The grounding of all metal window and door frames and approved lightning protection of all wiring will largely eliminate the possibility of high charges collecting before or during a thunderstorm and perhaps discharging to the ground with an accompanying flash or spark. Protection against actual lightning strokes is best left to authorities on this subject.[6] Many concerns shut down all mixing and loading operations during severe, nearby lightning storms, the employees leaving the processing rooms during that period. Radio sets are good indicators of approaching electrical storms, but if they are used, they should not be installed in the loading area owing to the hazard they introduce.

Highlights in Avoiding Aluminum Powder Explosions

1. All machinery and all metal door and window frames should be well grounded.
2. All mixing and conveying equipment should be constructed so as to minimize the escape of dust into rooms.
3. Sprinklers, scoops, conveyors and the like should be of non-sparking materials.
4. Motors, as far as possible, should be kept in separate rooms, outside the work-rooms. Where it is necessary to have them in the workrooms, they should be of the explosion-proof, dust-proof, splash-proof and water-proof type of squirrel-cage construction.
5. Dust should not be permitted to collect in workrooms; they should be cleaned several times a day, if necessary, although not while operations are going on.
6. Dust in the air should be kept at a minimum. Most people who do not work constantly with aluminum powder do not fully appreciate the explosibility of this material. Trostel and Frevert[1] state that the lower explosive limit for aluminum powder suspended in air varies with the method of ignition. With an electrically heated glowing wire, or with an arc, the lower explosive limit was found to be at a concentration of 7.0 mg. Al per liter of air, and at a concentration of 13.7 mg. with an induction spark.
7. Lighting of rooms should be provided by dust-proof, explosion-proof bulbs.
8. If necessary to use flashlights, they should always be of an Underwriters'-approved type, for use in explosive atmospheres.
9. All bearings and gears should be kept well lubricated and protected from dust.
10. All employees should wear approved type clothing, without pockets or cuffs, if feasible.
11. Operators engaged in mixing should wear respirators as a health precaution.
12. Safety shoes of a type which are both conductive and non-sparking should be worn by operators.
13. Conductive flooring should be employed if possible.
14. Operators should be instructed that in case of fire, they should walk out and close the door of the room until someone in authority arrives to take charge.
15. Aluminum powders should be stored only in sealed drums and apart from other materials, especially oxidizing agents or easily oxidizable substances.
16. Only dry sand or Underwriters'-approved extinguishers should be used on aluminum powder fires.
17. Care should be taken to prevent foreign substances from getting into aluminum powder.
18. Building construction should follow the recommendations of the National Fire Protection Association.[2]
19. In general, it is advisable to follow most of the precautions usually observed in the handling of explosives.

MIXERS AND PRESSES

Machinery used in mixing and pressing operations should be equipped with outboard dust-proof bearings, which should be kept well lubricated. Excessive temperature rise in any part should call for an immediate shutdown. If a shaft or other part should freeze on a bearing surface, no attempt should be made to loosen the part by force, such as by a hammer blow on the shaft, as long as any ignitible material is in the room. Exposed ring gears or bevel gears should be protected from aluminum-powder-containing materials, liberal applications of a heavy grease minimizing this danger.

The clothing worn by plant employees should be kept clean and free from aluminum dust by frequent washing. Many concerns supply shirts and slacks to both male and female employees, the slacks being made without cuffs. There is a possibility of danger when employees wear their work clothes to their homes before changing. For example, a spark from a cigarette may easily cause fatal burns to a person whose clothing is filled with the dust of a pyrotechnic mixture. Owing to the possibility of static charges, silk and silk-like materials should not be worn at work by employees.

The ideal arrangement in locker rooms for employees is to use a double locker system with an intervening shower or washroom. With this method, a locker is provided for each employee at each side of the shower or washroom. The employee removes his work clothes and places them in the work clothes locker, then takes his shower and continues to his second locker on the other side of the shower room where he secures his street clothing. Thus his work clothes locker is always available for inspection by company officials or for the removal of soiled clothing for replacement with clean clothing. As previously mentioned, spark-proof and conductive shoes should always be worn by employees in the loading and mixing areas.

REFERENCES

1. Trostel and Frevert, "The Lower Limits of Concentration for Explosions of Dusts in Air," *Chem. & Met.*, 38, No. 1, p. 141, Jan. 25, 1931.
2. "National Fire Code for the Prevention of Dust Explosions, 1940," National Fire Protection Association, Boston, Mass.
3. "Rules for Protection Against Lightning," Bulletin 121, U. S. Bureau of Standards. Obtainable from Supt. of Documents, Washington, D. C.
4. Mitchell and Patrick, "Playing with Lightning," Random House, New York, N. Y.

Advertisers In This Issue

Page

Abbé Inc., Paul O. 127
Acme Coppersmithing & Machine Co. 48
Allis-Chalmers Mfg. Co. 5, 16
Allis Co., Louis 223, 224
Aluminum Co. of America 89
Aluminum Ore Co. 214
American Chain & Cable Co. 198, 244
American District Steam Co 142
American Flange & Mfg. Co 44
American Locomotive Co. 236
American Mach. & Metals, Inc. 87, 254
American Meter Co., Inc. 44
American Pipe & Const. Co. 131
American Pulverizer Co. 140
American Smelting & Refining Co. 194
American Tool & Machine Co. 34
American Wringer Co. Inc. 192
Armstrong Mach. Works 128
Atlas Mineral Products of Penna. 231
Atlas Powder Co. 202

Babcock & Wilcox Co. 16, 58, 154-155
Bagpak, Inc. 232
Badger & Sons Co., E. B. 228
Baker & Co., Inc. 44
Baldwin-Hill Co. 188
Barnes Co., I. 232
Bates Co., W. 189
Bausch & Lomb Optical Co 247
Bemis Bro. Bag Co. 243
Bird Mach. Co. 7
Blaw-Knox Co. 31
Blickman, Inc., S. 185
Bolta Co. 249
Bonney Forge & Tool Works 152
Bradley Machinery Co. 376
Brighton Copper Works 243
Brill Equip. Corp 201
Bristol Co. 152
Buell Engrg. Co 235
Buffalo Forge Co. 201
Buffalo Fdry. & Mach. Co 207
Bump Pump Co. 128

Carbide & Carbon Chemicals Corp. 191
Carpenter Steel Co. 254
Cash Co., A. W. 111
Celltote Co. 226
Century Electric Co 36
Chapman Valve Co. 247
Chase Bag Co. 229
Chemical Construction Corp 214
Chicago Bridge & Iron Co 248
Chicago Metal Hose Corp 149
Clapsy Corp. 223
Cochrane Corp. 240
Cohen & Co., L. 248
Cole Mfg. Co., R. D. 250
Commercial Solvents Corp. 204-205
Consolidated Prods. Co. Inc 229
Continental Gin Co. 168
Cooper Alloy Fdry. Co. 148
Copper Engrg. Corp. 91
Corning Glass Works 247
C-O-Two Fire Equipment Co 199
Crane Co. 217

Dehydrating Ventilating Equipment Div. American Mach. & Metals, Inc. 254
De Laval Separator Co 218
De Laval Steam Turbine Co 253
Despatch Oven Co. 151
Diamond Alkali Co. 27
Dicalite Co. 136
Dings Magnetic Separator Co. 181
Dodge Mfg. Corp. 23
Dorr Co., Inc 24
Dougherty, James A. 264
Dow Chem. Co. 193
Downingtown Iron Works 42
Draco Corp. 229
Drakenfeld & Co., Inc., B. F. 273
Dunlop Co. 271
Duriron Co., Inc. 21

Eagle-Picher Lead Co. 253
Edge Moor Iron Works, Inc. 235
Electrical Engineers Equip. Co. 78
Elliott Co. 238
Electric Equipment Co. 200
Emsco Equip. Co. 203
Eppenbach, Inc. 164
Eppley Laboratory, Inc. 204
Ernst-Howell Sales Co. 203
Evans & Co., Victory 228
Everlasting Valve Co. 184

Fairbanks Co. 236
Fairbanks, Morse & Co. 186
Fawcett Inc. 220
Filter Paper Co. 226
First Mach. Corp. 200, 202, 231, 264
Fletcher Works 227
Foster Wheeler Corp. 219
Fiser Corp. Ltd. 237
Foote Bros. Gear & Mach. Corp. 227
Fosboro Co. 46
Fredrick Iron & Steel Co. 188
Fuller Co. 147

Garlock Packing Co. 50
Gelb & Son, S. 250
General Controls 178
General Elec. Co. 28-29, 41
General Elec. Co. Air Conditioning & Refrigeration Dept. 32
Girdler Corp. ..... 2nd Cover, 4, 118
Globe Steel Tubes Co 257
Gladding, McBean & Co. 250
Gaulde Pumps, Inc. 244
Graver Tank & Mfg. Co. Inc 242
Greene, Tweed & Co. 180
Grinnell Co. Inc. 23
Grove Regulator Co 211

Hardinge Co Inc 52
Harvey Bros. 200
Harvey Mfg. Co. 114
Hetherington & Berner, Inc. 256
Hicks Engrg. Co., Inc., S. D. 246
Hodgman Rubber Co. 151
Homestead Valve Mfg. Co 207
Hooker Electrochemical Co 256
Howell Electric Motors Co 53

Illinois Water Treatment Co 146
Ingersoll-Rand 60
Ingersoll Steel & Disc Div. Borg-Warner Corp. 49
International Minerals & Chem Corp. 14
International Nickel Co. Inc 67, 216
Iron & Steel Prods. Inc. 200
Island Equip. & Supply Co. Inc. 203

Jacobsen Co., C. S. 202
Jamar Mfg. Co., D. O. 48
Jeffrey Mfg. Co. 215
Jenkins Bros. 239
Johns-Manville 146
Jones Fdry. & Mach. Co. 246

Kahn Machy. Corp. 204
Kelley & Co., O. S. 262
Kemp Mfg. Co., C. M 182
Kennedy Valve Mfg. Co. 234
Kewaunee Mfg. Co. 257
Knight, Maurice A. 181
Kold-Hold Mfg. Co 254

La Motte Chem. Prod. Co 235
Lapp Insulator Co, Inc. 196
Lawrence Mach. & Pump Corp 224
Leyse & Bowler, Inc. 147
Lebanon Steel Fdry. 235
Lee Metal Prods. Co, Inc 246
Leeds & Northrup Co. 72
Linde Air Products Co. 13
Link-Belt Co. 7, 17
Louis Equip. Supply Co. 220
Lubriplate Div., Fiske Bros. Refining Co. 8
Lukens Steel Co. 249
Lummus Co. 251-252
Lunkenheimer Co. 200

Machinery & Equip. Corp. 204
Maehwart Mfg. & Sell, Co. 11
Marley Co. Inc 225
Master Electric Co. ..... 3rd Cover
McGraw-Hill Book Co. 220
Mercer Engrg. Works, Inc. 158
Merrick Scale Co 224
Metric Metal Works 54
Michigan Steel Casting Co 152
Midvale Co. 49
Midwest Piping & Supply Co. Inc. 45
Miller, Inc., L. 228
Mining Equip. Co, Inc. 125
Monarch Mfg. Works, Inc. 165
Monsanto Chemical Co 128
Morris Mach. Works 142
Morse Chain Co. 44
Mount Vernon Woodberry Mills, Inc. 188
Murray Mfg. Co., D. J. 248

Nash Engrg Co 251
National Box & Lumber Co. 252
National Radiator Co. 261
National Technical Labs. 174
Neville Co. 245
Niagara Alkali Co. 240-242
Niagara Filter Corp. 233
North American Mfg. Co. 47
Nuhem Pres. Corp. 61

Oliver United Filters Inc 213

Pangborn Corporation 164
Patterson, Arthur S. 203
Peerless Pump Div., Food Machy. Corp. 165
Pennsylvania Crusher Co. 228
Pennsylvania Salt Mfg. Co 57
Perez, Marino 260
Perkin-Elmer Corp. 218
Perry Equip. & Supply Co. 252
Peter-Chem Developement Co. Inc. 197
Pfaudler Co. ..... Back Cover
Philadelphia Gear Works 222
Photovolt Inc. 63
Pittsburgh Lectrodryer Corp 192
Pittsburgh Piping & Equip Co. 221
Porter Co., Inc., H. K. 144
Powell Co., Wm. 172-173
Powers Regulator Co. 170
Premier Mill Corp. 235
Pressflex Corp. 223
Pritchard & Co., J. F. 247
Proctor & Schwartz, Inc. 214
Professional Services 224
Pulverizing Machy. Co. 246

Quaker Oats Co. 157

Raymond Pulverizer Div., Combustion Engrg. Co, Inc. 12
Reading Chain & Block Corp. 160
Reading-Pratt & Cady (Div.) American Chain & Cable Co. 198, 244
Reeves Pulley Co. 103
Reichold Chemicals, Inc. 32
Reilly Tar & Chem. Corp. 235
Republic Textile Equip. Co., Inc. 224
Rhoads & Sons, J. E. 248
Richardson Scale Co 250
Roberts Filter Mfg. Co 31
Robins Conveying Belt Co. 48
Robinson Mfg. Co. 166
Roots-Connersville Blower Corp. 174
Rowan Controller Co 205
R-S Products Corp. 130
Ryerson & Son, Inc., J. T. 241

Sarco Co, Inc. 254
Searchlight Section 278-284
Sharples Corp. 18
Shepard, Niles Crane & Hoist Corp. 246
Shriver & Co., T. 248
Solvay Sales Corp. 208
Sperry & Co., D. R. 244
Sprout-Waldron Mfg. Co. 226
Standard Conveyor Co 210
Standard Oil Co. (Indiana) 83-84
Stebbins Engrg. & Mfg. Co. 254
Stein Equip. Corp. 252
Struthers Wells Corp. 241
Sturtevant Mill Co. 140
Sutton Steele & Steele, Inc., Separation Engrg. Corp. 192

Tahar Pump Co. 270
Taylor Forge & Pipe Works 71
Taylor Instl. Cos. 38
Texas Co. 14
Thermal Syndicate, Ltd. 224
Tidewater Equip. & Mech. Corp. 203
Timken Roller Bearing Co., Roller Bearing Div. 217
Timken Roller Bearing Co., Steel & Tube Div. 35
Thanium Alloy Mfg. Co. 232
Tolhurst Centrifugal Div., American Mach. & Metals, Inc. 67
Traylor Engrg. & Mfg. Co. 139
Tube-Turns, Inc. 4
Turner Halsey Co. 168

Union Bag & Paper Co 54
Union Bay State Co. 24
Union Carbide & Carbon Corp. 10, 191
Union Standard Equip. Co. 230
U. S. Ind. Alcohol Co. 19-20
U. S. Stoneware Co. 39-38
Utility Pump Co. 248

Virginia-Carolina Chemical Corp. 208
Vogt Mach. Co., H. 240

Wall-Colmonoy Corp. 250
Watson-Stillman Co. 241
Warren Steam Pump Co. 151
Western Precipitation Corp. 125
Westinghouse Elec. & Mfg. Co. 39
Weston Elec. Instl. Co. 270
Where to Buy 276
Whitlock Mfg. Co. 252
Wickwire Spencer Steel Co. 253
Willey & Sons, Inc., A. R. 45
Williams Pat. Crush & Pulv. Co. 171
Wilson Products Inc. 138
Worthington Pump & Machy. Corp. 195
Wright Mfg. Div. American Chain & Cable Co. Inc. 244
Wyckoff & Sons, A. 276

Professional Services 224

SEARCHLIGHT SECTION
CLASSIFIED ADVERTISING

Business Opportunities 278
Employment Service 278
Patents 278
Positions Vacant 278
Positions Wanted 279
Selling Opportunities 279
Wanted to Purchase 279
Used Surplus Equipment 279-284