

1 Q Then there is a second warning under that,
2 and if you could read what that says for the jury.

3 A When greasing the chassis, do not overlook
4 the lubricating fitting on both rear brake camshafts.
5 It is located at the rear of the brake camshaft
6 bracket just above the radius rod.

7 Q Thank you. I need the book back.

8 You said that, definitely on the Ford Model
9 A, that the brakes were meant to be ground; is that
10 correct?

11 A On some of the very early cars, yes, they
12 had linings that were of a different form than was
13 used today that did require machining.

14 Q I would like to show you another document.
15 Just so it is not confusing, this is not from the Ford
16 service bulletin, this is from another document.

17 But within this on figure 15 it has the
18 special grinder for Ford shoes?

19 A Yes.

20 Q Is that a grinder that would have been used
21 for Ford shoes on Ford Model A vehicles?