

FILE NAME: Allied Signal Bendix (ASB)

DATE: 1976 Dec 10

DOC#: ASB135

DOCUMENT DESCRIPTION: Bendix Ballot RE FMSI Recommending
Procedures for Reducing Asbestos Dust During Brake Servicing

BALLOT

Friction Materials Standards Institute, Inc.
E-210 Route 1
Paramus, New Jersey 07652

Subject: Publication in FMSI Catalogs of Recommended
Procedures for Brake Service Shops

Gentlemen:

- | | YES | NO |
|---|----------|----|
| 1. I favor the Asbestos Study Committee recommending to the Board of Directors the printing of a page in FMSI Catalogs recommending procedures for reducing asbestos dust during brake servicing. | <u>X</u> | — |
| 2. I favor use of the write-up "Recommended Procedures for Reducing Asbestos Dust During Brake Servicing" as written. | <u>X</u> | — |
| 3. Those with <u>comment</u> , and those in favor of rewriting the recommended procedures, please enter comments below. | | |

I PRINTED A PAGE IN THE FIRST CATALOGS STILL DOES NOT GET PASSED
INTO THE HANDS OF THE ~~REPAIR SHOPS~~
THE IDEAL SOLUTION IS FOR REBUILDERS OR OTHER PEOPLE PUTTING
LINING SETS INTO INDIVIDUAL BOXES TO INCLUDE A FOLDED
OR X11 SHEET ON PROCEDURES IN EACH BOX.
THE DRAINAGE OF COURSE IS SEVERAL PENNIES COST.

BY David E. Stein

Company BENDIX - FRICTION MATERIALS DIV.
TELE. N.Y.

Date DEC. 10. 1976