EXHIBIT 3
Deponent Martinez
Date 10/2/12 Rptr ANS
www.depobook.com

JAN 22 1981

U.S. CONSUMER PRODUCT SAFETY COMMISSION

Cleveland Regional Office
55 Erieview Plaza
Suite 520
Cleveland, Ohio 44114
(216) 522-3886

January 20, 1981

Mr. John P. Kennedy, Vice President & General Counsel
O.M. Scott & Sons
- A Subsidiary of ITT-
333 N. Maple
Marysville, OH 43040

Dear Mr. Kennedy:

On 7/18/79 an investigator from this office collected a sample (E-860-1705) of Scott's Turf Builder Lawn Fertilizer, 27 - 3 -3, net weight 27 3/4 lbs., which was subsequently screened by our laboratory for asbestos content.

Dispersion staining characteristics were found to indicate a trace amount of chrysotile asbestos; no quantitative analyses were performed.

We regret any inconvenience to you regarding the inordinate delay in receiving this information.

Sincerely,

Paul E. Phillips

Paul E. Phillips
Compliance Officer
(216)-522-7150

Cincinnati Resident Office
Federal Office Bldg. Rm. 3031
550 Main Street
Cincinnati, Ohio 45202
(513) 684-2972

Detroit Resident Office
McNamara Federal Bldg.
Rm. M-24
477 Michigan Avenue
Detroit, Michigan 48226
(313) 226-4040

EXHIBIT
26
DAVIDSON
PENGAD 800-631-6989