

METHODS

SINGLE LINE PIPE DRAWING SYMBOLS
VALVES


GATE SCREWED




GLOBE SCREWED




FLANGED



SOCKET WELD



AUTO - CONTROL



3-WAY

