

- Inspection
 - gloves, 17
 - ladders, 35
 - mechanical handling equipment, 26
 - rigging equipment, 33
 - rope, 33-34
 - safety, 14, 15
 - safety belts, 35
 - scaffolds, 38
 - tools, 31
 - welding equipment, 42
- Instruction, safety, 14
- Insulation
 - asbestos. *See* Asbestos/RCF
 - permits for removal, 20
- Intersections, traffic at, 6
- Intoxicants, 9
- Jackets, Nomex, 26
- Jewelry, 15, 26
- Job requirements, 18-31
 - access, 27
 - asbestos/RCF, 30
 - confined spaces, 30-31
 - danger tag and lockout, 21-22
 - ductwork, 28
 - electrical work, 23-26
 - excavations, 27, 28
 - hazardous process areas, 18, 19
 - liquids
 - corrosive, 29
 - flammable, 29
 - material handling, 26, 27
 - permits/authorizations, 19-21
 - stability control, 27
 - trash, 30

- Junction switch boxes, 23
- "Keep Out" signs, 40
- Kettles, melting, 44-45
- Laboratory, eye protection, 16
- Ladders, 35, 36
 - head protection under, 16
 - metal, 35, 43
- Lamp holder, 23
- Landfill buckets, 30
- Landscaping, damage to, 9-10
- Lanyards, 35
- Lasers, 48
- Latches, safety
 - on hooks, 33
 - on ladders, 36
- Lawns, damage to, 9-10
- Lead, molten, eye protection for, 17
- Leads, welding, 42
- Leaks of petroleum products, 12, 13
- Leveling screws on scaffolds, 37-38
- License requirements for drivers, 3-4
- Lifelines, 34
 - on scaffolds, 38
- Lighting
 - on road blocks, 39
 - temporary, 23
- Liquids
 - corrosive, 29
 - flammable, 29
 - hot, eye protection for, 17
- Liquor, 9
- Loads and loading, 6
 - control of, 26, 33
 - overhead clearance at docks, 6
 - on scaffolds, 38
- Lockout tag, 21-22