May 15, 1972

Mr. C. L. Fralick, Plant Engineer
International Harvester Company
Construction Equipment Division
10400 West North Avenue
Melrose Park, Illinois 60160

Dear Mr. Fralick:

Thank you for writing May 3 about handling Transformer Pyranol.

On page 4 of the enclosed Askarel Inspection and Maintenance Guide, suggestions for proper handling are given. On page 5 you will note that prolonged exposure to Askarel vapors, such as would be generated at elevated temperatures, must be avoided.

Enclosed is a guide of instructions in the event that you have scrap Askarel. This should be returned to us for incineration. Because of concern of PCB environmental pollution, these transformer fluids should not be discarded into the sewer systems and they should not be introduced into the general environment.

If we can be of further service, please let us know.

Yours very truly,

Paul O. Benignus
Market Manager
Dielectric Fluids

/jp
Enclosures
cc: R. V. Weyland

MONS 091746