Monsanto

FROM (NAME—LOCATION—PHONE): Evan J. Young - Akron 160

DATE : September 5, 1978 CC:

SUBJECT : THERMINOL 55

REFERENCE :

TO :

File Note

When Finch came in to work today he found a small pool of Therminol 55 near one of the pumps.

Apparently this occurred by seepage around a pump seal when the system shut itself off Sunday night owing to cool weather. It is surmised this was caused by a small carbon particle under the seal, which normally would have been washed out by pump action, but interfered with seal action when shut down.

Finch vacuumed up about a gallon of fluid, which he retained in a marked drum. He then spread "Oil Spunge" to absorb the residue, and placed these sweepings in a second marked drum, for indefinite storage.

Evan J Young

E. J. Young

/sh

IN - 10 (REV. 8/77)

PCB-ARCH-EXT0377839