Monsanto

LEVER BROTHERS

CC:

FROM (LOCATION) WILMINGTON

DATE : June 20, 1966

SUBJECT :

REFERENCE :

TO : ~~STAN SHAW and DON ROUSH~~ - ST. LOUIS

Spoke to Art Sullivan today--the fellow responsible for the new Therminol unit at Lever Brothers in Baltimore. Found it most interesting that the problem was never one of leakage. The ball valve in the sight glass on their expansion tank had malfunction indicating that their system was filled even though this was never the case. They subsequently discovered that fluid reached the expansion tank only when it was brought to high temperatures. Needless to say, the system is now filled. Am relieved, in that stress, corrosion, cracking is not an issue here.

Hank (mjt)

HANK GILBERT

HAG/mjt

DSW 435091

IN-10 REV. 8-64

STLCOPCB4088152