

PCB's Found In
Oil-Filled Transformers

- 2 -

A number of states have recently enacted legislation providing for special reporting, labeling and/or disposition of PCB's. Because legislation varies in different states, Westinghouse said it is suggesting that customers institute any special procedures which may now be required unless they determine that oil-filled transformers are free of PCB concentrations.

It has recommended that oil-filled transformers manufactured or repaired by Westinghouse and others be checked for PCB content during maintenance and before disposal.

Westinghouse announced in July it would no longer submit quotes for transformers filled with PCB's for shipment after Dec. 31, 1976.

###

-1076-

NPC00012192

203918