

References

Anderson, A.E. (1969). Wear in brake materials. In: Proc. Amer. Sec. (M. Wear Conf.)

R. Anderson, A.E., Gealer, A.L., McCune, R.C. and Sprys, J.W. (1973). Asbestos emissions from brake dynamometer tests. Proc. Soc. Auto. Engin. Meeting, Detroit, Michigan, 14-18 May, 1973, (Rpt.) 730549.

Ball, M.C., Taylor, H.F.W. (1963). The dehydration of chrysotile in air and under hydrothermal conditions. Min. Mag., 35, 467-482.

Bark, L.S., Moran, D. and Percival, S.J. (1975). Chemical changes in asbestos-based friction materials during performance - a review. Wear, 34, 131-139.

Bates, T.F. and Comer, J.J. (1957). In: Proc. 6th Nat'l. Conf. Clays and Clay Mineralogy, Intl. Monog. Sec., 6, 237-248.

Bayer, S.G., Brown, T.A. and Zumwalde, R.D. (1975). Document TR-84, U.S. Department of Health, Education and Welfare, Public Health Service, National Institute for Occupational Safety and Health, Cincinnati, Ohio.

Berry, E.E. (1971). Thermal analysis of various chrysotiles using evolved water analysis techniques. In: Proc. 2nd Intl. Conf. Physical-Chemical Asbestos Minerals, Louvain Univ., 6-9 September, 1971, paper 2:7 15 p.

Biological Effects of Asbestos (1965). (I.J. Selikoff and J. Churg, Eds.), Ann. N.Y. Acad. Sci. 132(1), 766 p.

Boillat, M.A., Lob, M. (1973). Risk of asbestosis in workers employed in replacing automobile brake linings. Schweizerische Medizinische Wochenschrift. 103(39):1354-1359.

Bouhuys, A. (1975). Fibers and fibrosis. Ann. Intern. Med. 83(6), 898-899.

Bragg, L. and Claringbull, G.F. (1965). The crystalline state. In: "Crystal Structures of Minerals" (L. Bragg, G. Bell and Sons, Ltd., Eds.), Vol. IV, London.

Brindley, G.W. and Hayami, R. (1965). Mechanism of formation of forsterite and enstatite from serpentine. Min. Mag., 35, 189-195.

Burwell, J.T. (1957). Survey of possible mechanisms. Wear, 1, 119-141.

Carroll, W.G. (1962). The manufacture of brake linings. British Plastics, August, 414-417.

Castleman, R., Camarota, L.A., Iritsch, A.J., Mazzocchi, S. and Crawley, R.G. (1975). The hazards of asbestos for brake mechanics. Public Health Reports. Vol. 90 No. 3:251-256.

8005 1885

PQ

PRODUCED BY FORD