

1400 0700 "C" Reena 7/15/81
 (P) Brook lowly 56 / Gary Funderburk covered.

2 Dried the coarse batch from 654/655 into Gaylord & resifted to 680

(3) Straighten up the mixed storage freezer

(4) Isolated 903 recovery compressor ready for Maint @ 0700.

(5) Stained the south recovery cond. down & ready for Maint.

(6) #4 star valve chain broke called in Maint to repair

(7) #6 sensor motor burned out & Maint in to change out.

(8) The west vein return pump is isolated and ready for Maint

(9)