

To _____

From _____

Calculation Sheet

VISTA

A

1986 VCM Leak Detection SurveyVinyl Tank farm

Leak No.	VCM Concentration (ppm)	Drawing No.	Location
1	70	ABER-VTF-F	N. Hookup Station
2	50	ABER-VTF-G	S. M. Hookup Station

New Module

3	250	Aber-1	741 reactor VCM valve
---	-----	--------	--------------------------

Old Module

4	200	ABER LRS-7A	Blind on VCM Charge line
5	250	ABER LRS-4	Pressure gauge SRVCM receiver
6	500	ABER LRS-4	Nipple on SRVCM receiver
7	65	ABER-LRS-2	On/off valve N. RVCM receiver
8	60	ABER LRS-5	RVCM filter inlet valve
9	70	ABER LRS-11	S RVCM condenser
10	250	ABER-LRS-8	D-600 Recovery valve
11	200	ABER-LRS-8	D-600 VCM charge valve

Made By _____

Date _____

Page _____ of _____

Allmond 9944

Job No. _____

Title _____