

Interoffice Communication

To Distribution

From J. H. McCulley, Jr.

Date March 16, 1984

Subject 1983 Vinyl Chloride Safety Association Meeting Report

A report on the 1983 Vinyl Chloride Safety Association meeting is attached. As usual, the meeting was well worth attending. Several major incidents from the past were reviewed to prevent their lessons from being lost. Also a number of interesting audience surveys were made on various safety issues. The results from an industry questionnaire on controlling runaway PVC reactors were of particular interest. The BFG VCM storage tank safety standard and maintenance work standard that were developed as a result of a large (1 1/2 MM pound) VCM release from a sphere need to be evaluated.

Please contact Dick, Steve, or John if there are any questions.

R. A. Frohreich by JHM

R. A. Frohreich
Chief Process Engineer
Aberdeen Plant

Steve Ashby by JHM

Steve Ashby
Safety Director
VCM Plant

John H. McCulley, Jr.

John H. McCulley, Jr.
Chief Process Engineer
Chemicals (Vista) Division
Process Engineering Department

pjc

Enc

CC:

JF:CRM:PEM:RAF:AHS:HDG:AWS:CWT:JPW:

RG:RAC:JWW:SA:SSP:VCL:ELK:RLP:DRW:WLM

PVC Group

File

