

Documents in EPA Docket OPTS 62035 PCB (Fires)

- *6 Toxicity of Soot from PCB Transformer Fires
- * Ambient Water Quality Criteria for 2,3,7,8-TCDD
- ** Final Report on Industrial Hygiene Assessment of PCB Exposure of GSA Switchgear Operators - Johns Hopkins 9/1/81-10/1/82
- *9 Summary of Regional Data on PCB transformer fires
- *11 Preliminary Study and Cost Effectiveness Analysis of Alternative Regulations for Indoor PCB Transformers - Putnam, Hayes & Bartlett 2/84
- *12 Substitutes for PCB's for use in indoor electrical transformers - PEDCo 1/84

- 8 letter to David Dull from Equitable Life Assurance Society of the US
- 19 Putnam, Hayes & Bartlett, Inc. (PHB) w/BOMA
- 21 PHB w/Boston Edison
- 22 PHB w/Commonwealth Edison
- 23 PHB w/Dow Corning Corporation
- 25 PHB w/Factory Mutual Eng. Res.
- 27 PHB w/IT Corp.
- 30 PHB w/Kansas Gas & Electric Corp
- 32 PHB w/Met. Elect. Test Co., Inc.
- 34 PHB w/Pacific Gas & Electric
- 35 PHB w/RTE Corp.
- 37 PHB w/Southern IN Gas & Elect
- 42 PHB w/Southern IN Gas & Elect
- 43 PHB w/St. of CA, Dept. of General Services
- 46 PHB w/Travelers Co.
- 47 PHB w/ NIOSH - Boston Area PCB Transformer incidents
- 48 PHB w/EPA Region I - Boston Area PCB Transformer incidents
- 49 PHB/EPA - PCB Coordinator - PCB Transformer alternatives
- 51 PHB w/West and Hansen Engineers
- 52 PHB w/Westinghouse - Alternatives
- 55 Summaries of German articles concerning transformer explosions
- 56 Summary of 10/3/83 meeting on cleanup of PCB transformer fire at First National Bank Building (Chicago)
- *54 PCB Capacitor Explosion in Finland - Versar, Inc.

- 58 Cases study of contamination : PCBs in feed - Anonymous
- 59 Summary of PCB air sampling results - One Market Plaza - Anon 8/15/83
- ?? Summary of PCB air sampling results for PCBs and TCDGs at One Market Plaza - Anon 9/12/83
- 61 Cleanup after San Francisco Explosion - Bartlett, et al
- 62 Downtown dioxin danger - Burks
- 63 Formation of PCDFs and PCDDs from pyrolysis of chlorobenzenes - Buser 1979
- 64 Formation of PCDFs from the pyrolysis of individual PCB isomers - Buser 1979
- 65 Formation of PCDFs from the pyrolysis of PCBs - Buser 1978
- ?? Toxicology - The Basic Sciences of Poisons - Casarett & Doull, pp 23-25
- 66 Mechanistic aspects of the thermal formation of halogenated organic compounds including PCDFs - Cloughry & Hutzinger 1982
- *67 State-of-Art review: PCDDs and PCDFs in Utility PCB Fluid - EPRI 1983
- 68 Hochgiftiges Clophen spritzte aus den Trafos - Folx 1983
- 69 City crisis began after fire ended (Binghamton) - Geiman 1983
- 70 Tests show PCB danger unlikely at Chimes Bldgs - Heath 1983
- 71 Formation of PCDF during a fire accident in capacitors containing PCBs - Jansson et al 1982

- 72 100 PCBs leaks reported in downtown San Francisco - Melnick 1983
- 73 PCDF formation from PCB mixture by heat and oxygen - Morita et al 1978
- *74 Comparative toxicity of PCBs & Dibenzofurans in rats - Oishi et al 1977
- *75 PCDD and PCDFs and other polychlorinated polynuclear aromatics formed during incineration and PCB fires - Rappe, et al 1983
- *76 PCDDs, PCDFs & other PCPNAs formed during PCB fires - Rappe, et al 1982
- *77 Degradation of PCBs in electrical equipment - RTE Corporation 1982
- 78 Contamination of an office building in Binghamton, NY... - Schechter 1983
- 79 Big PG & E explosion - SF highrise shut - Smith 1983
- 80 Analysis for 2,3,7,8-tetrachlorodibenzofuran & 2,3,7,8-tetrachlorodibenzo-p-dioxin in a soot sample from a transformer explosion in Binghamton, NY - Smith, et al 1982
- *81 Interim guidelines for acceptable exposure levels in office settings contaminated with PCB & PCB combustion products - California Department of Health - Gravitz, et al 1983
- 82 Analysis of Binghamton soot sample for TCDF and TCDD - Smith, et al 1981
- 83 Analysis of 2,3,7,8 TCDF and 2,3,7,8 TCDD in soot sample from transformer explosion in Binghamton - Smith, et al 1981
- 84 Background of Binghamton, NY - DOH 1981
- 85 Determination of PCDF in soot samples.... - Smith, et al 1982
- 86 Determination of TCDFs and TCDDs in air.... - Smith, et al 1983
- 88 Determination of Tetra-hexa CDFs and tetra-CDDs in air samples from.... Binghamton... - Smith, et al 1983
- *88 Revised risk assessment of Binghamton State Office Building - Kim & Hawley 1983
- *89 Comparisons of chemical and biological data on soot samples from Binghamton - Eadon et al 1982
- *90 The Binghamton State Office Building clean-up: a progress report update - NY state office of General Services 1983
- 92 Investigation - Determination of toxic compounds in sprayed-on ceilings - insulators: sampling & analysis of PCBs, PCDDs & PCDFs - VERSAR 1983
- 93 Investigation of contamination remaining in Binghamton State Office Building following preliminary cleanup - VERSAR 1982
- 96 Exposure Assessment: Fires involving PCB transformers - VERSAR 1983 rev. 1984
- 97 Development of Flammability Criteria for Transformer Dielectric fluids - Department of Energy 3/80
- *95 Environmental Assessment of PCBs in the Atmosphere - EPA 1977
- ?? The Carinogen Assessment Group's Risk Assessment on 2,4,5-T, silvex and TCDD - 9/80
- ?? Workers returning to PCB skyscraper - Wegars 1983

* CMA has document
 ** CMA has executive summary