225 STEVENS STREET, GRAND RAPIDS, MICHIGAN 49502 • PHONE (616) 245-0455



DOYLE VACUUM CLEANER COMPANY

May 30, 1975

Mr. S. F. Svoboda
Ford Service Research Center
18751 Oakwood Blvd.
Dearborn, Michigan 48121

Dear Stan:

Enclosed is description of Model AARE 705476 vacuum cleaner for brake service dust recovery, drawings and photos of the product.

Filtration separation and dust retention data have not been included since all such testing was conducted by the Industrial Hygiene Department of Ford Motor Company, their data was never made available to us, and we have relied solely on their acceptance.

Since this product was developed at our expense on the specific request of Ford Service Research Center, we are not able to offer any warranty as to the suitability for brake service dust recovery and our quotation to Ford Purchasing contains a warranty statement to this effect, copy enclosed.

We are still waiting approval of the CAUTION and INSTRUCTION label by Ford legal. We must hold up ordering such labels. We do feel that we should add a statement to the label indicating that all disposable filters should be replaced when the paper collector bag is 1/2 filled with dust or after decontamination. Will you please expedite action by Ford legal.

I trust this is the material you need.

Cordially,

DOYLE VACUUM CLEANER COMPANY

Jack Doyle
President

JD/cp

002767

PRODUCED BY FORD

105477