

FILE NAME: Owens-Corning (OC)

DATE: 1963 Jan 11

DOC#: OC106

DOCUMENT DESCRIPTION: Union Management Meeting Minutes - Notes
Excessive Dust from Trim Saw

UNION MANAGEMENT MEETING
JANUARY 11, 1963

Present:
L. Sandro
L. Marella
A. DePietro
S. Capoferri
C. Streck

R. C. Amos
R. E. Grimmie

Old Business

1. Subject: Still no solution on the storage of LP gas tanks.
Action: Management stated they will study this situation further.
2. Subject: Excessive dust condition at the MPC trim saws still has not been corrected. *Misc*
Action: Larger mesh screen installed in "C" saw. Efforts should be made to see that all outlets not being used are closed.
3. Subject: The Union again requested a restudy of the flat wa're finishing line standards.
Action: Management stated that this was being studied.
4. Subject: The poor condition of some of the cargotainers was again brought to the attention of management. *6/10*
Action: Management will try and keep a man full time on this job; it was also pointed out again that this program could be helped a great deal if truck drivers would take more care and cause less damage.
5. Subject: Union asked again about frequent door openings at the scrap dock.
Action: This door must be opened and closed to get scrap out. Management will investigate shield for molded billet machine and the possibility of quicker opening door. *Shield
between
2 built in*

6. Subject: Some vending machines are frequently empty. jk

Action: Management stated that in the future these machines will be serviced on weekends.

7. Subject: Excessive cold conditions on batch floor.

Action: Management stated a heater will be installed. Df

8. Subject: Dust and dirt still falls from the batch floor to the main floor when the batch trucks are moved across the floor.

Action: Management agrees something should be done. This will be taken care of in the very near future.

9. Subject: Dowtherm fumes and smoke still in dowtherm control area.

Action: Management will continue investigations to improve working conditions in this area. New dowtherm packing is on order for trial.

Spencer
Inlet
Outlet
valves

New Business

1. Subject: Union asked that management give all written reports on all changes affecting the men sooner.

Action: Management stated that these changes will be kept up with sooner in the future.

2. Subject: Union asked for four (4) hours pay for Angelo Tierno who was denied overtime on his regular job.

Action: Mr. Amos said he will talk to Mr. Tierno and the foreman involved and have the situation straightened out.

3. Subject: Union requests some kind of top for lift trucks in mold repair and raw material area.

Action: This has been done for raw material; management said if this proves successful others will follow.

4. Subject: Hoist railing in Mold Shop should be extended.

Action: Management has checked on this and it will be corrected.

5. Subject: Union asked for new clock in Mold Repair area.

Action: A new clock has been ordered.

6. Subject: Union also asked a shear be installed in mold area.

Action: Management stated that this was too expensive at the present time, because shear would be idle 90% of the time.

7. Subject: Union asked for four (4) hours pay involving men who were asked to clean out SID's.

Action: Management stated this situation will be looked into.

A. DePietro
R. E. Grimmie