

MINUTES OF OSIA STEERING COMMITTEE MEETING NO. 16

NOVEMBER 1, 1972

- Baton Rouge

F. S. Venable covered our current position on dealing with hazardous materials.

- Both Humble and Enjay Mechanical Divisions will instigate further action to reemphasize the problem of handling asbestos containing materials.
- Technical will contact Purchasing to get a positive statement in all contracts which will prohibit the use of high asbestos content materials.
- F. S. Venable will begin working with Mechanical to develop noise level data for certain tools.

The Committee began selecting items to be part of the sixth Humble - Enjay Safety Regulations Bulletin.

1. No loose combustible material, empty or full drums or barrels, shall be permitted within the diked area of a tank while it is in service.
2. Machine guarding shall be provided to protect the operator and other employees in the machine area from hazards such as those created by the moving point of operation, nip points, flying chips and sparks.

The remaining items needed to complete the sixth bulletin will be chosen at the next OSIA Steering Committee meeting.

RRDochier, Jr.:msn
November 15, 1972

002215

1B-0000795