

SPICER CLUTCH DIVISION
P.O. BOX 191 • AUBURN, IND. 46706



DANA CORPORATION

Spicer Clutch

March 6, 1973

Mack Trucks, Inc.
Box 1761
Allentown, Pennsylvania
18105

- G50 -
R773 ST 98239
20025

Attention: Mr. D. S. Oplinger

Gentlemen:

Pursuant to our telephone conversation today, enclosed are the prints you requested. These prints are of the cover assembly, driven disc assemblies, and intermediate plate.

The following part numbers make up the installation for Roadway's order using Detroit Diesel 8V-71 engine. Roadway requested dampened, organic (1488 material), 1.750-10 spline in the AS-1402 design.

Prints to
Cage - 3/12/73
127400-1X, AS-1402 Cover Assembly (3200#) 11HBA4152-P3
127261-4X, Front Driven Disc Assembly (1488 Material) 101HB455
127262-4X, Rear Driven Disc Assembly (1488 Material) 101HB456
113C49 Intermediate Plate 597HB327 2
11HBA219 → 107C35-27 Assy includes 274C-6 Drive Pins (6)
When we can be of further assistance, please contact us. 183GC185

Sincerely,

DANA CORPORATION
Spicer Clutch Division

Jerry Rathburn
Jerry Rathburn
Product Engineer
Clutch Engineering

cc JDC
M. T. Hill = w/drawn 8
3/12/73

slr

cc: T. Dickson

Return Prints to DS Oplinger when parts released
1 2 3 1073

TELEX NO. 23-2659 — TELEPHONE 219/925-3800

BUS-0065

DANA-0317.025