Operation Report
Dept. 246 - Aroclor
October - 1964

PRODUCTION SUMMARY

Scheduled -	1,757,000#
Actual -	1,950,819#
% of Schedule -	111%

DOWNTIME

Repair - 4.84% Process - 11.16% Other - 4.44% Total - 20.44%

YIELDS

	Standard	Actual	Y.T.D.
% Theory on Biphenyl -	95.63%	97.30%	97.36%

SIGNIFICANT ITEMS THIS MONTH

#2 Still was equipped with a new horizontal pump and 3" coil which has worked well except when bottoms come off. The way to correct this problem is being investigated. The HCl off gas line plugged due to high Biphenyl concentration in the carry-over. The HCl scrubbing tower plugged backing some water into the system causing failures in blow tanks and in an off-gas spool.

PRODUCT - Aroclor	1st of Mo.	Last of Mo.
Whse. Stock -	817,900#	1,001,835#
Dept. Stock -	640,376#	498,746#
Total -	1,458,276#	1,500,581#

E. E. Martin

ghw

DSW 296480

STLCOPCB4066424