TABLE II

ABBREVIATIONS USED IN VENTILATION DIAGRAMS

Abbreviation	*Meaning*
DP	Drill Press
EG	Edge Grinder
MD	Multipress Drill
PF	Preforming Station
R	Ripper
S	Band Saw
SG	Surface Grinder

The following ventilation diagrams use the above codes and denote where the sampling was done during the special survey at Winchester in the preforming and finishing area.