

SENTRY INSURANCE

October 26, 1971

Mr. David Childress, Manager
Rayloc, Inc.
2680 Horn Lake Road
Memphis, Tennessee

Dear Mr. Childress:

A survey of your plant was made on October 13, 1971, in order to evaluate your employees exposure to asbestos dust. The results of the air sampling, are shown on the attached data sheet, and indicate that the grinder operator is exposed to excessive amounts of asbestos dust. Procedures, findings and a brief discussion are also presented on the attached report of survey.

Based on the survey findings, the following recommendations are made.

Important:

1. Provide annual chest x-ray examinations for all regular operators of the brake lining grinding machines.
2. Shield the existing grinder exhaust system from the outside influence of air currents, such as that from the electric motor housing nearby.

Thank you for your cooperation in permitting me to complete this survey. Please do not hesitate to contact me if you want further technical assistance in complying with these recommendations.


Very truly yours,

Marvin A. Kennebeck, Jr.
Industrial Hygienist

SENTRY INSURANCE A MUTUAL COMPANY

ps

"This report is provided as an advisory service. Its purpose is to advise you on matters that may affect your insurance costs, and to keep you informed on the relationship of your operations to company standards of insurability. By providing this report, and the service call which it confirms, the company does not undertake or assume the responsibility for the discovery and elimination of hazards likely to cause accidents or damage."



NAPA 036

NOV051103

SCF-NAPA-1240