SOUTHERN MANGANESE CORPORATION

DIVISION OF THE SWANN CORPORATION

ANNISTON, ALABAMA

July 11, 1932

IN REPLY REFER TO _____

Aroclor Specifications - 1254

Mr. Logue
Mr. Carothers

To detect contamination of 1254 with 1268 or 1269, the following specification is proposed:

> "Crystallization: The residue remaining after distilling off 94% shall not show crystals on standing 24 hours nor shall crystals appear in the condenser tube at end of the distillation".

Such a specification would prevent shipment of contaminated Aroclor as reported by New England Lacquer Company. The limit of accuracy for such a specification will be determined as soon as time permits.

If this specification is satisfactory, it will be incorporated in our 1254 specifications.

A.B. Gerber

ABG-hp

DSW 312245

STLCOPCB4072231