PLAINTIFF'S EXHIBIT
FWS-16

NAME

ADDRESS

No.	DATE	CUSTOMER	WORK	AMOUNT	S. I. DATE	No.
6194	10-23-64		Relined 2 doors on Perguy Glass oven	1200	11-25-64	P-911-C
6969	6-1-66	Addyston, O.	— All Duraon Const. Co.			
8006	5-22-68	Addyston O.	Reconstruct dumper comp out of plastic refractory repair as quickly as hot spots.	10367	6-5-68	P-385-C
8279	9-30-68	Addyston O.	Misc repairs in #2 B&W Boiler	2100	11-5-68	P-896-C
8503	3-7-69	Nicholas Rd Plt	Install lining in new research rotary kiln	475	3-26-69	P-203-C
8561	4-14-69		Insulation work on experimental Kiln & Harper furnace	800	10-10-69	S-490-C
8565	4-16-69		Line air reheater for experimental kiln	350	5-6-69	P-307-C
8616	5-19-69		Misc. repairs to #3 B&W Boiler Addyston, Oh.	3090	5-27-69	P-370-C
8655	6-6-69	Addyston Oh.	Misc refractory repairs on B&W Blr.	3890	6-20-69	P-418-C
8780	8-4-69	" "	Misc refractory repairs in #4 Boiler	4630	9-9-69	P-710-C
8830	9-2-69	Nicholas Rd Plt	Refractory repairs in rear section of 6 Furnace Scale Machine #6 Furnace	2312	9-25-69	P-797-C
9029	12-19-69	Addyston Plt	Install, operate & maintain 1 unit of 22 W. Blast Lites Portable, operate by batteries in cranes & trucks	1318	1-14-70	P-26-C
9238	5-11-70	Addyston Plt.	Repairs to refractory in #3 B&W Boiler	6696	6-5-70	P-385-C
9272	6-2-70	" "	Install KL Fans on floor of Incinerator	4690	6-6-70	P-592-C
9273	6-2-70	" "	Rebuild burners comp. on Incinerator	3678	8-6-70	P-593-C
9332	7-6-70	Miamisburg	Bros. Boilers & gas piping. Necessary refractory work to convert #2, 3 & 4	120	Vern Weller Co.	
9409	8-12-70	Repairs to Floor		450	9-4-70	S-425-
9457	9-4-70	Addyston Oh.	Repair front wall install 3 #1 K-L mix on floor Boilers	4988	9-22-70	P-794-

S02329