1977-present: (Wagner Step-by-Step Installation Guide for Brake Disc Pads):	"CAUTION - Brake lining materials contain asbestos fibers. Avoid creating dust when removing pads or cleaning caliper and rotor areas. The use of a damp rag for cleaning operations will help aviod dust. Breathing asbestos dust may be a potential health hazard." "Clean road dirt from areas over which brake parts must move. Use a damp cloth for cleaning to avoid raising asbestos dust. Dispose of cleaning rags after use."
1977-present (Wagner Step-by-Step Installation Guide for Drum Brake Shoe and Lining Sets):	"CAUTION - Brake lining materials contain asbestos fibers. Avoid creating dust when removing drums and cleaning parts. Breathing asbestos dust may be a potential health hazard. "With all the brake parts off the backing plate, clean off the backing place with a damp cloth to avoid raising any asbestos dust."
1978-1981 (Wagner Diagnostic Analysis and Reconditioning Manual):	"Since the lining materials contain asbestos fibers, avoid creating dust when removing the drums and cleaning the parts. <u>Breathing asbestos dust may be a potential health hazard</u>. "Clean the backing place and the parts to be reused; wipe with a damp rag to avoid