

NOV 21 1961

PG

10 PL TO PG 11/21

3 PL TO BE

O W PFEIFER PG

CC R F SHANNON PL MAIL

CC R C ARDS BE

CC R E GRIMMIE BE

DID NOT KNOW NEW 18 INCH BAUER MILL DESIGNED FOR DRY MILLING.

EXPECT A DUST PROBLEM UNLESS DUST COLLECTING SYSTEM INSTALLED.

SUGGEST TRY WET MILLING. HV 3 CONSIDERED 18 INCH MILL FOR ASBESTOS

RESERVING 36 INCH MILL FOR DUST ONLY. IN NEW FORMULATIONS MORE

DDUST AND LESS ASBESTOS WILL BE MILLED.

18 INCH PLATES ONLY ONE-THIRD COST OF 36 INCH PLATES. MORE FREQUENT

REPLACEMENTS AT TOTAL LOWER COST COULD BE MADE. END RESULT COULD BE

BETTER CONTROL OVER ASBESTOS FIBERIZATION. DO NOT EXPECT FREQUENT

PLATE RENEWALS WITH DUST USING 36 INCH MILL.

G L KALOUSEK 930 MS

01 036 1181

ALL-STATE LEGAL®

PLAINTIFF'S
EXHIBIT

WV-001786

ALL-STATE LEGAL®

PLAINTIFF'S
EXHIBIT

05355.00