

American Brakeblok Division

May 18, 1971

Mr. Wes Combs
Rayloc
600 Rayloc Drive, S.W.
Atlanta, Georgia 30378

Dear Wes:

The attachment helps explain the significance of the edge coding on linings. There are no doubt a number of jobbers who would welcome this information so as to be sufficiently versed on the subject should a customer raise the question.

You may want to circularize this information in a jobber bulletin.

Sincerely,

Patrick J. Meade
Technical Service Engineer

PJM/pn

Attachment