

FILE NAME: Westinghouse (WH)

DATE: 1979 Mar

DOC#: WH054

DOCUMENT DESCRIPTION: Memo RE Bearing Bracket Sealing (Tite Seal) -
Places Limits on Use of Asbestos Products

Asb. use in 1979
"Tite Seal"

WWS-888317

IN RE: ALBRAMS

November 1992

Generator Installation Service Projects
73-2044
March 8, 1979
Bearing Bracket Sealing (Tite Seal)

Man Made
a copy of this
for Bob Bequest

All PCSD Area and District Managers

Bob I don't know what this
is all about but you should
check

A quantity of Asbestos based Tite Seal has been made available to us. This Tite Seal is to be used on the Exciter End bearing bracket of Generators known to have higher than normal temperatures in the area of the gland seal bracket. To date only the 2-108 x 270 and some of the 2-104 x 245 Generators have this condition, but if during an inspection or outage of any kind the seal in the area in question shows signs of heating "II" charring, shrinking, or hardening contact this office and a quantity of Tite Seal will be sent to the site.

Asbestos free Tite Seal is to be used only in the area between the feed nipples closest to the bearing bracket hub on the horizontal joint and gland seal bracket joint. The remainder of the joint is to be filled with the standard medium weight Tite Seal.

C.C. Rousch
C.C. Rousch
Generator Installation & Service Projects
Power Generation Service Division

RECEIVED
MAR 21 1979

POWER DIVISION
OFFICE



03117355