

ABERDEEN PLANT

VINYL CHLORIDE MONOMER OVEREXPOSURE SUMMARY

FY 1992

DATE	JOB	SHIFT	SAMPLE	RESP.	TASK
2/17	MECHANIC	DAY	3.02	NO	CHANGING SPRAYHEAD - 745 RX
2/17	MECHANIC	DAY	5.98	NO	CHANGING SPRAYHEAD - 745 RX
4/1	MECHANIC	DAY	6.9	NO	BLANKED D-500 CONDENSER
5/9	OU "A" OP	NIGHT	3.4	YES	CHANGING VCM FILTERS
6/16	MECHANIC	DAY	1.06	YES	REMOVED BLANK FROM RECOV. LINE
7/10	MECHANIC	DAY	1.8	YES	CHANGING OUT 903 COMPRESSOR
9/14	CHF. OP.	DAY	1.9	NO	UNKNOWN

FY 1993

11/15	MECHANIC	DAY	25.8	YES	RMV/RPLC RAM VALVE ON D400
11/19	MECHANIC	DAY	1.5	NO	CHG. RX SEAL ON 742
2/24	SHFT SUP	DAY	21.33	YES	OPENED D600 RX - HYDRO
3/3	MECHANIC	DAY	11.7	NO	LIQ. VCM LINE, WRKD ON CORKEN
3/15	OPERATOR	A	6.9	YES	CHNG RING SEAL H2O FILTERS
3/25	MECHANIC	DAY	2.0	NO	UNKNOWN