

Monsanto

FROM (NAME & LOCATION)

R. V. Sharp - Texas City, Purchasing PER(Ext. 3211)

PLAINTIFF'S EXHIBIT

MON-1231

DATE

April 26, 1985

cc.

R. A. Forsthoffer
Jake Linkey
Roger Mears
SHAC

SUBJECT

Second Quarter Safety & Housekeeping
Inspection - AN-5

REFERENCE

TO : D. A. Barfoot AN-5

The Second Quarter Safety and Housekeeping Inspection for AN-5 was conducted by the Inspection Team of George Pappas, Jake Linkey, Roger Mears and Rick Sharp on April 23, 1985.

General Comment:

1. Bypassing interlock system - good procedure that is working.
2. AVIP - totally in compliance.
3. Plectrons - working O.K.
4. Department has several task forces working on improving safety in handling of high hazardous materials. Operations feel knowledgeable about materials that they are handling.

South:

Safety

1. Scaffolding on west side of E-12 had no toe board.
2. Could find no light on HCN alarm on 21.
3. Homemade wooden ladder on deck below SO₂ rotometers on 1st level.
4. Breathing air station on top deck not mounted.
5. Other breathing air stations have no covers.

Housekeeping

1. General clutter under 51D1-1.
2. Rope in pipe rack above SO₂ building.
3. Scaffolding material and sheet metal tubing laying loose on top of deck.
4. General housekeeping - good.

North:

Safety

1. Sign on N.E. corner of dept. needs replacing (HCN Warning sign).
2. Cover goggle sign next to PS-25 nearly illegible.
3. N₂ cylinder not chained at N₂ rack by 51R1-2.

4. Portable building (used in shutdown) not tied down.
5. 51P4-6 breathing air line has no handle on valve.
6. Electrical box about 30 feet off ground in northwest corner of department has no cover and tie-ins are exposed.
7. Steam-line next to 51P94-1 needs insulation to be re-installed.
8. Fresh air hose near southwest corner of control house needs inspection.
9. Safety shower light near pit (old 24) burned out.
10. Water hose near 51S18-2 needs inspection.

Housekeeping:

1. Doors on oil storage/portable pump locker needs to be fixed-wired together now.
2. Insulation pads on 51P5 laying on floor - need to be re-installed.
3. Need bicycle rack at slip-stream control house.
4. General Housekeeping - good.

Please respond in writing to R. A. Forsthoffer by May 17, 1985.



R. V. Sharp

RVS/ps

SC

000324

LAM001521