



05
Ontario

LIBERTY MUTUAL



United California Bank Building, 315 Pomona Mall West, Pomona, California 91766 • Tel. (714) 623-6965

February 8, 1973

Mr. Al Drzewinski, Plant Manager
Kelly-Moore Paint Co., Inc.
1400 South Campus Avenue
Ontario, California

Dear Mr. Drzewinski:

This letter will confirm my visit to the plant on January 19, 1973.

Due to the fact that you were away from the plant at the time of my visit, we did not have an opportunity to accomplish the following objectives:

1. Conduct a joint Safety Survey in the plant.
2. Followup on previously submitted Safety Survey recommendations.
3. Review serious injury incurred by Sidney Agent, Truck Driver, on 12/28/72.

We will complete these objectives during my next visit to the plant.

Yours very truly,

R. V. Ekersall
R. V. Ekersall *per Et*
Loss Prevention Consultant

RVE:vlc

cc: Mr. H. Lambert, General Mgr.-Southern Division
Mr. W. Dusseldorf, Prod. Mgr.
Mr. W. E. Moore, President
Mr. G. W. Voshatzner, Secretary-Treasurer
- Mr. R. Miller, Prod. Mgr.

KMX 00616

OSHA - Ontario

KELLY-MOORE MEMO

SOUTHERN DISTRICT

TO Bob Miller

FROM Al Drzewinski

DATE 1-15-73

SUBJECT FORM NO. 102 OSHA

Form No. 102 "Summary of Occupational Injuries and Illnesses" have been completed and posted on all bulletin boards throughout the plant.

Al Drzewinski
(in hospital)

Jana Miller
Jana Miller

KMX 00617

OSHA - Ontario

KELLY-MOORE MEMO

SOUTHERN DISTRICT

TO Bob Miller FROM Roy Remus DATE 1-12-73

SUBJECT OSHA POSTING REQUIREMENTS

Compliance with posting requirements by the Southern Division
have been met as of this date.

RR/bc

cc: J. Martin Lambert

KMX 00618

CSAA - Ontario

LIBERTY MUTUAL



United California Bank Building, 315 Pomona Mall West, Pomona, California 91766 • Tel. (714) 623-6965

January 4, 1973

Mr. Al Drzewinski, Plant Mgr.
Kelly-Moore Paint Co., Inc.
1400 So. Campus Avenue
Ontario, California

Dear Mr. Drzewinski:

This letter will confirm our conference on December 6, 1972.

On September 7, 1972 Mr. J. Thorne, Liberty Mutual Industrial Hygienist, collected filter paper samples in selected areas of the Ontario plant for analysis for airborne asbestos concentrations. The samples were analyzed in our Hopkinton Laboratory utilizing a phase contrast microscope.

We reviewed the attached Data Sheet which indicates that all of the employees in the areas where samples were collected are exposed to asbestos concentrations in excess of the currently accepted Threshold Limit Value of 5 fibers of asbestos greater than 5 microns in length per milliliter of air based on an eight hour work day and the proposed Threshold Limit Value of 2 fibers greater than 5 microns in length per milliliter of air. As indicated, the current Threshold Limit Value is based on an eight hour workday; however, it carries a 10 fiber per milliliter ceiling which was also exceeded.

As I indicated to you, Mr. Thorne and members of our staff recently met with Mr. Moore in San Carlos and it was decided that no action will be taken in Ontario until our recommendations are completed at the San Carlos plant and a resurvey conducted. Our recommendations would be essentially the same at the Ontario plant.

I presented you with a copy of the San Carlos plant Evaluation of Airborne Asbestos Report of July 7, 1972 for your review and records.

As a result of Mr. Thorne's Ontario Plant Evaluation Survey, it is recommended that:

KMX 00619

BAG BALER

Empty bags of asbestos and other material are baled in an open baler. This can add to the overall excessive concentrations of asbestos fibers in the work environment. Consequently, it is suggested that the baler be enclosed as much as possible and exhaust ventilation should provide a velocity of not less than 80 to 100 linear feet per minute at any opening while the baler is in the crushing or baling cycle.

Yours very truly,

R. V. Eckersall
R. V. Eckersall, *and Brock Hurst*
Loss Prevention Consultant

RVE:cb

cc: Mr. M. Lambert, General Mgr. - Southern Div.
Mr. W. Dusseldorf, Prod. Mgr.
Mr. W. E. Moore, President
Mr. S. V. Vachetzer, Secretary-Treasurer
✓ Mr. R. Miller, Prod. Mgr.

KMX 00620

OSHA-TEXAS

**LIBERTY
MUTUAL**



100 North University Drive, Fort Worth, Texas 76107 • Tel. (817) EDison 2-8411

December 24, 1972

**Mr. Wayne Hargy
Production Manager
Kelly-Moore Paint Company, Inc.
Texas Division
301 Hurst Boulevard
Hurst, Texas**

Re: 1972 PRODUCTION VISIT AT HURST, TX, 12/11/72

Dear Mr. Hargy:

At this visit I assisted you with a safety meeting and also discussed with you a recent serious accident. This accident involved Michael Hall who turned over a fork lift. This was apparently due to reckless driving on the part of the operator.

As a result of this accident, the film, "Color of Danger", was shown again. Hopefully, as a result of this accident and of the film, fork lift operators will exercise more caution than they have in the past.

The best control for accidents of this sort will be to make sure that all operators of fork lifts are as thoroughly trained as possible. A formal training program should be followed for each operator. I will be contacting you in the near future concerning such a program. This would include behind the wheel training, a review of safety rules, and a written test.

Sincerely,

W. L. Latta, Jr.
W. L. Latta, Jr.

WLL/ep

**cc: Mr. Lee Fulkerson, Controller
cc: Mr. William E. Moore, President
cc: Mr. Glenn H. Vachutian, Secretary-Treasurer
cc: Mr. Robert Miller, Production Manager**

KMX 00621