

EMPLOYEE EXPOSURE SUMMARY

QUARTER 1 YEAR 1979PLANT CA II BLOCK 3601 STRESS HCRD MINIMAL DETECTABLE LIMIT AND UNIT 1 ppb

			PERSONNEL					AREA				EXCURSION			
NO.	JOB CLASS	AREA/TASK	*PT. EQ.	TWA BASIS	NO. SAMPLES	AVG.	HIGH	SAMPLE DURATION	NO. SAMPLES	AVG.	HIGH	EXCUR. DURATION	NO. SAMPLES	AVG.	HIGH
01	OTT														
02	OT														
03	SOT														
04	OS														
05	SS														
06	EDO	2/7	2									8 Hr.	1	9.7	9.7
07	LAB														
08	TECH														
09	CLER.														
10	INSTR														
11	LABORER														
12	SUMMER														
13	CONT MAINT														
14	NON-OS SPEC.														
15	SECUR.														
16	MATL CONT														
17	LOADING														
18	T/C CLNG														
19	MGRS/NON-OP														
20	AREA SAMP (NO JC)														

DO 093359
CONFIDENTIAL

DO 093359
CONFIDENTIAL

PROTECTIVE EQUIPMENT: (1) Mouthpiece (2) Full Face (3) Half or Dust Face (4) Air Supply (5) Hearing Protection

EMPLOYEE EXPOSURE SUMMARY

QUARTER 1 YEAR 1979PLANT CA IIBLOCK 3601 STRESS DEADMINIMAL DETECTABLE
LIMIT AND UNIT1 ppb

NO.	JOB CLASS	AREA/ TASK	PERSONNEL					AREA				EXCURSION			
			*PT. EQ.	TWA BASIS	NO. SAMPLES	AVG.	HIGH	SAMPLE DURATION	NO. SAMPLES	AVG.	HIGH	EXCUR. DURATION	NO. SAMPLES	AVG.	HIGH
01	OTT														
02	OT														
03	SOT	4	0	8hr	1	5.1	5.1								
04	OS														
05	SS														
06	EDO														
07	LAB														
08	TECH														
09	CLER.														
10	INSTR														
11	LABORER														
12	SUMMER														
13	CONT MAINT														
14	NON-OS SPEC.														
15	SECUR.														
16	MATL CONT														
17	LOADING														
18	T/C CLNG														
19	MGRS/NON- OP														
20	AREA SAMP (NO JC)														

DO 093360
CONFIDENTIAL

PROTECTIVE EQUIPMENT: (1) Mouthbit (2) Full Face (3) Half or Dust Face (4) Air Supply (5) Hearing Protection

EMPLOYEE EXPOSURE SUMMARY

QUARTER 1 YEAR 1977PLANT CA IIBLOCK 3601 STRESS HEARDMINIMAL DETECTABLE
LIMIT AND UNIT 1 ppb

NO.	JOB CLASS	AREA/ TASK	PERSONNEL					AREA				EXCURSION			
			*PT. EQ.	TWA BASIS	NO. SAMPLES	AVG.	HIGH	SAMPLE DURATION	NO. SAMPLES	AVG.	HIGH	EXCUR. DURATION	NO. SAMPLES	AVG.	HIGH
01	OTT														
02	OT														
03	SOT	5	0	8 hr	1	4.0	4.0								
04	OS														
05	SS														
06	EDO														
07	LAB														
08	TECH														
09	CLER.														
10	INSTR														
11	LABORER														
12	SUMMER														
13	CONT MAINT														
14	NON-OS SPEC.														
15	SECUR.														
16	MATL CONT														
17	LOADING														
18	T/C CLNG														
19	MGRS/NON- OP														
20	AREA SAMP (NO JC)														

DO 093361
CONFIDENTIAL

* PROTECTIVE EQUIPMENT: (1) Mouthbit (2) Full Face (3) Half on Dust M

EMPLOYEE EXPOSURE SUMMARY

QUARTER 1 YEAR 1979PLANT CA IIBLOCK 3601 STRESS HCBMINIMAL DETECTABLE
LIMIT AND UNIT 1 ppb

NO.	JOB CLASS	AREA/TASK	PERSONNEL					AREA				EXCURSION			
			*PT. EQ.	TWA BASIS	NO. SAMPLES	AVG.	HIGH	SAMPLE DURATION	NO. SAMPLES	AVG.	HIGH	EXCUR. DURATION	NO. SAMPLES	AVG.	HIGH
01	OTT														
02	OT														
03	SOT	2/2	2									4 hr/day	2	151.8	283.4
04	OS														
05	SS														
06	EDO														
07	LAB														
08	TECH														
09	CLER.														
10	INSTR														
11	LABORER														
12	SUMMER														
13	CONT MAINT														
14	NON-OS SPEC.														
15	SECUR.														
16	MATL CONT														
17	LOADING														
18	T/C CLNG														
19	MGRS/NON-OP														
20	AREA SAMP (NO JC)														

DO 093362
CONFIDENTIAL