

Lead Industries Association

420 LEXINGTON AVENUE

NEW YORK 17, N.Y.

CLINTON H. CRANE, PRESIDENT
K. C. BROWNELL, VICE PRESIDENT
F. W. ROCKWELL, VICE PRESIDENT
ROBERT LINDLEY ZIEGFELD
SECRETARY-TREASURER


MANFRED BOWDITCH
DIRECTOR OF HEALTH AND SAFETY

November 19, 1951

Dear Bob:

I have just returned to my office after six weeks' absence and find among the mass of correspondence on my desk an inquiry relative to the possibility of a lead hazard in the welding of such lead-bearing steels as the Inland Steel Company's "Ledloy." Since this contains a maximum of 0.25 per cent lead, I would consider any such hazard quite remote, even in confined spaces. However, there appears to have been no study made of this question and I therefore write to ask your opinion. If by any chance there has been some report on this that I have missed, the reference would, of course, be appreciated. I am quite aware of the fact that there is a lead hazard in the manufacture of such steels.

Sincerely yours,



Robert A. Kehoe, M.D., Director
Kettering Laboratory of Applied Physiology
University of Cincinnati
College of Medicine
Eden Avenue
Cincinnati 19, Ohio

MB:JA

KE 0014980

