

JUN 10 1982

F2J76

5547* LBS.

COMTYP JOB NAME: 01YE698DM3

TYPED BY: JMW

(DATE) (LOT) (NET WGT)

EQUIP MENT	NAME: MOLYBDATE ORANGE	USE LBS	N-CODE	ACCT LBS
PREP				
1	1 OBTAIN FOR S-20	84	108-A	84
	2 CALCULATE & SET ON BADGER METER FOR S-23 64.76%	72	33-D	50
	3 OBTAIN FOR S-28	734	4-A	73
	4 OBTAIN FOR S-32	146	3-A	146
	5 OBTAIN FOR S-34	237	32-D	237
	6 OBTAIN FOR S-38	350	3-A	350
	7 OBTAIN FOR S-41	70	711-B	70
351 2	8 WEIGH INTO V-351 CHECKED BY: # 196.3895%	4840	10-D	1885
359 3	9 WEIGH. IN. OPTR _____, MK 35, T-360, 24.47% OPTR _____, MK _____, T- _____, _____%	1238	423-D	356
SV 4	10 RUN 20" (996 G) WATER INTO V-245			
	11 RUN IN FROM V-354. OPTR 60, MK 350, *F RECORD: G/ML 1.312 (1.270-1.328) 26.40% RECORD: PH 2.0 (2.2-3.7)	11992	41-D	5110
	12 ADJ TO 76" (3625G) AT 67-69°F RECORD: TEMP 69 *F		57-A	
	13 STIR 5 MIN & RECORD: PH 3.1 (2.2-3.7)		33-D	
	14 IF NECESSARY, ADJ TO PH 3.0-3.1 ASSUME 60% RECORD: PH _____		7-D	
	NOTE: DILUTE N-7-D 10:1 WITH WATER BEFORE ADDING ASSUME 50%			
	15 RECORD: 1.142 G/ML (1.142-1.144) NOTE: IF G/ML OUT OF LIMITS FILL OUT CHECK LIST & ATTACH			
	16 STIR AT 67-69°F FOR S26. TAKE 1 QT SAMPLE.			
358 5	17 RUN 10" (500 G) WATER INTO V-358			
	18 RUN V-359 INTO V-351 & PUMP IN V-351			
	19 ADJ TO 55" (2600 G)			
	20 SIFT IN N-108-A FROM S 1			
	21 STIR 5 MIN & RECORD: PH 10.5 (9.0-10.0)			
	22 ADJ TO PH 9.8-9.9 & RECORD: PH 9.9 ASSUME 50% ASSUME 60%		7-D 33-D	
	23 ADD N-33-D FROM S 2 USING BADGER METER			
	24 ADJ TO 66" (3121 G) AT 67-69°F RECORD: VOL 66" & 69 *F			
	25 STIR 5 MIN & RECORD: PH 7.7 (7.4-7.6) & G/ML 1.082 (1.080-1.083) NOTE IF G/ML OUT OF LIMITS FILL OUT CHECK LIST & ATTACH. TAKE 1 QT SAMPLE			

JUN 18 1982

	26	OBTAIN 1 QT SAMPLES OF S-16 & S-25 SOLUTIONS & TITRATE TWICE RECORD: LOWEST PH <u>2.12</u> & ML N-10-D <u>7.48</u> LOWEST PH <u>2.22</u> & ML N-10-D <u>7.45</u> NOTIFY SUPV IF ML N-10-D IS NOT IN RANGE 7.1-7.4 OR IF THE TWO TITRATIONS DIFFER BY MORE THAN 0.10 ML N-10-D (IF YES, FLUSH ALL EQUIPMENT & REPEAT TITRATIONS) DO NOT PROCEED IF N-10-D TITRATION IS OUT OF RANGE ADJUST V-358 TO OBTAIN A TITRATION PH = <u>2.25</u> (2.00-2.10) <u>2.20-2.30</u>				
SV 6	27	WHEN S-26 TITRATION OK, STRIKE V-358 THRU BOTH UNDERSURFACE DISTRIBUTORS INTO SV IN 16-18 MIN RECORD: START <u>1:57 PM</u> , TOTAL MIN <u>18</u> NOTE: STRIKE TIME UP WHEN 1/2 VAT BOTTOM SHOWS & BUBBLES APPEAR IN SIGHT GLASSES				
	28	IMMEDIATELY DUMP IN N-4-A FROM S 3 & SET TIMER FOR 15 MINUTES				
	29	DURING S 28, WASH IN V-358				
	30	STIR 2 MIN & RECORD PH <u>1.75</u> (1.8-2.5) PBXS, <u>7</u> (MUST BE +)				
	31	STIR TOTAL OF 15 MIN FROM S-28 & RECORD: TEMP <u>23</u> *F (67-73*F)				
	32	DUMP N-3-A FROM S-4				
	33	STIR 3 MIN				
	34	POUR IN N-32-D FROM S-5				
	35	STIR 2 MIN				
	36	RUN IN USING BADGER METER.	734	115-A	367	
	37	STIR 3 MIN & FLUSH ALUM LINE WITH WATER.				
	38	DUMP IN N-3 FROM S-6				
	39	STIR 4 MIN FOR S-43				
390 7	40	RUN IN USING WEIGHT & FLOW CONTROL PANEL MK _____, <u>29.59%</u> MK _____, _____%			28-D 105 28-D	
	41	DURING S-39 SIFT N-711-B FROM S-7 INTO V-390 WITH AGITATOR ON IN 1-2 MIN				
	42	STIR 1-2 MIN TO MILKY SOLUTION				
SV 8	43	WHEN S-39 COMPLETE, IMMEDIATELY RUN IN N-711-B SOLUTION GRADUALLY OVER 5 MIN PERIOD INTO SV WATCH FOAM!!! IF FOAMING IS EXCESSIVE, STOP UNTIL FOAM SUBSIDES.				
	44	DUMP IN	350	128-A	350	
	45	STIR 10 MIN				
	46	RECORD: PH <u>5.6</u> (5.8-6.0)				
	47	IF NECESSARY, ADJ TO PH <u>5.8-6.0</u> & RECORD: PH <u>5.2</u> RECORD: TIME <u>2:45 PM</u>	ASSUME 50% ASSUME 66%		7-D 33-D	
	48	FLOOD TO 153" (7619 G)				
	50	STOP AGITATOR START FINISH OPTR HELPER <u>11:50 PM 2:00 PM 86 04</u>				

ME-71190

Ende der R

A 01.10.12-7
TO 11.10.12-7

0 10 20 30 40 50 60 70 80 90 100

10.10.12
11.10.12
12.10.12
13.10.12
14.10.12
15.10.12
16.10.12
17.10.12

7.45

7.48