



DASHIELL CORPORATION
ENGINEERS - CONSTRUCTORS

A9
H71

POST OFFICE BOX 147
BATON ROUGE, LA 708
PHONE: 504/293-9359

23 February 1990

Dow Chemical USA
P.O. Box 150
Plaquemine, LA 70765

Attention: Mr. Jimmy Jumonville

Re: P.O. #1175704
Ground Grid Check
Dashiell Job No. 2586

Dear Mr. Jumonville:

Enclosed are results of the tests performed by our company for the above referenced project.

Thank you for the opportunity to be of service. If you should have any questions, please call our office.

Sincerely,

DASHIELL CORPORATION

W. H. Bland
Vice President,
Field Services

WHB/hle

Enclosures

DO A 023176
CONFIDENTIAL

DOW CHEMICAL
PLAQUEMINE, LA

DASHIELL JOB NO. 2586

We have completed testing Block 26, Areas 5, 6, and 7, with the exceptions of the areas noted on the result sheets, everything appears to be in satisfactory condition.

As you will notice, there are two areas not thoroughly tested:

- 1) Area one is by the Control Room end of Cells 1-8 where the I-beams were covered with pipe and there were only a couple of places to check.
- 2) Area two is on the warehouse side of the Hydrogen Unit where Emmett Irwin asked us not to test because of the danger of a hydrogen fire.

Thank you for the opportunity to be of service. If we can help you in the future, feel free to call upon us.

James D. Smith
Technician,
Field Services

DO A 023177
CONFIDENTIAL

