

**CONOCO CHEMICALS – ABERDEEN PVC PLANT
DOSIMETRY CARD (A)**
SAMPLE N^o 1179

A

Hazard: VCM (✓) Lead () Noise () () Date 10/18/80

Name Doug Spann S. S. #418/66/3073 Shift A

Department Wing Job Class Chief Lead

Instrument No. 472R	Start	Stop
Time 640	AM() PM(✓) 705	AM(✓) PM()
Noise Cell No.	Airflow	

Analyst: J. Grace Analysis Date: 10-30-80

Hazard	TWA Exposure	
VCM	PEL: 1 PPM	0.1 PPM
Noise	Over () Under () 115 dBA	% of PEL
Lead (Micrograms)	TOT: PEL: Per M ³	Per M ³

**CONOCO CHEMICALS – ABERDEEN PVC PLANT
DOSIMETRY DATA CARD (B)**
SAMPLE N^o 1179

Hazard: VCM (✓) Lead () Noise () () Date 10/18/80

Time Clock (Lead Sampling Only) : IN: 640 AM() PM(✓) OUT: 0700 AM() PM()

List areas you spent most time in and estimate amount of time (nearest hour is sufficient) spent.

Area	Time	Area	Time
Rx's			
Dryers			

List most likely causes of possible overexposure to the hazard.

1. Recovery Systems
- 2.
- 3.

Check respiratory protection you used:

☒ None () Dust Mask (X) Air-line Respirator () Scott Air-pak

Signature Doug Spann

Please complete and return to guard