

FROM: R.E. CLARK

TO: MEMORANDUM

SEPTEMBER 7, 1988

RE: ASBESTOS INSULATION PROCEDURES

A recent incident involving the repair of a leaking steam pipe pointed out some confusion regarding our policy regarding asbestos insulation. In order to ensure that each of our employees understand the regulations, I suggest the following action:

- * Each unit supervisor cover this procedure in one of their September safety meetings. (See R.C. Remaley for a tape that describes the requirements)
- * Do not attempt any repairs of equipment or piping systems that have asbestos insulation. (Notify Brooks Parker or myself to assist in determining the appropriate action)
- * Engineering will evaluate the steam piping system and we will decide how to proceed.

P.S. Don't forget to send Bobby a list of employees that have been covered.

Eddie

R.E. Clark

S.J. KNIGHT
S.J. SPELL
J.D. LEGGETT
J.M. MITCHELL
L.G. PARSONS
W.T. ECKERT
G.C. GRIESBACH
E.B. PARKER

J.D. QUINN
G.R. HOLLAS
J.L. THROCKMORTON
E.D. STOUGH
C.B. ALLISION
J.I. BASTOW
J.A. CHURCH
A.L. GLASER
A.J. JOHNSTON
F.D. MARSHALL
J.R. McCLAIN
S.E. McFAULL
M.L. PEVEHOUSE
V.G. POMYKAL
L.E. PRATT
R.C. REMALEY
H.E. RYAN

ARD 003952