

UNION CARBIDE CORPORATION  
Specialty Chemicals Division

WV-0204 #49

Sistersville, WV

October 29, 1986

To: JRD - fyi

Ref: SV project.


Letter req'd by Danbury to help support

On item 3, can we document  
any unsafe cond. reports here?

RECEIVED

NOV 04 1986

D. A. GOSSELIN



Sistersville

COMMENTS:

- \* The condition of installed asbestos is the top I/H safety concern at Sistersville.
- \* The project addresses insulation that is exposed/cracked to the degree that wind movement causes fibers to be spread through the air or pieces to fall to the ground. We are addressing insulation that is unacceptable as regards its upkeep and maintenance.
- \* It is a major morale and health concern among the employees. For instance, in the last three years we have received 41 unsafe condition reports and seven incident reports concerning exposure. OSHA audits in the Small Scale and Monomers Units have also highlighted the need to maintain/remove damaged asbestos insulation.
- \* The issue is potential for exposure. We have no definite data that says windblown fibers are going to cause a problem or exceed OSHA guidelines. However, it is the opinion of plant management that health problems will result if maintenance of the insulation is not accelerated and that complaints to OSHA will occur. OSHA would not look favorably on the facilities if the deteriorated condition of the asbestos was pointed out. This project will provide excellent insurance and protection to the workforce.
- \* The alternative to the project is to add six insulators and complete the work as expense. The plant is not in a position to upgrade per the need at current insulator staffing (overtime in this craft will run 25% in 1986).
- \* There is reference to a Phase II insulation project after 1989. This may be avoided if government guidelines do not decree "total asbestos removal" and the maintenance workforce continues to upgrade at the rate accomplished in 1986.

  
W. V. Summers

WVS/jec  
2262A

UCC 006433

UNION CARBIDE CORPORATION  
Specialty Chemicals Division

Sistersville, WV

October 29, 1986

① CRN  
② DAG

MEMO TO: D. Liebeskind

COPY TO: D. G. Beddow  
K. F. Carroll  
D. A. Gosselin  
R. P. Leichliter  
L. W. Phair  
A. Walker

RECEIVED

NOV 04 1986

D. A. GOSSELIN

SUBJECT: Asbestos Insulation Upgrade Project

Per our discussion of 10/20/86 relative to the Sistersville Asbestos/Insulation Upgrade Project, a few comments:

- \* The condition of installed asbestos is the top I/H safety concern at Sistersville.
- \* The project addresses insulation that is exposed/cracked to the degree that wind movement causes fibers to be spread through the air or pieces to fall to the ground. We are addressing insulation that is unacceptable as regards its upkeep and maintenance.
- \* It is a major morale and health concern among the employees. For instance, in the last three years we have received 41 unsafe condition reports and seven incident reports concerning exposure. OSHA audits in the Small Scale and Monomers Units have also highlighted the need to maintain/remove damaged asbestos insulation.
- \* The issue is potential for exposure. We have no definite data that says windblown fibers are going to cause a problem or exceed OSHA guidelines. However, it is the opinion of plant management that health problems will result if maintenance of the insulation is not accelerated and that complaints to OSHA will occur. OSHA would not look favorably on the facilities if the deteriorated condition of the asbestos was pointed out. This project will provide excellent insurance and protection to the workforce.
- \* The alternative to the project is to add six insulators and complete the work as expense. The plant is not in a position to upgrade per the need at current insulator staffing (overtime in this craft will run 25% in 1986).
- \* There is reference to a Phase II insulation project after 1989. This may be avoided if government guidelines do not decree "total asbestos removal" and the maintenance workforce continues to upgrade at the rate accomplished in 1986.

  
W. V. Summers

WVS/jec  
2262A

UCC 006434