

To Distribution

AT

DATE November 3, 1976

FROM J. P. Sandstedt

AT Burlington

COPY TO

SUBJECT EPA/VCM COMPLIANCE - WAIVER DOCUMENTS


Waivers to be requested, by plant, are listed below.

1 - Waiver of compliance for time necessary to implement procedures or install new equipment

2 - Request for use of equivalent procedure or equipment

Area	Paragraph	Plant		
		Burlington	Flemington	Pasadena
Reactor Opening	61.64 (a)2	1,2-1 to only	1	1
Stripped Slurry/Latex	61.64 (e)1	1,2	1,2	1
Monomer Recover System				
-Carbon Adsorption	61.64 (a)1,(b)(c)(d)	1	1	1
	61.65 (b)1,2,3iii,6ii,3i			
Loading/Unloading Lines	61.65 (b)1	1	1	1
Slip Gauges	61.65 (b)2	1	-	1
Rotating Pumps	61.65 (b)3(i)	1	1	1
Rotating Compressors	61.65 (b)3(iii)	-	1	-
Reciprocating Compressors-				
	61.65 (b)3(iv)	1	-	1
Opening of Equipment	61.65 (b)6(i)	1	1	1
In Process Wastewater	61.65 (b)9(ii),c	1	1	1
Analytical-				
Test Method 106	61.71 App B	2	2	2
" " 107	61.71 App B	2	2	2

J. P. Sandstedt



JPS/ib

TO Distribution

AT

DATE November 3, 1976

FROM J. P. Sandstedt

AT Burlington

COPY TO ~~ENV~~ ~~SCIENCE~~

SUBJECT EPA/VCM COMPLIANCE - WAIVER DOCUMENTS

-5


Waivers to be requested, by plant, are listed below.

- 1 - Waiver of compliance for time necessary to implement procedures or install new equipment
- 2 - Request for use of equivalent procedure or equipment


Area	Paragraph	<u>Plant</u>		
		<u>Burlington</u>	<u>Flemington</u>	<u>Pasadena</u>
Reactor Opening	61.64 (a)2	1,2	1,2	1,2
Stripped Slurry/Latex	61.64 (e)1	1,2	1,2	1
Monomer Recover System				
-Carbon Adsorption	61.64 (a)1,(b)(c)(d)	1	1	1
	61.65 (b)1,2,3iii,6ii, 3i			
Loading/Unloading Lines	61.65 (b)1	1	1	1
Slip Gauges	61.65 (b)2	1	-	1
Rotating Pumps	61.65 (b)3(i)	1	1	1
Rotating Compressors	61.65 (b)3(iii)	-	1	- /
Reciprocating Compressors-				
	61.65 (b)3(iv)	1	-	1
Opening of Equipment	61.65 (b)6(i)	1	1	1
In Process Wastewater	61.65 (b)9(ii),c	1	1	1
Analytical-				
Test Method 106	61.71 App B	2	2	2
" " 107	61.71 App B	2	2	2

JPS/ib

J. P. Sandstedt



Distribution: W. P. Anderson ✓
D. C. Coldiron
C. Crain
G. S. Flint
R. E. Harmond
F. X. Ritter
G. I. Rozand
P. R. Scarito
J. T. Sweeney
E. V. Schenke
C. G. Thompson



<u>Con. Dr.</u>		Use	
2500 -	1000	1000	20x
2400 -	400		40x
2000 -	10	200	40x

80
40

