

**PLAINTIFF'S
EXHIBIT****UC-P-135**

WLCREPTU

*** WORK REQUEST INQUIRY ***

*** SELECTION CRITERIA ***

WORK REQ : AREA: BLDG/UNIT: LVL: RESP: MO PRIO:
REF CHRG: ORIGINATOR: JOB STATUS: WORK TYPE: PLANNER:
PLAN STATUS: (UU/US/PU/PS) OPEN: Y (Y/N) CLOSED: Y (Y/N) PURGED: Y (Y/N)
DATE WRITT, FROM: 080195 TO: 110196 DATE WANTED, FROM: TO:
DATE COMPL, FROM: TO: DATE ENTERED, FROM: TO:
COST: PERIOD: T (C/P/Y/T) AMOUNT: BLANKET: (B/J/I/Y) WKCAT:
REQUESTED BY: PROP NO: PROCESS ID:
TO D/LOC: ACCT: IN: FST: SEC:

*** REPORT FORMAT ***

TYPE: L (H:HOURS D:DOLLARS C:CASCADE S:SUMMARY L:LIST B:BKLOG R:RES BKLOG)
PERIOD: (C:CURRENT MONTH P:PREVIOUS MONTH Y:YEAR TO DATE T:TOTAL TO DATE)

	S/T HRS	O/T HRS	TOTAL	LABOR \$\$	MAT'L \$\$	TOTAL \$\$
CURR MONTH	96	34	130	3835	936	4771
PREV MONTH	1091	155	1246	36495	4536	41031
Y-T-D	6796	446	7242	210192	39682	249874
T-T-D	8323	760	9083	262662	53335	315997

ENTER:EDIT/SEARCH PF1:HELP 3:RETURN 4:CODES 6:CLEAR SCRN 7:WRQ ENTRY
8:MULT CLOSE 9:MULT VERIFY 22:CMS 23:MENU 24:LOGOFF

003433

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 1 OF 14
DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
					T	SP	T	PR	CAT	WRITN	WANTED	CLOSED

<== SORT SELECTION LINE ==>

A84839	J			REMOVE ASBESTOS AT OL2	1	M0	8	2	SD	101996	112296	
A84730	I			CUT ASBES.MASTIC ON HEADS	1	M0	3	2	SD	101796	113096	
A84412	J			REMOVE ASBESTOS TILE	C	M0	8	1	SC	101196	101196	101196
A84155	I			REMOVE ASBESTOS GASKETS	C	M0	3	2	TA	100796	110896	110596
A83946	I			REMOVE ASBESTOS INSULATION	C	M0	8	2	RP	100396	101596	101596
A83895	J			REMOVE GASKET	C	M0	8	1		100396	100996	100796
A83842	I			ENCAPSULATE (ACM) NEAR CENTAC	C	M0	4	2		100296	113096	111596
A83606	I			BAG TRANSITE BARGE DOCKS	C	M0	8	2	US	092796	101996	101196
A83424	J			REMOVE ASBESTOS GASKETS	C	M0	8	3	SE	092696	101596	101196
A83336	J			B341 ABESTOS REMOVAL	C	M0	8	1		092596	092796	092796
A83126	J			REMOVE ASBESTOS WRAPPING	C	M0	8	3	PM	092396	101196	101096
A83052	J			8' BLIND FLANGE	C	M0	8	3	SE	092096	092796	092796
A82802	J			ASBESTOS INSULATION/GASKETS	C	M0	8	3	SE	091796	092096	091996
A82785	I			#15 COMP. ASBESTOS ABATEMENT	C	M0	8	2	US	091796	092496	091896

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003434

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A84839 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 838000 INDX: 92 1ST ORDER: 00006137 2ND ORD: 07300
PR: 2 OR: 99 WCAT: SD RW CD: RW RS: DESC: REMOVE ASBESTOS AT OL2
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 112296 RECNO: PROP NO:
REQ BY: R.REYES C&P: WRITTEN: 101996 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 650 610

JOB DETAILS: PLEASE REMOVE ASBESTOS MASTIC & INSUL.FOR PIPE SUPPORT.

DEL PHONE 3649
YTD TOTAL HRS: 61 YTD O/T: 16 YTD LAB\$: 1811 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 102196 LAST ACT: N DATE: 111496

PF3:RETURN

003435

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A84730 ORIG WR: A80449 PROCESS ID: TEA STILL COLUMN
DIV/LOC: 500510 ACCOUNT: 071100 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 08 WCAT: SD RW CD: RW RS: DESC: CUT ASBES.MASTIC ON HEADS
BLD/UNT: ODU AR: CH WK TP: 3 WANTED: 113096 RECNO: 011352 PROP NO:
REQ BY: CONTRERAS C&P: WRITTEN: 101796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 500 225

JOB DETAILS: PLEASE CUT PLUGS ON THE TOP & BOTTOM HEAD OF THE TEA STILL.
GARY K. KNOWS LOCATION. TO BE PERFORMED PRE-TURNAROUND & ALSO
DURING THE T/A.

DEL PHONE 3626
YTD TOTAL HRS: 22 YTD O/T: 0 YTD LAB\$: 650 YTD MAT\$: 282
IND: I CL YR: 96 DATE ENTR: 101796 LAST ACT: N DATE: 110296

PF3:RETURN

003436

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A84412 ORIG WR: 142100 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 094220 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 76 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS TILE
BLD/UNT: HPPE2 AR: H2 WK TP: 8 WANTED: 101196 RECNO: PROP NO:
REQ BY: FINLEY C&P: WRITTEN: 101196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101196 APPROVED BY: E.MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 500 500 00 00 15

JOB DETAILS: PLEASE REMOVE THE FLOOR TILE IN FINISHING CONTROL ROOM CONTAINS
ASBESTOS.

DEL 569 PHONE 3527
YTD TOTAL HRS: 51 YTD O/T: 31 YTD LAB\$: 1591 YTD MAT\$: 385
IND: J CL YR: 96 DATE ENTR: 101196 LAST ACT: N DATE: 110596

PF3:RETURN

003437

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A84155 ORIG WR: A83725 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 008510 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: TA RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: ASU AR: ES WK TP: 3 WANTED: 110896 RECNO: PROP NO:
REQ BY: M ADKINS C&P: WRITTEN: 100796 HWP: MTAG: SLIPBL:
SERV: VAPORIZER DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 110596 APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 260 180

JOB DETAILS: PLEASE FURNISH MANPOWER TO REMOVE ASBESTOS GASKETS ON O2 THROTTLE
VALVE REVISIONS WHEN PIPING IS REMOVED.
SEE M ADKINS FOR LOCATION AND DETAILS

DEL O2 UNIT PHONE 5298
YTD TOTAL HRS: 18 YTD O/T: 0 YTD LAB\$: 520 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 100796 LAST ACT: N DATE: 110696

PF3:RETURN

003438

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A83946 ORIG WR: A83598 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 002150 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 12 WCAT: RP RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 101596 RECNO: PROP NO:
REQ BY: M ADKINS C&P: WRITTEN: 100396 HWP: MTAG: SLIPBL:
SERV: COOLING WATER P DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 10 04 96
DATE COMPLETE: 101596 APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 400 280

JOB DETAILS: PLEASE HAVE CREW REMOVE ASBESTOS INSULATION AT #3 CW PUMP PER
L. MIKOLAS. HE HAS SHOWN THE AREA TO GARY F.

DEL 321 PHONE 5369
YTD TOTAL HRS: 28 YTD O/T: 0 YTD LAB\$: 808 YTD MAT\$: 378
IND: I CL YR: 96 DATE ENTR: 100396 LAST ACT: N DATE: 102596

PF3:RETURN

003439

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A83895 ORIG WR: 292931 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 292700 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 08 WCAT: RW CD: RW RS: DESC: REMOVE GASKET
BLD/UNT: 140-2 AR: WK TP: 8 WANTED: 100996 RECNO: PROP NO:
REQ BY: LLSADDLER C&P: WRITTEN: 100396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 100796 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR

JOB DETAILS: PLEASE REMOVE ASBESTOS GAKET FROM SAFETY VALVE FLANGE AT PROCESS
SAFETY.VALVE IS FROM N.FIELD TK.2931.

DEL PROCESS SAFETY PHONE 2328
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 100396 LAST ACT: N DATE: 100896

PF3:RETURN

003440

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A83842 ORIG WR: A81963 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 008140 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: M6 WCAT: RW CD: RW RS: DESC: ENCAPSULATE (ACM) NEAR CENTAC
BLD/UNT: ENSYS AR: ES WK TP: 4 WANTED: 113096 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 100296 HWP: MTAG: SLIPBL:
SERV: CENTAC AIR COMP DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 111596 APPROVED BY: DWJ(JC)
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 100 80

JOB DETAILS: PLEASE ENCAPSULATE (ACM) NEAR THE CENTAC AIR COMPRESSOR SEE BOSCO
FOR MORE INFORMATION. THIS WORK MUST BE DONE PRIOR TO THE TURN-
AROUND.

YTD TOTAL HRS: 8 YTD O/T: 0 YTD LAB\$: 231 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 100296 LAST ACT: N DATE: 111696

PF3:RETURN

003441

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A83606 ORIG WR: A82507 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 220530 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 29 WCAT: US RW CD: RW RS: DESC: BAG TRANSITE BARGE DOCKS
BLD/UNT: DOCKS AR: DI WK TP: 8 WANTED: 101996 RECNO: PROP NO:
REQ BY: R. MAREK C&P: WRITTEN: 092796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101196 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 690 390

JOB DETAILS: PLEASE BAG TRANSITE FROM ROOF OF OLD BUILDING AT BARGE DOCK
WASH OUT QUESTIONS SEE ROYAL MAREK OR KEITH VICKERY

YTD TOTAL HRS: 39 YTD O/T: 0 YTD LAB\$: 1126 YTD MAT\$: 316
IND: I CL YR: 96 DATE ENTR: 092796 LAST ACT: N DATE: 101896

PF3:RETURN

003442

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A83424 ORIG WR: 152900 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 139900 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 75 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: PPU AR: P1 WK TP: 8 WANTED: 101596 RECNO: PROP NO:
REQ BY: NIX C&P: WRITTEN: 092696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: N RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101196 APPROVED BY: L.WHITE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 120 00

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS ON OIL COOLER LOCATED BEHIND
THE PAINT SHOP -- PLEASE CALL J.LUCAS AT EXT. 2943 WHEN
COMPLETE

DEL PHONE 2707
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 204
IND: J CL YR: 96 DATE ENTR: 092696 LAST ACT: N DATE: 101596

PF3:RETURN

003443

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A83336 ORIG WR: 155581 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 83 WCAT: RW CD: RW RS: DESC: B341 ABESTOS REMOVAL
BLD/UNT: LPPE1 AR: L1 WK TP: 8 WANTED: 092796 RECNO: PROP NO:
REQ BY: E CAMPBELL C&P: WRITTEN: 092596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 092796 APPROVED BY: C DAVIS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 420 440

JOB DETAILS: PLEASE REMOVE ABESTOS RESIDUE FROM THE CHANNEL IRON AROUND
THE 2ND LEVEL OF B 341

YTD TOTAL HRS: 44 YTD O/T: 22 YTD LAB\$: 1336 YTD MAT\$: 279
IND: J CL YR: 96 DATE ENTR: 092596 LAST ACT: N DATE: 100996

PF3:RETURN

003444

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A83126 ORIG WR: 243692 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 231940 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M0 WCAT: PM RW CD: RW RS: DESC: REMOVE ASBESTOS WRAPPING
BLD/UNT: EVP AR: EP WK TP: 8 WANTED: 101196 RECNO: PROP NO:
REQ BY: GALLEMORE C&P: WRITTEN: 092396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101096 APPROVED BY: STEVE G
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 210 260

JOB DETAILS: PLEASE REMOVE ASBESTOS WRAPPING OFF OF TUBING LOCATED AT THE
HIGH STRENGTH SEWER PUMP STATION ON FIFTH STREET.

DEL PHONE 3584
YTD TOTAL HRS: 26 YTD O/T: 0 YTD LAB\$: 751 YTD MAT\$: 315
IND: J CL YR: 96 DATE ENTR: 092396 LAST ACT: N DATE: 102696

PF3:RETURN

003445

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A83052 ORIG WR: 155500 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 83 WCAT: SE RW CD: RW RS: DESC: 8' BLIND FLANGE
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 092796 RECNO: PROP NO:
REQ BY: L KUTCHKA C&P: WRITTEN: 092096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 09 22 96
DATE COMPLETE: 092796 APPROVED BY: T.T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 120 100

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKET ON BLIND FLANGE AT 341 N

DEL PHONE 2832
YTD TOTAL HRS: 10 YTD O/T: 0 YTD LAB\$: 289 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 092096 LAST ACT: N DATE: 100996

PF3:RETURN

003446

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A82802 ORIG WR: 154412 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148310 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 83 WCAT: SE RW CD: RW RS: DESC: ASBESTOS INSULATION/GASKETS
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 092096 RECNO: PROP NO:
REQ BY: DONNIE M. C&P: WRITTEN: 091796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 09 18 96
DATE COMPLETE: 091996 APPROVED BY: TOM T
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 130 80

JOB DETAILS: REMOVE ASBESTOS INSULATION AND GASKETS FROM PIPING LAYING IN THE
PERIMETER OF LP-1, NEED DONE SO PIPING CAN BE REMOVE TO SALVAGE
BEFORE VISISTORS ARRIVE.

DEL LP-1 BLOCK-12 PHONE 3506
YTD TOTAL HRS: 8 YTD O/T: 8 YTD LAB\$: 255 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 091796 LAST ACT: N DATE: 092896

PF3:RETURN

003447

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A82785 ORIG WR: A82423 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: US RW CD: RW RS: DESC: #15 COMP. ASBESTOS ABATEMENT
BLD/UNT: OLCOM AR: OL WK TP: 8 WANTED: 092496 RECNO: 003269 PROP NO: 630100130
REQ BY: B GEFFERT C&P: WRITTEN: 091796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 091896 APPROVED BY: HODDE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 180 140

JOB DETAILS: REMOVE ASBESTOS GASKETS FROM THE IPC CASE PIPING
CONTACT BUBBA 5-508

DEL PHONE 2774
YTD TOTAL HRS: 14 YTD O/T: 4 YTD LAB\$: 417 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 091796 LAST ACT: N DATE: 092896

PF3:RETURN

003448

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 2 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
					T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
				<== SORT SELECTION LINE ==>								
	A82690	I		REMOVE COVERS & SEAL ASBESTOS	C	M0	8	2	SD	091696	092396	091996
	A82644	I		ASBESTOS REMOVAL FOR#10	C	M0	8	2		091696	091796	091796
	A82287	I		INSUL PRE-WRK ODU T/A BU0019	C	M0	2	2		091196	101196	101096
	A82283	I		INSUL PRE-WRK ODU T/A BU0018	C	M0	2	2		091196	101196	101096
	A82281	I		INSUL PRE-WRK ODU T/A BU0017	1	M0	2	2		091196	113096	
	A82278	I		INSUL PRE-WRK ODU T/A BU0020	C	M0	2	2		091196	101196	101096
	A81926	I		DEINSULATE ASBESTOS INSULATION	C	M0	3	2	SC	090596	092096	091996
	A81848	I		ASBESTOS REMOVAL SD HP2	C	M0	8	2	SD	090496	091796	091696
	A81659	J		REMOVE ASBESTOS GASKETS	C	M0	8	3	SC	083096	090696	090696
	A81383	J		DEINSULATE DEA PIPE	C	M0	8	1	SC	082796	082796	082896
	A81230	I		REMOVE ASBESTOS GASKETS	C	M0	8	3	US	082696	091396	090596
	A80983	I		ASBESTOS REMOVAL	C	M0	8	1		082296	082296	082396
	A80700	I		INSUL PRE-WRK ODU T/A BU0021	1	M0	2	2		081696	113096	
	A80670	I		REMOVE ASBESTOS GASKETS	C	M0	3	2	SE	081696	081996	082196

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003449

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A82690 ORIG WR: A79855 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071300 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 11 WCAT: SD RW CD: RW RS: DESC: REMOVE COVERS & SEAL ASBESTOS
BLD/UNT: ACE AR: CH WK TP: 8 WANTED: 092396 RECNO: PROP NO:
REQ BY: J. RAMIREZ C&P: WRITTEN: 091696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 09 17 96
DATE COMPLETE: 091996 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 110 460

JOB DETAILS: PLEASE REMOVE THE INSULATION COVERS ON THE WEST & EAST MAKE HEAT EXCHANGERS AND SEAL THE ASBESTOS. AREA IS ALREADY SEALED BUT IT HAS CRACKS AND T&I WILL NEED TO INSPECT THESE AREAS. THANKS, JUAN 5-801. GARY ALREADY KNOWS ABOUT THE JOB.

DEL ODU (ACETATE) PHONE 3583
YTD TOTAL HRS: 46 YTD O/T: 0 YTD LAB\$: 1328 YTD MAT\$: 113
IND: I CL YR: 96 DATE ENTR: 091696 LAST ACT: N DATE: 100996

PF3:RETURN

003450

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A82644 ORIG WR: A82472 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 12 WCAT: RW CD: RW RS: DESC: ASBESTOS REMOVAL FOR#10
BLD/UNT: OLCOM AR: OL WK TP: 8 WANTED: 091796 RECNO: PROP NO:
REQ BY: JL,MEJIA C&P: WRITTEN: 091696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: PLAN CD: ASIS/ENGR: EST START: 09 17 96
DATE COMPLETE: 091796 APPROVED BY: HODDE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 150 100

JOB DETAILS: NEED ASBESTOS REMOVAL INSULATORS ON STANDBY WHILE REMOVAL OF
#10 COMP., 12" VALVE IS CHANGED OUT. THERE MAY BE ASBESTOS GASKETS
ON FLANGES. JOB IS TO START AT 12:30 PM TUESDAY 9-17-96.
ANY QUESTIONS SEE OR CALL JOE MEJIA AT EXT-2304 OR PAGER-312.
DEL 500 N PHONE 2304
YTD TOTAL HRS: 10 YTD O/T: 0 YTD LAB\$: 289 YTD MAT\$: 14
IND: I CL YR: 96 DATE ENTR: 091796 LAST ACT: N DATE: 092896

PF3:RETURN

003451

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A82287 ORIG WR: A76039 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: INSUL PRE-WRK ODU T/A BU0019
BLD/UNT: BUTYL AR: CH WK TP: 2 WANTED: 101196 RECNO: PROP NO:
REQ BY: E. ORTIZ C&P: WRITTEN: 091196 HWP: MTAG: SLIPBL:
SERV: BU0019 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 450 430 00 00 20

JOB DETAILS: PLEASE INSULATE ALL EXPOSE FLANGES ON #1,2,3 VERTICAL REACTORS
FOR DETAILS PAGE 5-747.

DEL PHONE 3589
YTD TOTAL HRS: 45 YTD O/T: 30 YTD LAB\$: 1382 YTD MAT\$: 4
IND: I CL YR: 96 DATE ENTR: 091196 LAST ACT: N DATE: 101196

PF3:RETURN

003452

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A82283 ORIG WR: A76038 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: INSUL PRE-WRK ODU T/A BU0018
BLD/UNT: BUTYL AR: CH WK TP: 2 WANTED: 101196 RECNO: PROP NO:
REQ BY: E. ORTIZ C&P: WRITTEN: 091196 HWP: MTAG: SLIPBL:
SERV: BU0018 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 80 60

JOB DETAILS: PLEASE REPAIR ALL LOOSE SECTION OF METAL OF BUCS COL. FOR
DETAILS PAGE 5-747

DEL PHONE 3589
YTD TOTAL HRS: 6 YTD O/T: 0 YTD LAB\$: 173 YTD MAT\$: 75
IND: I CL YR: 96 DATE ENTR: 091196 LAST ACT: N DATE: 101196

PF3:RETURN

003453

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A82281 ORIG WR: A76037 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: INSUL PRE-WRK ODU T/A BU0017
BLD/UNT: BUTYL AR: CH WK TP: 2 WANTED: 113096 RECNO: PROP NO:
REQ BY: E. ORTIZ C&P: WRITTEN: 091196 HWP: MTAG: SLIPBL:
SERV: BU0017 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 100 50

JOB DETAILS: PLEASE REPAIR INSULATION AS NEEDED FOR DETAILS CONTACT E. ORTIZ
PAGER 5-747

DEL PHONE 3589
YTD TOTAL HRS: 5 YTD O/T: 0 YTD LAB\$: 144 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 091196 LAST ACT: N DATE: 101696

PF3:RETURN

003454

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A82278 ORIG WR: A76040 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: INSUL PRE-WRK ODU T/A BU0020
BLD/UNT: BUTYL AR: CH WK TP: 2 WANTED: 101196 RECNO: PROP NO:
REQ BY: E. ORTIZ C&P: WRITTEN: 091196 HWP: MTAG: SLIPBL:
SERV: BU0020 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 120 100

JOB DETAILS: PLEASE REPAIR INSULATION AS NEEDED SEE R ORTIZ FOR DETAILS.

PAGE 5-747

DEL PHONE 3589
YTD TOTAL HRS: 10 YTD O/T: 0 YTD LAB\$: 288 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 091196 LAST ACT: N DATE: 101196

PF3:RETURN

003455

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A81926 ORIG WR: A80449 PROCESS ID: ASBESTOS PIPE
DIV/LOC: 500510 ACCOUNT: 071100 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 08 WCAT: SC RW CD: RW RS: DESC: DEINSULATE ASBESTOS INSULATION
BLD/UNT: AMINE AR: CH WK TP: 3 WANTED: 092096 RECNO: 067419 PROP NO:
REQ BY: CONTRERAS C&P: WRITTEN: 090596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 091996 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 280 340

JOB DETAILS: PLEASE DEINSULATE SECTIONS OF ASBESTOS INSULATION. T&I WILL
BE INSPECTING THE PIPE IN THESE DEINSULATED AREAS. VIRGINIA
CONTRERAS WILL SHOW YOU THE LOCATION OF THE JOB. THANK YOU.
PAGER 5-586

DEL PHONE
YTD TOTAL HRS: 34 YTD O/T: 0 YTD LAB\$: 982 YTD MAT\$: 24
IND: I CL YR: 96 DATE ENTR: 090596 LAST ACT: N DATE: 092696

PF3:RETURN

003456

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A81848 ORIG WR: A81070 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 76 WCAT: SD RW CD: RW RS: DESC: ASBESTOS REMOVAL SD HP2
BLD/UNT: HPPE2 AR: H2 WK TP: 8 WANTED: 091796 RECNO: PROP NO:
REQ BY: MUNSCH C&P: WRITTEN: 090496 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 09 04 96
DATE COMPLETE: 091696 APPROVED BY: MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 120 220

JOB DETAILS: PROVIDE MANPOWER FOR ASBESTOS REMOVAL DURING SEPT4 SD
MIKE MUNSCH 5-713
MIKE CAMPBELL 5-576

YTD TOTAL HRS: 22 YTD O/T: 0 YTD LAB\$: 634 YTD MAT\$: 268
IND: I CL YR: 96 DATE ENTR: 090496 LAST ACT: N DATE: 092696

PF3:RETURN

003457

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A81659 ORIG WR: 119587 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 090696 RECNO: PROP NO:
REQ BY: MINETREA C&P: WRITTEN: 083096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: 30R8 ASIS/ENGR: EST START: 09 03 96
DATE COMPLETE: 090696 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 100 90

JOB DETAILS: REMOVE ASBESTOS GASKET FROM FURNACE PIPING AT FURNACE WELD SHOP.

DEL PHONE 2478
YTD TOTAL HRS: 9 YTD O/T: 0 YTD LAB\$: 260 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 083096 LAST ACT: N DATE: 092696

PF3:RETURN

003458

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A81383 ORIG WR: 136540 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071100 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 22 WCAT: SC RW CD: RW RS: DESC: DEINSULATE DEA PIPE
BLD/UNT: ODU AR: CH WK TP: 8 WANTED: 082796 RECNO: PROP NO:
REQ BY: ANN T./J.M C&P: WRITTEN: 082796 HWP: MTAG: SLIPBL:
SERV: DIETHANOLAMINES DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: 278R ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 082896 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 75 00 00 360

JOB DETAILS: PLEASE DEINSULATE DEA PIPE IN NORTHWEST CORNER OF ODU IN THE HIGH PIPE RACK AS PER VERBAL INSTRUCTIONS FROM BRIAN RALSTON. THE INSULATORS HAVE ALREADY BEEN CONTACTED BUT IF THERE ARE ANY QUESTIONS CONTACT JOE MITSCHERLING AT EXT. 2750 PAGER 5-401.

DEL

PHONE 2750

YTD TOTAL HRS: 43 YTD O/T: 8 YTD LAB\$: 1165 YTD MAT\$: 453
IND: J CL YR: 96 DATE ENTR: 082796 LAST ACT: N DATE: 100396

PF3:RETURN

003459

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A81230 ORIG WR: A80957 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 04 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: R/S AR: WK TP: 8 WANTED: 091396 RECNO: PROP NO:
REQ BY: D. SPEED C&P: WRITTEN: 082696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: R826 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 090596 APPROVED BY: KELLEY
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 170 90

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS FROM THE STEAM TURBINE LOCATED
AT THE PUMP REPAIR SHOP BLDG.140.JOB IS FOR OLEFINS.GARY K.
KNOWS ABOUT THIS JOB.

DEL REPAIR SHOP PHONE 2528
YTD TOTAL HRS: 9 YTD O/T: 0 YTD LAB\$: 260 YTD MAT\$: 31
IND: I CL YR: 96 DATE ENTR: 082696 LAST ACT: N DATE: 092096

PF3:RETURN

003460

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A80983 ORIG WR: A80397 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: WCAT: RW CD: RW RS: DESC: ASBESTOS REMOVAL
BLD/UNT: 140-2 AR: WK TP: 8 WANTED: 082296 RECNO: PROP NO:
REQ BY: GILBREATH C&P: WRITTEN: 082296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: R822 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 082396 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: PLEASE SUPPLY MANPOWER FOR REMOVAL OF ASBESTOS
GASKET FROM SAFETY VALVE.

DEL PHONE 2328
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 082296 LAST ACT: N DATE: 082496

PF3:RETURN

003461

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A80700 ORIG WR: A76041 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: INSUL PRE-WRK ODU T/A BU0021
BLD/UNT: BUTYL AR: CH WK TP: 2 WANTED: 113096 RECNO: PROP NO:
REQ BY: E.ORTIZ C&P: WRITTEN: 081696 HWP: MTAG: SLIPBL:
SERV: BU0021 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 10 19 96
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 440 180

JOB DETAILS: PLEASE REPAIR MISC INSULATION ON OUTLET PIPING, VERTICAL RXTRS.
FOR DETAILS, E. ORTIZ 5-747. ASBESTOS INCAPSULANT REQUIRED.

YTD TOTAL HRS: 18 YTD O/T: 0 YTD LAB\$: 520 YTD MAT\$: 135
IND: I CL YR: 96 DATE ENTR: 081696 LAST ACT: N DATE: 110296
DEL PHONE

PF3:RETURN

003462

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A80670 ORIG WR: A80551 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148250 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: M2 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: LP1F AR: L1 WK TP: 3 WANTED: 081996 RECNO: PROP NO:
REQ BY: T.MIDDAUGH C&P: WRITTEN: 081696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 082196 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 130 70

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS FROM PIPE FLANGES ON SIEVE PREHEATE
R .WILL NOTIFY IF AND WHEN NEEDED.THANKS

DEL PHONE 2828
YTD TOTAL HRS: 7 YTD O/T: 0 YTD LAB\$: 202 YTD MAT\$: 77
IND: I CL YR: 96 DATE ENTR: 081696 LAST ACT: N DATE: 090496

PF3:RETURN

003463

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 3 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

T
X WK REQ P JOB DESCRIPTION S RE W WK ----- DATES -----
T SP T PR CAT WRITN WANTED CLOSED
<== SORT SELECTION LINE ==>

A80333	J	VULCANIZABLES UPGRADE	1	M0	8	3		081296	113096	
J66944	J	SAMPLE FOR ASBESTOS AT 507	C	M0	8	4		073196	113096	100296
A79213	J	PRECURSOR ASBESTOS REMOVAL	C	M0	8	3	SE	072496	093096	091196
A78807	I	BLDR 341 ROOF REMOVAL	C	M0	8	3	RP	071796	093096	092596
A78658	I	PROVIDE INSUL PLANNER AMINES	C	M0	3	2		071696	112296	111596
J70698	J	ODU CONTROL SYSTEM UPGRADE	1	M0	8	3	NC	060496	121596	
J61851	J	CHECK INSUL.AT ODU SHED	C	M0	8	3		053196	113096	102196
A78420	I	REMOVE ASBESTOS PAINT	C	M0	8	3	RP	071196	082096	081396
A78247	I	REMOVE ASB. MASTIC OX2-RC-17	C	M0	4	2	SD	070996	112496	111596
A77929	*I	REMOVE ASBESTOS AT BLDG.321	1	M0	8	4	PM	070396	122096	
A77812	I	REMOVE ASBESTOS INSULATION	C	M0	4	2	TA	070296	110496	110196
A77693	J	SEAL LOOSE ASBESTOS INSULATION	1	M0	8	3	SA	070196	121596	
A76185	J	CHECK OUT INSULATION & REMOVE	1	M0	8	3	SC	060496	123196	
A76178	I	PROVIDE INSUL. PLANNER BUTYL	C	M0	4	2		060496	112296	111596

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003464

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A80333 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006408 2ND ORD: 59000
PR: 3 OR: LC WCAT: RW CD: RW RS: DESC: VULCANIZABLES UPGRADE
BLD/UNT: HP11 AR: H2 WK TP: 8 WANTED: 113096 RECNO: PROP NO:
REQ BY: L CORONADO C&P: WRITTEN: 081296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: 12R8 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1250 1080

JOB DETAILS: GARY, I NEED SAMPLES TAKEN OF MASTIC ON PIPE AND EQUIPMENT AT HP11
VULCANIZABLE FOR UPCOMING WORK. ERNEST HERNANDEZ HAS INFO ON
LOCATIONS OF AREAS OF CONCERN. THANK YOU. NOTIFY ME OF RESULTS.
CONTACT LUPE CORONADO X3649

DEL PHONE
YTD TOTAL HRS: 108 YTD O/T: 0 YTD LAB\$: 3117 YTD MAT\$: 536
IND: J CL YR: 96 DATE ENTR: 081296 LAST ACT: N DATE: 101996

PF3:RETURN

003465

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J66944 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006364 2ND ORD: 73000
PR: 4 OR: WCAT: RW CD: RW RS: DESC: SAMPLE FOR ASBESTOS AT 507
BLD/UNT: 507 AR: OL WK TP: 8 WANTED: 113096 RECNO: PROP NO:
REQ BY: BUD PETERS C&P: WRITTEN: 073196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: 086V ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 100296 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 680 580

JOB DETAILS: TAKE SAMPLES OF FLOOR TILE AND MASKING IN BL 507 FOR ASBESTOS.
IF SAMPLING DETECTS ASBESTOS, REMOVE AS NEEDED.

DEL PHONE 3450
YTD TOTAL HRS: 58 YTD O/T: 0 YTD LAB\$: 1673 YTD MAT\$: 106
IND: J CL YR: 96 DATE ENTR: 080296 LAST ACT: N DATE: 100396

PF3:RETURN

003466

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A79213 ORIG WR: 153912 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148250 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 83 WCAT: SE RW CD: RW RS: DESC: PRECURSOR ASBESTOS REMOVAL
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 093096 RECNO: PROP NO:
REQ BY: BECKY J. C&P: WRITTEN: 072496 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: R722 ASIS/ENGR: 5 EST START: 07 24 96
DATE COMPLETE: 091196 APPROVED BY: TOM T
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 250 00

JOB DETAILS: REMOVE ASBESTOS AND GASKETS FROM DEMO PIPING TO SUPPORT
B&R PIPEFITTERS.

DEL B-443 PHONE 2851
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 072496 LAST ACT: C DATE: 092796

PF3:RETURN

003467

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A78807 ORIG WR: A76206 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: FB WCAT: RP RW CD: RW RS: DESC: BLDR 341 ROOF REMOVAL
BLD/UNT: LP I AR: L1 WK TP: 8 WANTED: 093096 RECNO: PROP NO:
REQ BY: F BERGER C&P: WRITTEN: 071796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: 7R18 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 092596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 450 350

JOB DETAILS: REMOVE SECTION OF ROOF FROM BLDG 341 WHERE FILTER HOUSING WAS
LOCATED. THIS SECTION OF ROOFING CONTAINS SOME ASBESTOS MATERIAL.

DEL PHONE
YTD TOTAL HRS: 35 YTD O/T: 0 YTD LAB\$: 1011 YTD MAT\$: 318
IND: I CL YR: 96 DATE ENTR: 071796 LAST ACT: C DATE: 092796

PF3:RETURN

003468

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A78658 ORIG WR: A78381 PROCESS ID: FALL TA AMINES
DIV/LOC: 500510 ACCOUNT: 071100 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: PROVIDE INSUL PLANNER AMINES
BLD/UNT: AMINE AR: CH WK TP: 3 WANTED: 112296 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 071696 HWP: MTAG: SLIPBL:
SERV: AM000 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: RB PLAN CD: 1113 ASIS/ENGR: EST START: 08 05 96
DATE COMPLETE: 111596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 3875 3755

JOB DETAILS: PLEASE PROVIDE AN INSULATOR TO HELP PLAN THE AMINES TURNAROUND.
SEE BOSCO FOR DETAILS.

DEL PHONE 2617
YTD TOTAL HRS: 375 YTD O/T: 33 YTD LAB\$: 10918 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 071696 LAST ACT: N DATE: 112296

PF3:RETURN

003469

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J70698 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006417 2ND ORD: 59100
PR: 3 OR: LC WCAT: NC RW CD: RW RS: DESC: ODU CONTROL SYSTEM UPGRADE
BLD/UNT: ODU AR: CH WK TP: 8 WANTED: 121596 RECNO: PROP NO:
REQ BY: L CORONADO C&P: WRITTEN: 060496 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: 0406 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 3420 2990 00 00 40

JOB DETAILS: SAMPLE INSULATION ON TRANSMITTERS AT ODU AND REMOVE ANY ACM NEEDED
TO REPLACE INSTRUMENTS. THIS WILL BE DONE BY THE ABATEMENT GROUP
. TAKE ALL NECESSARY PRECAUTIONS.

DEL PHONE 2508
YTD TOTAL HRS: 303 YTD O/T: 32 YTD LAB\$: 8828 YTD MAT\$: 89
IND: J CL YR: 96 DATE ENTR: 060496 LAST ACT: N DATE: 112296

PF3:RETURN

003470

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J61851 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006435 2ND ORD: 73000
PR: 3 OR: CW WCAT: RW CD: RW RS: DESC: CHECK INSUL.AT ODU SHED
BLD/UNT: ODU AR: CH WK TP: 8 WANTED: 113096 RECNO: PROP NO:
REQ BY: C WELFEL C&P: WRITTEN: 053196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: 3105 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 102196 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 690 610

JOB DETAILS: PLEASE CHECK FOR ABESTOS ON POT IN STORAGE SHED WEST SIDE ODU IN
CENTER OF BLOCK. IF IT CONTAINS ASBESTOS, PLEASE REMOVE IT.
CONTACT BRIAN KRAUSE X2978 PAGER 5-631 IF ANY QUESTIONS. CALVIN
WELFEL 5-183

DEL PHONE 2467
YTD TOTAL HRS: 61 YTD O/T: 0 YTD LAB\$: 1760 YTD MAT\$: 165
IND: J CL YR: 96 DATE ENTR: 053196 LAST ACT: N DATE: 102396

PF3:RETURN

003471

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A78420 ORIG WR: A77324 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M3 WCAT: RP RW CD: RW RS: DESC: REMOVE ASBESTOS PAINT
BLD/UNT: HP2 AR: H2 WK TP: 8 WANTED: 082096 RECNO: PROP NO:
REQ BY: S SANDERS C&P: WRITTEN: 071196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: R117 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 081396 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1400 2320

JOB DETAILS: REMOVE ASBESTOS PAINT FROM ROOF OF SUB"P"AT HP2

DEL 5-357 PHONE 2448
YTD TOTAL HRS: 232 YTD O/T: 0 YTD LAB\$: 6699 YTD MAT\$: 1052
IND: I CL YR: 96 DATE ENTR: 071196 LAST ACT: N DATE: 082196

PF3:RETURN

003472

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A78247 ORIG WR: A77236 PROCESS ID: MG-403
DIV/LOC: 500510 ACCOUNT: 127200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: SD RW CD: RW RS: DESC: REMOVE ASB. MASTIC OX2-RC-17
BLD/UNT: REC AR: OX WK TP: 4 WANTED: 112496 RECNO: 009860 PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 070996 HWP: MTAG: SLIPBL:
SERV: RC-17 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: R107 ASIS/ENGR: EST START: 10 06 96
DATE COMPLETE: 111596 APPROVED BY: BATES
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 310 220 00 00 20

JOB DETAILS: REMOVE MASTIC (NON-FRIABLE) ASBESTOS FROM THE EAST MAIN SCRUBBER
PUMP. SEE BOSCO FOR MORE INFORMATION.
(TO BE DONE DURING THE OXIDE T/A)

DEL PHONE 2617
YTD TOTAL HRS: 24 YTD O/T: 5 YTD LAB\$: 701 YTD MAT\$: 73
IND: I CL YR: 96 DATE ENTR: 070996 LAST ACT: N DATE: 111696

PF3:RETURN

003473

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A77929 ORIG WR: A55879 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 003550 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: 81 WCAT: PM RW CD: RW RS: DESC: REMOVE ASBESTOS AT BLDG.321
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 122096 RECNO: PROP NO:
REQ BY: B.B. C&P: WRITTEN: 070396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: R736 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 3430 3010

JOB DETAILS: PLEASE REPAIR OR REMOVE ASBESTOS INSULATION ON THE WEST
SIDE OF BLDG.321 AS PER CONVERSATION.ALSO REMOVE INSUL.
ON INTERIOR AS NEEDED.GARY K.KNOWS LOCATION.

DEL PHONE 2592
YTD TOTAL HRS: 301 YTD O/T: 0 YTD LAB\$: 8688 YTD MAT\$: 505
IND: I CL YR: 96 DATE ENTR: 070396 LAST ACT: N DATE: 092896

PF3:RETURN

003474

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A77812 ORIG WR: A77236 PROCESS ID: MG-403
DIV/LOC: 500510 ACCOUNT: 127200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: TA RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNT: REC AR: OX WK TP: 4 WANTED: 110496 RECNO: 009860 PROP NO:
REQ BY: B GEFFERT C&P: WRITTEN: 070296 HWP: MTAG: SLIPBL:
SERV: RC-17 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: RB PLAN CD: 0276 ASIS/ENGR: EST START: 10 06 96
DATE COMPLETE: 110196 APPROVED BY: BATES
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 460 805 00 00 70

JOB DETAILS: REMOVE THE ASBESTOS INSULATION FROM THE EAST MAIN SCRUBBER WATER
PUMP. FABRICATE BLANKET INSULATION FOR THE PUMP AND FLANGES.
CONTACT BUBBA 5-508

DEL PHONE 2774
YTD TOTAL HRS: 87 YTD O/T: 7 YTD LAB\$: 2544 YTD MAT\$: 236
IND: I CL YR: 96 DATE ENTR: 070296 LAST ACT: N DATE: 112196

PF3:RETURN

003475

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A77693 ORIG WR: PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SA RW CD: RW RS: DESC: SEAL LOOSE ASBESTOS INSULATION
BLD/UNT: BUTYL AR: CH WK TP: 8 WANTED: 121596 RECNO: PROP NO:
REQ BY: VOIGT/AT C&P: WRITTEN: 070196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: 17K6 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1560 1030

JOB DETAILS: SEVERAL FLANGES/ELLS HAVE LOOSE ASBESTOS INSULATION. PLEASE SEAL
OR REPLACE.
200# STEAM SUPPLY AT BATTERY LIMITS

THNX, ANN T. 5-401 DEL PHONE 2750
YTD TOTAL HRS: 103 YTD O/T: 0 YTD LAB\$: 2975 YTD MAT\$: 306
IND: J CL YR: 96 DATE ENTR: 070196 LAST ACT: N DATE: 110896

PF3:RETURN

003476

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A76185 ORIG WR: 113609 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 16 WCAT: SC RW CD: RW RS: DESC: CHECK OUT INSULATION & REMOVE
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 123196 RECNO: PROP NO:
REQ BY: R BASALDUA C&P: WRITTEN: 060496 HWP: MTAG: SLIPBL:
SERV: INSULATION DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: 0406 ASIS/ENGR: EST START: 06 05 96
DATE COMPLETE: APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 430 00

JOB DETAILS: PLEASE CHECK OUT INSULATION IN THE EAST-WEST PIPERACK ON THE 2ND
LEVEL IN OXIDE BLOCK FOR ASBESTOS AND REMOVE OR REPAIR. SEE
RICHARD BASALDUA AT COGEN BLDG. 428 OR PHONE 2031 OR 5358 FOR
BETTER LOCATION OF SUSPECTED ASBESTOS INSULATION.

THANKS BB DEL COGEN PHONE 2592
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 060496 LAST ACT: N DATE: 112196

PF3:RETURN

003477

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A76178 ORIG WR: A76022 PROCESS ID: 96 FALLSD
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: PROVIDE INSUL. PLANNER BUTYL
BLD/UNT: BUTYL AR: CH WK TP: 4 WANTED: 112296 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 060496 HWP: MTAG: SLIPBL:
SERV: BU0001 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M6 PLAN CD: 0406 ASIS/ENGR: EST START: 07 01 96
DATE COMPLETE: 111596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 4900 4760

JOB DETAILS: PLEASE PROVIDE AN INSULATOR TO HELP PLAN THE ODU TURNAROUND IN
SEPTEMBER. SEE BOSCO FOR MORE INFORMATION.

DEL PHONE 2617
YTD TOTAL HRS: 476 YTD O/T: 38 YTD LAB\$: 13835 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 060496 LAST ACT: N DATE: 112296

PF3:RETURN

003478

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 4 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
					T	SP	T	PR	CAT	WRITN	WANTED	CLOSED

<== SORT SELECTION LINE ==>

A75231	*J			REPAIR COMPRESSOR BLDG ROOF	C	M0	8	3	SC	051796	101196	101196
A71222	J			ASBESTOS REMOVAL IN OL2 SEP.	Y	M0	8	4	RP	031196	031197	
A70930	*J			REPAIR INSUL. AT CONF.CORNER	Y	M0	8	4	RP	030696	030697	
A70929	J			PIPE RACK INSULATIO S,OF OX	Y	M0	8	4	RP	030696	030697	
A70926	J			PIPE RACK BLOCK 22 S.OF COGEN	Y	M0	8	4	RP	030696	030697	
A70925	J			BLOCK 15 W. OF ODU	Y	M0	8	4	SC	030696	030697	
A69070	I			SECURE & REMOVE POSS.ASBESTOS	1	M0	8	4	RP	020596	123196	
A68468	J			REMOVE ASBES.INSUL.AT O2 UNIT	C	M0	4	2	SC	012696	12SA74	110596
A67304	*J			SEAL FURN AREA ASBESTOS INSUL	Y	M0	8	4	SA	011196	011197	
A66582	J			REMOVE ASBES.HOT COMP.AT LP-1	1	M0	8	4	SE	010296	113096	
A66581	J			REMOVE ASBESTOS AT LP-1 RXN.	1	M0	8	4	SE	010296	113096	
A66191	I			STRIP INSULATION ON STM. LEGS	1	M0	8	4	SE	122195	123196	
A63709	J			SAMPLE ARC CANS FOR ASBESTOS	C	M0	8	3	SE	110795	093096	092596
A58387	J			INSPECT MECH.RM.OL-2 B-501	1	M0	8	4	SC	081695	113096	

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003479

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A75231 ORIG WR: 116400 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: SC RW CD: RW RS: DESC: REPAIR COMPRESSOR BLDG ROOF
BLD/UNT: OLCOM AR: OL WK TP: 8 WANTED: 101196 RECNO: PROP NO:
REQ BY: SIMMONS C&P: WRITTEN: 051796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101196 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 390 370

JOB DETAILS: REPAIR/REPLACE MISSING PANEL ON TOP OF COMPRESSOR BLDG ROOF.
SEE JOHN SIMMONS FOR DETAILS.

DEL PHONE 2965
YTD TOTAL HRS: 37 YTD O/T: 0 YTD LAB\$: 1068 YTD MAT\$: 43
IND: J CL YR: 96 DATE ENTR: 051796 LAST ACT: N DATE: 102596

PF3:RETURN

003480

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A71222 ORIG WR: 119997 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: 82 WCAT: RP RW CD: RW RS: DESC: ASBESTOS REMOVAL IN OL2 SEP.
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 031197 RECNO: PROP NO:
REQ BY: B WARZECHA C&P: WRITTEN: 031196 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: Y PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 03 11 96
DATE COMPLETE: APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 2160 1120

JOB DETAILS: REMOVE ASBESTOS AS NEEDED IN OLEFINS SEPARATIONS AREA. TO COVER
THE COST OF REMOVING, REPIARING, SAMPLING, & MAINTAINING ASBESTOS
INSUL. IN UNIT.

DEL PHONE 2536
YTD TOTAL HRS: 112 YTD O/T: 0 YTD LAB\$: 3233 YTD MAT\$: 700
IND: J CL YR: 95 DATE ENTR: 031196 LAST ACT: N DATE: 102596

PF3:RETURN

003481

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A70930 ORIG WR: 113609 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: WCAT: RP RW CD: RW RS: DESC: REPAIR INSUL. AT CONF. CORNER
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 030697 RECNO: PROP NO:
REQ BY: BBBROWNING C&P: WRITTEN: 030696 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: Y PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 03 06 96
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 4800 3825 00 00 100

JOB DETAILS: REPAIR INSULATION AT CONFUSION CORNER. MAINTINANCE & REPAIRS TO
ASBESTOS INSUL. IN PIPERACK.

YTD TOTAL HRS: 392 YTD O/T: 25 YTD LAB\$: 11366 YTD MAT\$: 436
IND: J CL YR: 95 DATE ENTR: 030696 LAST ACT: C DATE: 111496

PF3: RETURN

003482

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A70929 ORIG WR: 113609 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: WCAT: RP RW CD: RW RS: DESC: PIPE RACK INSULATIO S,OF OX
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 030697 RECNO: PROP NO:
REQ BY: BBBROWNING C&P: WRITTEN: 030696 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: Y PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 03 06 96
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 6990 4865

JOB DETAILS: REPAIRS TO PIPE RACK INSULATION SOUTH OF OXIDE.MAINTINANCE &
REPAIR OF ASBESTOS INSUL.

DEL PHONE
YTD TOTAL HRS: 486 YTD O/T: 93 YTD LAB\$: 14322 YTD MAT\$: 3617
IND: J CL YR: 95 DATE ENTR: 030696 LAST ACT: N DATE: 110196

PF3:RETURN

003483

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A70926 ORIG WR: 113609 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: WCAT: RP RW CD: RW RS: DESC: PIPE RACK BLOCK 22 S.OF COGEN
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 030697 RECNO: PROP NO:
REQ BY: BBBROWNING C&P: WRITTEN: 030696 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: Y PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 03 06 96
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 2820 880

JOB DETAILS: REPAIRS TO INSULATIONS IN BLOCK 22 S. OF COGEN.MAINTENANCE TO
ASBESTOS INSUL.IN PIPE RACK.

YTD TOTAL HRS: 88 YTD O/T: 0 YTD LAB\$: 2540 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 030696 LAST ACT: N DATE: 092696

PF3:RETURN

003484

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A70925 ORIG WR: 113609 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: WCAT: SC RW CD: RW RS: DESC: BLOCK 15 W. OF ODU
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 030697 RECNO: PROP NO:
REQ BY: BBBROWNING C&P: WRITTEN: 030696 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: Y PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 03 06 96
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 2280 490

JOB DETAILS: REPAIRS TO INSULATION IN BLOCK 15 (ODU AREA) .FOR MAINTENANCE &
SAMPLING OF ASBESTOS INSUL.IN PIPERACK.

DEL PHONE
YTD TOTAL HRS: 49 YTD O/T: 0 YTD LAB\$: 1415 YTD MAT\$: 266
IND: J CL YR: 96 DATE ENTR: 030696 LAST ACT: N DATE: 100996

PF3:RETURN

003485

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A69070 ORIG WR: A47976 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: 82 WCAT: RP RW CD: RW RS: DESC: SECURE & REMOVE POSS.ASBESTOS
BLD/UNT: OL-2 AR: OL WK TP: 8 WANTED: 123196 RECNO: PROP NO:
REQ BY: A.URESTI C&P: WRITTEN: 020596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 2430 2125

JOB DETAILS: SECURE & REMOVE POSSIBLE ASBESTOS INSULATION IN PIPERACK
NORTH OF 306

DEL PHONE 2982
YTD TOTAL HRS: 212 YTD O/T: 0 YTD LAB\$: 6136 YTD MAT\$: 1401
IND: I CL YR: 96 DATE ENTR: 020796 LAST ACT: N DATE: 110896

PF3:RETURN

003486

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A68468 ORIG WR: 111625 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 008510 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: WCAT: SC RW CD: RW RS: DESC: REMOVE ASBES.INSUL.AT O2 UNIT
BLD/UNT: E/S AR: ES WK TP: 4 WANTED: 12SA74 RECNO: 000747 PROP NO:
REQ BY: BBBROWNING C&P: WRITTEN: 012696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 110596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 510 490 00 00 10

JOB DETAILS: REMOVE ASBESTOS INSULATION FROM STEAM PIPING AT THE O2 UNIT.
CONTACT THE OPERATOR OR RICK GOMEZ FOR LOCATION.SOME OF THIS
WORK WILL NEED TO TAKE PLACE WHEN STEAM CAN BE VALVED IN.
UNIT WILL NOTIFY WHEN JOB CAN TAKE PLACE.POSSIBLE S\D.

DEL PHONE
YTD TOTAL HRS: 50 YTD O/T: 5 YTD LAB\$: 1454 YTD MAT\$: 2
IND: J CL YR: 96 DATE ENTR: 012696 LAST ACT: N DATE: 112196

PF3:RETURN

003487

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A67304 ORIG WR: 119587 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: 82 WCAT: SA RW CD: RW RS: DESC: SEAL FURN AREA ASBESTOS INSUL
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 011197 RECNO: PROP NO:
REQ BY: OSPINA C&P: WRITTEN: 011196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: Y PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 7900 6820 00 00 230

JOB DETAILS: FURNACE AREA LINES NEED TO HAVE ASBESTOS INSULATION SEALED.
CONTACT JAVIER OSPINA FOR DETAILS.SOME REMOVAL ALSO INVOLVED.

DEL PHONE 2608
YTD TOTAL HRS: 705 YTD O/T: 0 YTD LAB\$: 20275 YTD MAT\$: 1253
IND: J CL YR: 94 DATE ENTR: 011296 LAST ACT: N DATE: 091096

PF3:RETURN

003488

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A66582 ORIG WR: 155581 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: 83 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBES.HOT COMP.AT LP-1
BLD/UNT: LP1F AR: L1 WK TP: 8 WANTED: 113096 RECNO: PROP NO:
REQ BY: FRANK BEN. C&P: WRITTEN: 010296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 01 02 96
DATE COMPLETE: APPROVED BY: T.T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 3560 380

JOB DETAILS: PLEASE REMOVE OR REPAIR INSULATION LOCATED IN THE HOT COMPOUND
AREA WEST OF THE CONTROL ROOM NEXT TO STAIRWAY.GARY K. KNOWS
LOCATION.

DEL B-341 PHONE 2832
YTD TOTAL HRS: 38 YTD O/T: 0 YTD LAB\$: 1097 YTD MAT\$: 901
IND: J CL YR: 95 DATE ENTR: 010296 LAST ACT: N DATE: 111296

PF3:RETURN

003489

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A66581 ORIG WR: 154412 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148310 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: 83 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS AT LP-1 RXN.
BLD/UNT: LP1R AR: L1 WK TP: 8 WANTED: 113096 RECNO: PROP NO:
REQ BY: BOEHM C&P: WRITTEN: 010296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 01 02 96
DATE COMPLETE: APPROVED BY: T.T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 4180 90

JOB DETAILS: REMOVE ASBESTOS FROM JUNCTION BOXES & CONDUIT LINES IN PIPERACK
EAST OF THE REACTION CONTROL RM. GARY K. KNOWS LOCATION.

DEL 343 PHONE 2832
YTD TOTAL HRS: 9 YTD O/T: 0 YTD LAB\$: 260 YTD MAT\$: 60
IND: J CL YR: 95 DATE ENTR: 010296 LAST ACT: N DATE: 102596

PF3: RETURN

003490

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A66191 ORIG WR: A60261 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: 31 WCAT: SE RW CD: RW RS: DESC: STRIP INSULATION ON STM. LEGS
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 123196 RECNO: PROP NO:
REQ BY: C FANELLI C&P: WRITTEN: 122195 HWP: MTAG: SLIPBL:
SERV: COGEN STM SYSTE DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 12 28 95
DATE COMPLETE: APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 5500 4885

JOB DETAILS: PLEASE STRIP INSULATION OFF OF VARIOUS STEAM LEGS THROUGHOUT THE
UTILITIES PIPE RACKS. NEW PIPE WILL HAVE TO BE REINSULATED. THANK-
YOU. SEE C. FANELLI AT 5-802 FOR ADDITIONAL INFO.

DEL PHONE 3589
YTD TOTAL HRS: 488 YTD O/T: 0 YTD LAB\$: 14101 YTD MAT\$: 2062
IND: I CL YR: 95 DATE ENTR: 122195 LAST ACT: N DATE: 103196

PF3:RETURN

003491

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63709 ORIG WR: 135617 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: SAMPLE ARC CANS FOR ASBESTOS
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 093096 RECNO: PROP NO:
REQ BY: KRAUSE/AT C&P: WRITTEN: 110795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 092596 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 950 870

JOB DETAILS: PLEASE SAMPLE EACH CAN SECTION ON ARC FOR ASBESTOS.
THNX, ANN T. 5-401

DEL PHONE
YTD TOTAL HRS: 80 YTD O/T: 0 YTD LAB\$: 2309 YTD MAT\$: 440
IND: J CL YR: 95 DATE ENTR: 110795 LAST ACT: N DATE: 092696

PF3:RETURN

003492

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58387 ORIG WR: 120311 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 4 OR: 82 WCAT: SC RW CD: RW RS: DESC: INSPECT MECH.RM.OL-2 B-501
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 113096 RECNO: PROP NO:
REQ BY: BOCHAT C&P: WRITTEN: 081695 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: 1 PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 190 80

JOB DETAILS: INSTALL SIGN AND PERFORM VERIFICATION OF ASBESTOS.
LOCATIONS: BLDG 501 CONTROL ROOM BEHIND CONTROL PANELS
BLDG 500 CONTROL ROOM (COMPRESSOR BLDG)
ATTENTION: FRED BERGER

DEL PHONE 2909
YTD TOTAL HRS: 6 YTD O/T: 0 YTD LAB\$: 173 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 081695 LAST ACT: C DATE: 092796

PF3:RETURN

003493

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 5 OF 14
DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK	REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
						T	SP	T	PR	CAT	WRITN	WANTED	CLOSED

<== SORT SELECTION LINE ==>

A58031	J				BLDG.341 ASBESTOS WARNING	C	M0	8	3	SE	081095	113096	100996
A79433	I				REMOVE ASBESTOS GASKET	X	M0	8	1	SE	072996	073196	073196
A79077	J				REMOVE INSULATION	X	M0	8	1		072396	072496	072396
A79074	I				STRIP ASBESTOS FROM GSKTS.	X	M0	8	3	SE	072396	072496	072396
A78665	I				SAMPLE MASTIC HP2-RX2-20	X	M0	4	2		071696	072696	072496
J61820	J				REMOVE ASBESTOS GASKETS	X	M0	8	3	SE	052096	113096	063096
A78393	I				REMOVE MASTIC FROM CHILLER	X	M0	8	3		071196	072296	071996
A78343	J				REMOVE POSSIBLE ASBESTOS	X	M0	8	1	EP	071096	071596	071296
A78022	I				SAMPLE MASTIC FOR (ACM) OL2	X	M0	8	3		070596	071296	071296
A77667	I				REMOVE ASBESTOS GASKETS/DIST.	X	M0	8	3	US	062996	070896	070596
A77209	I				ASBESTOS GASKET REMOVAL HP2	X	M0		2	SD	062196	080296	080296
A71917	I				CHECK CAULK FOR ASBESTOS	X	M0	8	3		032196	072896	072696
A66541	*J				REMOVE ASBESTOS FROM CONDS LIN	X	M0	8	3	SC	010296	073196	073196
A58281	*J				FAB AND INSTALL SIGN	X	M0	8	3	US	081595	083196	073096

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003494

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58031 ORIG WR: 155581 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 83 WCAT: SE RW CD: RW RS: DESC: BLDG.341 ASBESTOS WARNING
BLD/UNT: LP1RX AR: L1 WK TP: 8 WANTED: 113096 RECNO: PROP NO:
REQ BY: B.SAINZ C&P: WRITTEN: 081095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: C PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 08 14 95
DATE COMPLETE: 100996 APPROVED BY: T.T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 270 290

JOB DETAILS: PLEASE INSTALL ASBESTOS WARNING SIGNS ON ALL ENTRY DOORS ON BLDG.
341. ALSO REQUEST ASBESTOS VERIFICATION PER FRED BERGER.
THIS IS THE OLD G-1750 CONTROL ROOM.

DEL B-341 PHONE 2359
YTD TOTAL HRS: 29 YTD O/T: 0 YTD LAB\$: 836 YTD MAT\$: 1083
IND: J CL YR: 95 DATE ENTR: 081095 LAST ACT: N DATE: 110196

PF3:RETURN

003495

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A79433 ORIG WR: A78329 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 303010 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: M2 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 073196 RECNO: PROP NO:
REQ BY: R. BRANDT C&P: WRITTEN: 072996 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 7R30 ASIS/ENGR: EST START: 07 29 96
DATE COMPLETE: 073196 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: PLEASE PROVIDE MANPOWER TO REMOVE ASBESTOS BASKET AT SPRAY GAS
COOLER #4. SEE TERRY MIDDLEAUGH FROM BROWN & ROOT IN UNIT FOR
DETAILS, OR CALL RUSSELL BRANDT AT PAGER 5-509; EXT. 3778.

DEL PHONE 2828
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LABS: 0 YTD MAT\$: 204
IND: I CL YR: 96 DATE ENTR: 080296 LAST ACT: N DATE: 092496

PF3:RETURN

003496

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A79077 ORIG WR: 122900 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 76 WCAT: RW CD: RW RS: DESC: REMOVE INSULATION
BLD/UNT: HP-2 AR: WK TP: 8 WANTED: 072496 RECNO: PROP NO:
REQ BY: F.DROZD C&P: WRITTEN: 072396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 237R ASIS/ENGR: EST START: 07 23 96
DATE COMPLETE: 072396 APPROVED BY: EDMYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 120

JOB DETAILS: PLEASE REMOVE INSULATION ON 1ST STAGE CYLINDER ON
VENT GAS MACHINE.

DEL PHONE 2749
YTD TOTAL HRS: 12 YTD O/T: 0 YTD LAB\$: 346 YTD MAT\$: 241
IND: J CL YR: 96 DATE ENTR: 072396 LAST ACT: N DATE: 080196

PF3:RETURN

003497

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A79074 ORIG WR: A78585 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 12 WCAT: SE RW CD: RW RS: DESC: STRIP ASBESTOS FROM GSKTS.
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 072496 RECNO: PROP NO:
REQ BY: C FANELLI C&P: WRITTEN: 072396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: R723 ASIS/ENGR: EST START: 07 23 96
DATE COMPLETE: 072396 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 80

JOB DETAILS: PLEASE STRIP 8" FLANGE OF ASBESTOS GASKETS. SEE C FANELLI AT
5-802 FOR DETAILS. THANKYOU.

DEL PHONE 2304
YTD TOTAL HRS: 8 YTD O/T: 0 YTD LAB\$: 231 YTD MAT\$: 233
IND: I CL YR: 96 DATE ENTR: 072396 LAST ACT: N DATE: 080196

PF3:RETURN

003498

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A78665 ORIG WR: A72220 PROCESS ID: EA-612
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: SAMPLE MASTIC HP2-RX2-20
BLD/UNT: HPPE2 AR: H2 WK TP: 4 WANTED: 072696 RECNO: 012100 PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 071696 HWP: MTAG: SLIPBL:
SERV: RX2-20 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 167R ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 072496 APPROVED BY: E.MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 90 220

JOB DETAILS: PLEASE SAMPLE THE MASTIC ON THE EAST VENT GAS COOLER FOR POSSIBLE
ASBESTOS CONTAINING MATERIALS. SEE BOSCO FOR LOCATION AND DETAILS.

DEL PHONE 2617
YTD TOTAL HRS: 22 YTD O/T: 0 YTD LAB\$: 635 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 071696 LAST ACT: N DATE: 080396

PF3:RETURN

003499

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J61820 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006355 2ND ORD: 73000
PR: 3 OR: CW WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: AIR AR: ES WK TP: 8 WANTED: 113096 RECNO: PROP NO:
REQ BY: C WELFEL C&P: WRITTEN: 052096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 063096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1615 1515

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS FROM SCRAP PIPE BY OLD AIR BUILDING
WEST OF OXIDE II. CONTACT DON LEITA (WOP) @ 2914 OR RADIO #12 ON
CONSTRUCTION FREQUENCY. C. WELFEL PAGER 5-183

DEL PHONE 2467
YTD TOTAL HRS: 151 YTD O/T: 0 YTD LAB\$: 4373 YTD MAT\$: 306
IND: J CL YR: 96 DATE ENTR: 052096 LAST ACT: N DATE: 101696

PF3:RETURN

003500

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A78393 ORIG WR: A75149 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M6 WCAT: RW CD: RW RS: DESC: REMOVE MASTIC FROM CHILLER
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 072296 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 071196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 11R7 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 071996 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 210 140

JOB DETAILS: PLEASE REMOVE THE NON-FRIABLE ASBESTOS MASTIC FROM THE GLYCOL
CHILLER AT OLEFINS. SEE BOSCO OR RICKY CARTER FOR MORE DETAILS

DEL PHONE 2617
YTD TOTAL HRS: 14 YTD O/T: 0 YTD LAB\$: 404 YTD MAT\$: 129
IND: I CL YR: 96 DATE ENTR: 071196 LAST ACT: N DATE: 091496

PF3:RETURN

003501

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A78343 ORIG WR: 243692 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 231940 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 15 WCAT: EP RW CD: RW RS: DESC: REMOVE POSSIBLE ASBESTOS
BLD/UNT: EVP AR: EP WK TP: 8 WANTED: 071596 RECNO: PROP NO:
REQ BY: GALLEMORE C&P: WRITTEN: 071096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 071296 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 120

JOB DETAILS: PLEASE REMOVE POSSIBLE ASBESTOS FROM DEA LEAK AT N.FIELD SO
THAT REPAIRS CAN BE MADE AND CLEANUP CAN BEGIN.

DEL PHONE 3584
YTD TOTAL HRS: 12 YTD O/T: 12 YTD LAB\$: 383 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 071896 LAST ACT: N DATE: 072696

PF3:RETURN

003502

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A78022 ORIG WR: A73044 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 10 WCAT: RW CD: RW RS: DESC: SAMPLE MASTIC FOR (ACM) OL2
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 071296 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 070596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 5K65 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 071296 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 100 60

JOB DETAILS: PLEASE SAMPLE THE MASTIC ON THE GLYCOL CHILLER FOR POSSIBLE
ASBESTOS CONTAINING MATERIALS. SEE BOSCO FOR MORE INFORMATION.

DEL PHONE 2617
YTD TOTAL HRS: 6 YTD O/T: 0 YTD LAB\$: 173 YTD MAT\$: 90
IND: I CL YR: 96 DATE ENTR: 070696 LAST ACT: N DATE: 080696

PF3:RETURN

003503

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A77667 ORIG WR: A74538 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 231940 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 11 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS/DIST.
BLD/UNT: DIST AR: DI WK TP: 8 WANTED: 070896 RECNO: PROP NO:
REQ BY: J. RAMIREZ C&P: WRITTEN: 062996 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 0701 ASIS/ENGR: EST START: 07 01 96
DATE COMPLETE: 070596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 210 80

JOB DETAILS: PLEASE REMOVE 4-3" ASBESTOS GASKETS OF THE FLANGES LOCATED ON THE
NORTH SIDE OF THE TRUCK LOADING RACK AT DISTRIBUTION/NORTH FIELD.
WILL SHOW LOCATION OF PIPE SPOOLS WHEN READY. THANKS, JUAN 5-801.

DEL CALL WHEN COMPLETE PHONE 3583
YTD TOTAL HRS: 8 YTD O/T: 0 YTD LAB\$: 231 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 070196 LAST ACT: N DATE: 072396

PF3:RETURN

003504

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A77209 ORIG WR: A76828 PROCESS ID: HPA3-K-204M
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: SD RW CD: RW RS: DESC: ASBESTOS GASKET REMOVAL HP2
BLD/UNT: HPPE2 AR: H2 WK TP: WANTED: 080296 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 062196 HWP: MTAG: SLIPBL:
SERV: RX2-00 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 0621 ASIS/ENGR: EST START: 07 16 96
DATE COMPLETE: 080296 APPROVED BY: E.MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 490 155

JOB DETAILS: PLEASE PROVIDE AN ASBESTOS QUALIFIED PERSON TO REMOVE GASKETS AS
NEEDED DURING THE #2 REACTOR TURNAROUND. SEE BOSCO OR J. ESTRADA.

DEL PHONE 2617
YTD TOTAL HRS: 15 YTD O/T: 0 YTD LAB\$: 447 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 062196 LAST ACT: N DATE: 082496

PF3:RETURN

003505

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A71917 ORIG WR: A70994 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 293240 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M7 WCAT: RW CD: RW RS: DESC: CHECK CAULK FOR ASBESTOS
BLD/UNT: NF AR: DI WK TP: 8 WANTED: 072896 RECNO: PROP NO:
REQ BY: BOB BLACK C&P: WRITTEN: 032196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: FAB ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 072696 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 770 520

JOB DETAILS: CHECK CAULKING ON SEVERAL TANKS IN NORTH FIELD FOR
ASBESTOS. WILL SHOW YOU THE TANKS.REMOVE GASKET MATERIAL AS
NECESSARY FOR BLASTING.

DEL PAGER 534 PHONE 2672
YTD TOTAL HRS: 52 YTD O/T: 0 YTD LAB\$: 1499 YTD MAT\$: 679
IND: I CL YR: 96 DATE ENTR: 032196 LAST ACT: N DATE: 072796

PF3:RETURN

003506

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A66541 ORIG WR: 119927 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS FROM CONDS LIN
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 073196 RECNO: PROP NO:
REQ BY: WARZECHA C&P: WRITTEN: 010296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 073196 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 730 700

JOB DETAILS: REMOVE ASBESTOS INSULATION FROM CONDENSATE LINE SOUTH OF #1 ARU
ACETONE PUMPS SO LINE CAN BE REMOVED.

DEL PHONE 2536
YTD TOTAL HRS: 70 YTD O/T: 0 YTD LAB\$: 2020 YTD MAT\$: 42
IND: J CL YR: 96 DATE ENTR: 010296 LAST ACT: N DATE: 080396

PF3:RETURN

003507

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58281 ORIG WR: 237811 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 220530 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 89 WCAT: US RW CD: RW RS: DESC: FAB AND INSTALL SIGN
BLD/UNT: 82 AR: DI WK TP: 8 WANTED: 083196 RECNO: PROP NO:
REQ BY: B.CANCHOLA C&P: WRITTEN: 081595 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 073096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 310 20

JOB DETAILS: FAB AND INSTALL ASBESTOS PRESENCE SIGN AT MECHANICAL ROOM AT THE B
ARGE DOCKS, WEST SIDE OF BLDG. 82.

DEL PHONE 2524
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 081595 LAST ACT: N DATE: 080396

PF3: RETURN

003508

WLCLIST

*** WORK REQUEST LISTING ***

PAGE .6 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
					T	SP	T	PR	CAT	WRITN	WANTED	CLOSED

<== SORT SELECTION LINE ==>

A77255	J			G-5 GASKET ROOM REMOVE ASBEST.	X	M0	8	3	SA	062496	070596	070296
A76785	I			REMOVE ASBESTOS GASKETS	X	M0	8	3	US	061496	062896	062796
A76761	I			STRIP ASBESTOS GSKTS. (DIST)	X	M0	8	3		061496	062096	061996
A76129	I			REMOVE ASBESTOS GASKETS G5 T/A	X	M0	8	2		060396	062096	061096
A76128	I			REMOVE INSUL AS NEEDED G-5 RX	X	M0	4	2		060396	061496	061096
A76123	J			REMOVE ASBESTOS GASKET	X	M0	4	2	PM	060396	060696	060696
A76078	J			REMOVE ASBES.INSUL.ON #1 BRC	X	M0	8	3	NC	053096	060796	060696
A75561	I			ENCAPSULATE ASBESTOS TUBING	X	M0	8	3		052396	060796	060596
A74955	J			#1 MISC COL NOZZLES	X	M0	8	3	SE	051396	060796	060596
A74730	J			GASKETS ON BINS AT SALVAGE	X	M0	8	3	SC	050996	061496	060596
A73323	J			REMOVE TRANSITE AT PUMP HOUSE	X	M0	8	3	RP	041696	062896	062796
A72184	I			REMOVE ASB. GASKETS (3 FLGS)	X	M0	4	2	SD	032796	061896	061496
A64776	J			ESTIMATE FOR ASBESTOS REMOVAL	X	M0	8	3	SE	112895	061496	061496
A64774	J			ESTIMATE FOR ASBESTOS REMOVAL	X	M0	8	3	SE	112895	061496	061496

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003509

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A77255 ORIG WR: 154412 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148310 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 83 WCAT: SA RW CD: RW RS: DESC: G-5 GASKET ROOM REMOVE ASBEST.
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 070596 RECNO: PROP NO:
REQ BY: MIKE WARD C&P: WRITTEN: 062496 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 2406 ASIS/ENGR: EST START: 06 24 96
DATE COMPLETE: 070296 APPROVED BY: TOM
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 220 240

JOB DETAILS: REMOVE AND DISPOSE OF GASKETS FROM STORAGE ROOM LOCATED ON
THE SECOND FLOOR OF THE G-5 REACTOR STRUCTURE.

DEL B-343 PHONE 2307
YTD TOTAL HRS: 24 YTD O/T: 0 YTD LAB\$: 693 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 062496 LAST ACT: N DATE: 071996

PF3:RETURN

003510

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A76785 ORIG WR: A74679 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 293220 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 11 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: DIST AR: CH WK TP: 8 WANTED: 062896 RECNO: PROP NO:
REQ BY: J. RAMIREZ C&P: WRITTEN: 061496 HWP: X MTAG: X SLIPBL:
SERV: HEXANOL DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 1406 ASIS/ENGR: EST START: 06 14 96
DATE COMPLETE: 062796 APPROVED BY: MORGAN
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 180

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKET OFF THE FLANGE ON THE SOUTH SIDE
OF THE SPHERE. AL HARTMAN WILL SHOW WHICH FLANGE NEEDS TO BE
WORKED ON. I HAVE ALREADY TALKED TO GARY K. THANKS, JUAN 5-801.

DEL PHONE 3583
YTD TOTAL HRS: 18 YTD O/T: 0 YTD LAB\$: 520 YTD MAT\$: 142
IND: I CL YR: 96 DATE ENTR: 061496 LAST ACT: N DATE: 072396

PF3:RETURN

003511

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A76761 ORIG WR: A74538 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 231940 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 11 WCAT: RW CD: RW RS: DESC: STRIP ASBESTOS GSKTS. (DIST)
BLD/UNT: DIST AR: CH WK TP: 8 WANTED: 062096 RECNO: PROP NO:
REQ BY: J. RAMIREZ C&P: WRITTEN: 061496 HWP: MTAG: SLIPBL:
SERV: ASBESTOS DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 1406 ASIS/ENGR: EST START: 06 14 96
DATE COMPLETE: 061996 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 120

JOB DETAILS: PLEASE STRIP THE ASBESTOS GASKETS OFF THE FLANGES THAT CAME OFF
THE FILTER JOB AT DISTRIBUTION. PIPE IS LOCATED ON THE NORTH
SIDE OF THE RAILROAD TRACK AT RACK 2. FOR MORE INFORMATION CALL
3583 OR PAGER #5-456. THANKS.

DEL NORTH OF RACK 2 PHONE 3583
YTD TOTAL HRS: 12 YTD O/T: 0 YTD LAB\$: 346 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 061496 LAST ACT: N DATE: 062796

PF3:RETURN

003512

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A76129 ORIG WR: A75052 PROCESS ID: G-5 REACTOR
DIV/LOC: 500510 ACCOUNT: 148310 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS G5 T/A
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 062096 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 060396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 0306 ASIS/ENGR: EST START: 06 03 96
DATE COMPLETE: 061096 APPROVED BY: TOMT
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 270 345

JOB DETAILS: PLEASE REMOVE THE ASBESTOS GASKET FROM THE G-5 WATER PIPING. SEE
BOSCO FOR DETAILS.

DEL PHONE 2617
YTD TOTAL HRS: 34 YTD O/T: 24 YTD LAB\$: 1070 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 060396 LAST ACT: N DATE: 061596

PF3:RETURN

003513

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A76128 ORIG WR: A75052 PROCESS ID: G-5 REACTOR
DIV/LOC: 500510 ACCOUNT: 148310 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: REMOVE INSUL AS NEEDED G-5 RX
BLD/UNT: LP1 AR: L1 WK TP: 4 WANTED: 061496 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 060396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 0306 ASIS/ENGR: EST START: 06 03 96
DATE COMPLETE: 061096 APPROVED BY: TOMT
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 240 140

JOB DETAILS: PLEASE REMOVE INSULATION AS NEEDED FOR THE PIPEFITTER. DO NOT
RE-INSULATE AT THIS TIME. IF PERSONNEL PROTECTION IS REQUIRED
ON THIS EQUIPMENT A SHOP ORDER WILL BE SENT LATER. SEE BOSCO FOR
LOCATION. (G-5 OUTAGE WORK.)

DEL PHONE 2617
YTD TOTAL HRS: 14 YTD O/T: 0 YTD LAB\$: 404 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 060396 LAST ACT: N DATE: 061596

PF3:RETURN

003514

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A76123 ORIG WR: 158617 PROCESS ID: G2 S. SEAL OIL COO
DIV/LOC: 500510 ACCOUNT: 148700 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 74 WCAT: PM RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET
BLD/UNT: LP2 AR: L2 WK TP: 4 WANTED: 060696 RECNO: PROP NO:
REQ BY: TED C&P: WRITTEN: 060396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 0306 ASIS/ENGR: EST START: 06 03 96
DATE COMPLETE: 060696 APPROVED BY: SEVIER
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 80 00

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKET ON THE G2 SOUTH SEAL OIL
COOLER BETWEEN THE TUBE SHEET AND SHELL. THANKS, TED.

DEL A PHONE 2009
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 49
IND: J CL YR: 96 DATE ENTR: 060396 LAST ACT: N DATE: 071996

PF3:RETURN

003515

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A76078 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006435 2ND ORD: 73000
PR: 3 OR: WCAT: NC RW CD: RW RS: DESC: REMOVE ASBES.INSUL.ON #1 BRC
BLD/UNT: ODU AR: WK TP: 8 WANTED: 060796 RECNO: PROP NO:
REQ BY: B PETERS C&P: WRITTEN: 053096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: 0306 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 060696 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 190 160

JOB DETAILS: REMOVE ASBESTOS INSULATION ON THE #1 BRC COLUMN AS PER LUPE
CORONADO'S INSTRUCTIONS.

DEL PHONE 3450
YTD TOTAL HRS: 16 YTD O/T: 0 YTD LAB\$: 462 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 060396 LAST ACT: N DATE: 060896

PF3:RETURN

003516

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A75561 ORIG WR: A73605 PROCESS ID: FB2-C-5124
DIV/LOC: 500510 ACCOUNT: 148150 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M6 WCAT: RW CD: RW RS: DESC: ENCAPSULATE ASBESTOS TUBING
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 060796 RECNO: 040911 PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 052396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 05 03 96
DATE COMPLETE: 060596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 270 240

JOB DETAILS: PLEASE ENCAPSULATE THE TUBING ON AND AROUND THE HEXENE DEGASSING
COLUMN. SEE BOSCO FOR DETAILS AND LOCATION.
(SEND TO THE ASBESTOS DEPARTMENT)

DEL PHONE 2617
YTD TOTAL HRS: 24 YTD O/T: 0 YTD LAB\$: 693 YTD MAT\$: 108
IND: I CL YR: 96 DATE ENTR: 052396 LAST ACT: N DATE: 070996

PF3:RETURN

003517

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A74955 ORIG WR: 135625 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: #1 MISC COL NOZZLES
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 060796 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 051396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 060596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 340 250

JOB DETAILS: REMOVE ASBESTOS INSULATION AROUND NOZZLES AT BOTTOM OF #1 MISC COL
FOR INSPECTION FOR CORROSION. MIKE BOLDT WILL PROVIDE DETAILS.
THNX, ANN T. 5-401
MIKE BOLDT 2754 5-295

YTD TOTAL HRS: 25 YTD O/T: 0 YTD LAB\$: 721 YTD MAT\$: 12
IND: J CL YR: 96 DATE ENTR: 051396 LAST ACT: N DATE: 062296

PF3:RETURN

003518

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A74730 ORIG WR: 142017 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 094210 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: MM WCAT: SC RW CD: RW RS: DESC: GASKETS ON BINS AT SALVAGE
BLD/UNT: MMD AR: MM WK TP: 8 WANTED: 061496 RECNO: PROP NO:
REQ BY: S.WIEST C&P: WRITTEN: 050996 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 060596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 310 200

JOB DETAILS: STORAGE BINS LOCATED IN THE SALVAGE YARD NEED TO HAVE GASKET
MATERIAL CHECKED TO SEE IF IT IS ASBESTOS. CALL SAM WIEST FOR
LOCATION OF MATERIAL. EXT 2290, PAGER 5-644

DEL PHONE
YTD TOTAL HRS: 20 YTD O/T: 0 YTD LAB\$: 577 YTD MAT\$: 285
IND: J CL YR: 96 DATE ENTR: 050996 LAST ACT: N DATE: 062096

PF3:RETURN

003519

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A73323 ORIG WR: 237812 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 220530 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 89 WCAT: RP RW CD: RW RS: DESC: REMOVE TRANSITE AT PUMP HOUSE
BLD/UNT: PMPHS AR: DI WK TP: 8 WANTED: 062896 RECNO: PROP NO:
REQ BY: N HANKE C&P: WRITTEN: 041696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 062796 APPROVED BY: MORGAN
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 580 1200

JOB DETAILS: REMOVE THE TRANSITE FROM THE INSIDE SOUTH EAST CORNER OF THE
PUMP HOUSE AT THE BARGE DOCK. CONTACT DON MORGAN OR NORMAN HANKE
BEFORE STARTING.

DEL BARGE DOCK PHONE 5622
YTD TOTAL HRS: 120 YTD O/T: 0 YTD LAB\$: 3464 YTD MAT\$: 685
IND: J CL YR: 96 DATE ENTR: 041696 LAST ACT: N DATE: 072396

PF3:RETURN

003520

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A72184 ORIG WR: A71705 PROCESS ID: G-241
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 31 WCAT: SD RW CD: RW RS: DESC: REMOVE ASB. GASKETS (3 FLGS)
BLD/UNT: HPPE2 AR: H2 WK TP: 4 WANTED: 061896 RECNO: PROP NO:
REQ BY: LUCAS 726 C&P: WRITTEN: 032796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: PLAN CD: ASIS/ENGR: EST START: 05 22 96
DATE COMPLETE: 061496 APPROVED BY: E.MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 120

JOB DETAILS: PLEASE REMOVE 3 FLGS. OF ASB. GASKETS. THE VALVE WILL BE REMOVED
IN THE AM OF 5-22-96. LOCATION IN IN THE S/W CORNER, ON #1 HYPER
FLOOR. SEE JIM FOR LOCATION AND EXACT TIME SERVICES NEEDED!

DEL 566 PHONE 2943
YTD TOTAL HRS: 12 YTD O/T: 0 YTD LAB\$: 346 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 033096 LAST ACT: N DATE: 061596

PF3:RETURN

003521

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A64776 ORIG WR: 135136 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: ESTIMATE FOR ASBESTOS REMOVAL
BLD/UNT: BUTYL AR: CH WK TP: 8 WANTED: 061496 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 112895 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 061496 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1120 430

JOB DETAILS: TO COVER THE COST OF ESTIMATING COST FOR ASBESTOS REMOVAL IN BUTYL
FOR '96: 1.#1 BRC COLUMN 2. OTHER ASBESTOS IN BUTYLS THAT MAY BE
IN PIPERACKS, GROUND LEVEL OR SMALL VESSELS. DO NOT INCLUDE RXTRS
OR ANY OTHER LARGE VESSELS. SEPARATE THESE TWO ESTIMATES PLEASE.

THNX, ANN T. 5-401 DEL PHONE
YTD TOTAL HRS: 43 YTD O/T: 0 YTD LAB\$: 1240 YTD MAT\$: 750
IND: J CL YR: 95 DATE ENTR: 112895 LAST ACT: N DATE: 070596

PF3:RETURN

003522

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A64774 ORIG WR: 136558 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071100 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: ESTIMATE FOR ASBESTOS REMOVAL
BLD/UNT: AMINE AR: CH WK TP: 8 WANTED: 061496 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 112895 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 061496 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1120 550 00 00 20

JOB DETAILS: TO COVER THE COST OF ESTIMATING COST FOR ASBESTOS REMOVAL IN AMINE
FOR '96: 1.MAIN STRUCTURE UPPER LEVEL. 2.MAIN STRUCTURE GROUND
LEVEL. 3. AMINES TANK FARM
PLEASE SEPARATE THESE INTO 3 ESTIMATES AS LISTED ABOVE.

THNX, ANN T. 5-401 DEL PHONE
YTD TOTAL HRS: 57 YTD O/T: 0 YTD LAB\$: 1639 YTD MAT\$: 575
IND: J CL YR: 95 DATE ENTR: 112895 LAST ACT: N DATE: 070396

PF3:RETURN

003523

WLCLIST ,

*** WORK REQUEST LISTING ***

PAGE 7 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

T		S	RE	W	WK	DATES					
X	WK REQ	P	JOB DESCRIPTION	T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
	fp		<== SORT SELECTION LINE ==>								
	J70695	J	SAMPLE-REMOVE INSUL.AT HP-2	X	M0	8	1	SC	042496	051096	050696
	A75651	I	REMOVE ASBES.GASKETS #14 COMP.	X	M0	8	1	SD	052596	052596	052896
	A75410	J	REMOVE ASBESTOS GASKETS	X	M0	8	1	SC	052196	053196	052496
	A75189	I	CHECK FOR ASBESTOS	X	M0	8	3		051696	053096	052496
	A74860	I	REMOVE ASB GSKETS OLEFINS	X	M0	8	3	SC	051096	051396	051496
	A74857	I	REMOVE ASB ON VAC TOWER	X	M0	8	3	SD	051096	051096	051496
	A74846	I	HC-5 CYCLE WATER PIPE ASBESTAS	X	M0	8	2	SE	051096	051096	051096
	A74510	J	E-LINE HTRS CONDS LINE ASBESTS	X	M0	8	3	SC	050696	060796	053196
	A74362	J	SAMPLE FOR ASBESTOS ENTRY	X	M0	8	3	PM	050296	051496	051496
	A71816	J	SAMPLE BLDG 327 ROOF	X	M0	8	3	SC	032096	050396	050696
	J61827	J	REMOVE ASBESTOS GASKETS	X	M0	8	3	SC	031596	032996	040596
	A73899	J	ASBESTOS INSULATION	X	M0	8	1		042596	053096	043096
	A73819	I	REMOVE ASB GASKETS @ 561	X	M0	8	3	SC	042496	042696	043096
	A73735	J	INCAPSULATE ASBESTOS INSULATIO	X	M0	8	3	SC	042396	042696	043096

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003524

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J70695 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006408 2ND ORD: 73000
PR: 1 OR: CW WCAT: SC RW CD: RW RS: DESC: SAMPLE-REMOVE INSUL.AT HP-2
BLD/UNT: HP11 AR: H2 WK TP: 8 WANTED: 051096 RECNO: PROP NO:
REQ BY: C. WELFEL C&P: WRITTEN: 042496 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 050696 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 300 640

JOB DETAILS: PLEASE SAMPLE DUCT WORK AT HPPEII FOR ASBESTOS AND REMOVE IF
NECESSARY. CONTACT L. CORONADO OR J. WEST FOR LOCATION.

DEL PHONE 2467
YTD TOTAL HRS: 64 YTD O/T: 0 YTD LAB\$: 1848 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 042696 LAST ACT: N DATE: 052996

PF3: RETURN

003525

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A75651 ORIG WR: A75615 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: WCAT: SD RW CD: RW RS: DESC: REMOVE ASBES.GASKETS #14 COMP.
BLD/UNT: OLCOM AR: OL WK TP: 8 WANTED: 052596 RECNO: PROP NO:
REQ BY: J.REYNA C&P: WRITTEN: 052596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 052896 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS FROM THE #14 COMPRESSOR WHEN THE
EQUIPMENT IS LIFTED FOR SHIPPING TO BE STEAM CLEANED.
THANK YOU.

DEL PHONE 2965
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 204
IND: I CL YR: 96 DATE ENTR: 052796 LAST ACT: N DATE: 061496

PF3:RETURN

003526

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A75410 ORIG WR: 119987 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 82 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 053196 RECNO: PROP NO:
REQ BY: WARZECHA C&P: WRITTEN: 052196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 052496 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 120

JOB DETAILS: REMOVE ASBESTOS GASKETS FROM EKL VAPORIZER. NEED THIS DONE
BY 5/22 SO T&I CAN INSPECT VAPORIZER.

DEL PHONE 2536
YTD TOTAL HRS: 12 YTD O/T: 0 YTD LAB\$: 346 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 052196 LAST ACT: N DATE: 060396

PF3:RETURN

003527

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A75189 ORIG WR: A72727 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 327480 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M3 WCAT: RW CD: RW RS: DESC: CHECK FOR ASBESTOS
BLD/UNT: B-2 AR: WK TP: 8 WANTED: 053096 RECNO: PROP NO:
REQ BY: S SANDERS C&P: WRITTEN: 051696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 052496 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: CHECK MATERIAL THAT IS COMING OFF CEILING FOR ASBESTOS IN
B-2 IH LAB NE PART OF BUILDING

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 105
IND: I CL YR: 96 DATE ENTR: 051696 LAST ACT: N DATE: 060896

PF3:RETURN

003528

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A74860 ORIG WR: A74421 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 12 WCAT: SC RW CD: RW RS: DESC: REMOVE ASB GSKETS OLEFINS
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 051396 RECNO: PROP NO:
REQ BY: M ADKINS C&P: WRITTEN: 051096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 05 13 96
DATE COMPLETE: 051496 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 100

JOB DETAILS: PLEASE REMOVE GASKETS ON PIPE THAT WAS REMOVED FROM RACK SO IT
CAN BE HAULED TO SALVAGE. UNIT WANTS PIPE REMOVED FROM UNIT.
PIPE IS LOCATED SOUTH SIDE.
THANKS

DEL PHONE
YTD TOTAL HRS: 10 YTD O/T: 0 YTD LAB\$: 289 YTD MAT\$: 236
IND: I CL YR: 96 DATE ENTR: 051096 LAST ACT: N DATE: 060696

PF3:RETURN

003529

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A74857 ORIG WR: A73042 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 12 WCAT: SD RW CD: RW RS: DESC: REMOVE ASB ON VAC TOWER
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 051096 RECNO: PROP NO:
REQ BY: M ADKINS C&P: WRITTEN: 051096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 051496 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 100

JOB DETAILS: WORK WAS DONE ALREADY. THIS IS TO COVER THE COST.

YTD TOTAL HRS: 10 YTD O/T: 0 YTD LAB\$: 289 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 051096 LAST ACT: N DATE: 060196
DEL 501 PHONE 5298

PF3:RETURN

003530

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A74846 ORIG WR: A74185 PROCESS ID: HC-5 PIPING
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 83 WCAT: SE RW CD: RW RS: DESC: HC-5 CYCLE WATER PIPE ASBESTAS
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 051096 RECNO: PROP NO:
REQ BY: BINO C&P: WRITTEN: 051096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 05 10 96
DATE COMPLETE: 051096 APPROVED BY: TOM T
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 50

JOB DETAILS: REMOVE ASBESTOS GASKETS FROM PIPING REMOVED FROM HC-5,
SO BINO CAN DISPOSE OF PIPING THIS AFTERNOON.

DEL B-353 PHONE 2832
YTD TOTAL HRS: 5 YTD O/T: 0 YTD LAB\$: 144 YTD MAT\$: 78
IND: I CL YR: 96 DATE ENTR: 051096 LAST ACT: N DATE: 060196

PF3:RETURN

003531

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A74510 ORIG WR: 119987 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: SC RW CD: RW RS: DESC: E-LINE HTRS CONDS LINE ASBESTS
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 060796 RECNO: PROP NO:
REQ BY: WARZECHA C&P: WRITTEN: 050696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 053196 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 270 140

JOB DETAILS: PLEASE STRIP ASBESTOS INSULATION UP TO FIRST FLANGE GOING
EAST FROM LEAKING ELBOW ON THE CONDENSATE LINE COMING FROM
THE E-LINE HEATERS. SEE BREND FOR QUESTIONS ON LOCATION.

DEL PHONE 2536
YTD TOTAL HRS: 14 YTD O/T: 0 YTD LAB\$: 404 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 050796 LAST ACT: N DATE: 060896

PF3:RETURN

003532

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A74362 ORIG WR: 135605 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: PM RW CD: RW RS: DESC: SAMPLE FOR ASBESTOS ENTRY
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 051496 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 050296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 051496 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 150 220

JOB DETAILS: WILL REQUIRE SCAFFOLD INSIDE UPPER ISO COL TO REACH. SCAFFOLD WILL
BE PUT IN 5 03 AM. ENTRY IS VERY TIGHT & CONGESTED INSIDE.
T&I REQUIRES INSULATION CUTS FOR INSPECTION. NEED TO KNOW IF THIS
IS ASBESTOS (VESSEL FLOOR UNDERSIDE) THNX, ANN T. 5-401

DEL PHONE
YTD TOTAL HRS: 22 YTD O/T: 0 YTD LAB\$: 635 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 050296 LAST ACT: N DATE: 051596

PF3:RETURN

003533

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A71816 ORIG WR: 337100 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 333010 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 44 WCAT: SC RW CD: RW RS: DESC: SAMPLE BLDG 327 ROOF
BLD/UNT: BL327 AR: GF WK TP: 8 WANTED: 050396 RECNO: PROP NO:
REQ BY: R. MAREK C&P: WRITTEN: 032096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 050696 APPROVED BY: RNT
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 450 410

JOB DETAILS: SAMPLE BUILDING 327 ROOF FOR ASBESTOS

YTD TOTAL HRS: 41 YTD O/T: 0 YTD LABS: 1183 YTD MATS: 1080
IND: J CL YR: 96 DATE ENTR: 032096 LAST ACT: N DATE: 051496

PF3:RETURN

003534

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J61827 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006407 2ND ORD: 73000
PR: 3 OR: CW WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: HPPE2 AR: H2 WK TP: 8 WANTED: 032996 RECNO: PROP NO:
REQ BY: C WELFEL C&P: WRITTEN: 031596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 040596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 140 120

JOB DETAILS: PLEASE REMOVE 8 ASBESTOS GASKETS IN HPPE-2 BY BIN PROJECT.
CONTACT DON LEITA AT X-2914 OR RADIO # 12 (CONSTRUCTION RADIO)

DEL PHONE 2467
YTD TOTAL HRS: 12 YTD O/T: 0 YTD LAB\$: 345 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 031596 LAST ACT: N DATE: 040696

PF3:RETURN

003535

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A73899 ORIG WR: 119987 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 82 WCAT: RW CD: RW RS: DESC: ASBESTOS INSULATION
BLD/UNT: OLSEP AR: WK TP: 8 WANTED: 053096 RECNO: PROP NO:
REQ BY: J.DELGADO C&P: WRITTEN: 042596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 043096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 130 80

JOB DETAILS: CLEAN UP ASBESTOS INSULATION ON SIDE WALK.

DEL PHONE 2965
YTD TOTAL HRS: 8 YTD O/T: 8 YTD LAB\$: 255 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 042596 LAST ACT: N DATE: 050396

PF3:RETURN

003536

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A73819 ORIG WR: A71983 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 09 WCAT: SC RW CD: RW RS: DESC: REMOVE ASB GASKETS @ 561
BLD/UNT: HPPE2 AR: H2 WK TP: 8 WANTED: 042696 RECNO: PROP NO:
REQ BY: LUCAS 726 C&P: WRITTEN: 042496 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 043096 APPROVED BY: E.MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 100

JOB DETAILS: PLEASE REMOVE ASB GASKETS ON PIPE FLGS. AT 561 (S/W CORNER). WE
NEED TO SALVAGE AND REUSE THE 4" CK. VALVE.
SEE JIM FOR LOCATION

DEL 561 PHONE 2943
YTD TOTAL HRS: 10 YTD O/T: 0 YTD LAB\$: 289 YTD MAT\$: 0
IND: I CL YR: 96 DATE ENTR: 042496 LAST ACT: N DATE: 050396

PF3:RETURN

003537

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A73735 ORIG WR: 136540 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071100 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SC RW CD: RW RS: DESC: INCAPSULATE ASBESTOS INSULATIO
BLD/UNT: ODU AR: CH WK TP: 8 WANTED: 042696 RECNO: PROP NO:
REQ BY: ANN T/J.M. C&P: WRITTEN: 042396 HWP: MTAG: SLIPBL:
SERV: STEAM DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 043096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 280

JOB DETAILS: PLEASE INCAPSULATE 3/4" STEAM PIPE FOR REMOVAL. JOB HAS ALREADY BEE
N SHOWN TO INSULATING CREW. E

DEL PHONE 2750
YTD TOTAL HRS: 28 YTD O/T: 0 YTD LAB\$: 808 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 042396 LAST ACT: N DATE: 060196

PF3:RETURN

003538

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 8 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

T		S	RE	W	WK	DATES					
X	WK REQ	P	JOB DESCRIPTION	T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
FP <== SORT SELECTION LINE ==>											
	A72809	I	RMV ASB GASKET MAT'L- O2 UNIT	X	M0	4	2	TA	040996	041796	041496
	A72445	J	REMOVE ASBESTOS INSULATION	X	M0	8	1	RP	040296	040896	040896
	A72130	I	ENCAPSULATE ACM AT N.T.F.	X	M0	8	3		032796	042696	042996
	A72128	I	SAMPLE MASTIC AND INSULATION	X	M0	8	3		032796	043096	042496
	A71839	I	SAMPLE LINES FOR (ACM) OXIDE	X	M0	4	2		032196	041996	041796
	A70976	*I	SAMPLE FOR ASBESTOS N/F	X	M0	8	3		030696	042996	041496
	A64061	*J	REMOVE ASBES. GASKETS AT OL-1	X	M0	8	3	SC	111395	032996	040996
	A72303	I	REMOVE ASBESTO GASKETS G1750	X	M0	8	1	SE	032996	032996	033096
	A72282	J	REMOVE ASBESTOS	X	M0	8	1	RP	032996	032996	033096
	A71811	I	SAMPLE INSULATION AT O2 UNIT	X	M0	8	3		032096	040496	032796
	A71538	I	G-1750 NITROGEN HEATER	X	M0	8	1	SE	031596	031596	032096
	A71508	I	ASBESTOS REMOVAL BLDG 13	X	M0	8	1	SA	031496	031496	032096
	A70163	J	ENCAPSULATE ASB INSUL ON FLNGS	X	M0	8	3	SE	022396	032996	033096
	A69603	J	ASBESTOS MASTIC	X	M0	8	3	SA	021396	031596	030596

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003539

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A72809 ORIG WR: A68890 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 008510 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: TA RW CD: RW RS: DESC: RMV ASB GASKET MAT'L- O2 UNIT
BLD/UNT: ASU AR: ES WK TP: 4 WANTED: 041796 RECNO: PROP NO:
REQ BY: CONTRERAS C&P: WRITTEN: 040996 HWP: MTAG: SLIPBL:
SERV: COOLING WTR PMP DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: JC PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 041496 APPROVED BY: DWJ(JC)
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 40 210

JOB DETAILS: REMOVE ASBESTOS GASKET MATERIAL FROM 16"-150# CHECK VALVE AND
FLANGES ON COOLING WATER PUMP AT O2 UNIT.

YTD TOTAL HRS: 21 YTD O/T: 0 YTD LAB\$: 606 YTD MAT\$: 131
IND: I CL YR: 96 DATE ENTR: 040996 LAST ACT: N DATE: 050396
JOE CONTRERAS 5-221
DEL O2 UNIT PHONE 3009

PF3:RETURN

003540

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A72445 ORIG WR: 292916 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 291740 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 89 WCAT: RP RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNT: NF AR: DI WK TP: 8 WANTED: 040896 RECNO: PROP NO:
REQ BY: BITTERLY C&P: WRITTEN: 040296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 040896 APPROVED BY: MORGAN
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 175

JOB DETAILS: REMOVE INSULATION FROM THE DEA LINE UNDER RACK 2. CONCACT DAVID
BITTERLY FOR EXACT LOCATION

DEL NF PHONE 2296
YTD TOTAL HRS: 17 YTD O/T: 0 YTD LAB\$: 505 YTD MAT\$: 0
IND: J CL YR: 96 DATE ENTR: 040296 LAST ACT: N DATE: 041396

PF3:RETURN

003541

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A72130 ORIG WR: A71590 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 293330 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: ENCAPSULATE ACM AT N.T.F.
BLD/UNT: NTF AR: WK TP: 8 WANTED: 042696 RECNO: PROP NO:
REQ BY: R. CARTER C&P: WRITTEN: 032796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 042996 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 210 90

JOB DETAILS: PLEASE SEAL\ENCAPSULATE ACM ON 2" LINE WHERE INSULATION
WILL BE TIED IN AT N.T.F. ON ACETIC ACID LINE SEE RICKY
OR JOE FOR LOCATION THANKS!!! 2473\5-209

YTD TOTAL HRS: 9 YTD O/T: 0 YTD LAB\$: 260 YTD MAT\$: 499
IND: I CL YR: 96 DATE ENTR: 032796 LAST ACT: N DATE: 052496

PF3:RETURN

003542

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A72128 ORIG WR: A71871 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: SAMPLE MASTIC AND INSULATION
BLD/UNT: SALV AR: WK TP: 8 WANTED: 043096 RECNO: PROP NO:
REQ BY: R. CARTER C&P: WRITTEN: 032796 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 042496 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 390 00

JOB DETAILS: PLEASE SAMPLE MASTIC AND INSULATION AND IF NEEDED REMOVE
FROM COMP. BOTTLES OLEFINS 2 EQUIPMENT SEE JOE OR RICKY
FOR LOCATION

5-209\5-173\2473

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 665
IND: I CL YR: 96 DATE ENTR: 032796 LAST ACT: N DATE: 071796

PF3:RETURN

003543

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A71839 ORIG WR: A63873 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 127200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: SAMPLE LINES FOR (ACM) OXIDE
BLD/UNT: REA AR: OX WK TP: 4 WANTED: 041996 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 032196 HWP: MTAG: SLIPBL:
SERV: R-19 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 041796 APPROVED BY: BATES
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 50

JOB DETAILS: PLEASE SAMPLE AND MARK THE LINES ON THE B1, B2 & B3 TETRALIN SYS.
FOR POSSIBLE ASBESTOS CONTAINING MATERIALS.

DEL PHONE 2617
YTD TOTAL HRS: 5 YTD O/T: 0 YTD LAB\$: 144 YTD MAT\$: 3184
IND: I CL YR: 96 DATE ENTR: 032196 LAST ACT: N DATE: 052396

PF3:RETURN

003544

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A70976 ORIG WR: A67830 PROCESS ID: NONE
DIV/LOC: 500510 ACCOUNT: 291740 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 08 WCAT: RW CD: RW RS: DESC: SAMPLE FOR ASBESTOS N/F
BLD/UNT: DIST. AR: WK TP: 8 WANTED: 042996 RECNO: 064449 PROP NO:
REQ BY: V.SPRAGUE C&P: WRITTEN: 030696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 041496 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1850 2090

JOB DETAILS: PLEASE SAMPLE THE PIPING PER SIMONS DIRECTIONS FOR ASBESTOS
IF IT IS ASBESTOS KEEP THIS S/O OPEN TO REMOVE AREAS AT THE SAME
LOCATIONS AS SAMPLES ARE TAKEN. WE WILL MOVE BACK THE DUE DATE IF
YOU HAVE TO CUT. THANKS VIVIAN X-3479 5-514

DEL PHONE
YTD TOTAL HRS: 209 YTD O/T: 6 YTD LAB\$: 6050 YTD MAT\$: 1654
IND: I CL YR: 96 DATE ENTR: 030796 LAST ACT: N DATE: 041696

PF3:RETURN

003545

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A64061 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 880000 INDX: 80 1ST ORDER: 00004830 2ND ORD: 00101
PR: 3 OR: MM WCAT: SC RW CD: RW RS: DESC: REMOVE ASBES. GASKETS AT OL-1
BLD/UNT: MMD AR: MM WK TP: 8 WANTED: 032996 RECNO: PROP NO:
REQ BY: S.WIEST C&P: WRITTEN: 111395 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 040996 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1730 1300

JOB DETAILS: REMOVE ASBESTOS GASKETS ON 12 HEATERS LOCATED ON THE SOUTH SIDE
OF # 1 GAS SEE SAM WIEST FOR LOCATION IF NECESSARY.

YTD TOTAL HRS: 96 YTD O/T: 0 YTD LAB\$: 2772 YTD MAT\$: 165
IND: J CL YR: 95 DATE ENTR: 111395 LAST ACT: N DATE: 041096

PF3:RETURN

003546

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A72303 ORIG WR: A72064 PROCESS ID: STEAM PIPE
DIV/LOC: 500510 ACCOUNT: 148370 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 83 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTO GASKETS G1750
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 032996 RECNO: PROP NO:
REQ BY: D. MAREK C&P: WRITTEN: 032996 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 03 29 96
DATE COMPLETE: 033096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 120 125

JOB DETAILS: REMOVE ASBESTO GASKETS FRON STEAM PIPING

DEL 341N PHONE 2396
YTD TOTAL HRS: 12 YTD O/T: 0 YTD LAB\$: 361 YTD MAT\$: 131
IND: I CL YR: 96 DATE ENTR: 032996 LAST ACT: N DATE: 060696

PF3:RETURN

003547

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A72282 ORIG WR: PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 355080 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: WCAT: RP RW CD: RW RS: DESC: REMOVE ASBESTOS
BLD/UNT: BLD2 AR: WK TP: 8 WANTED: 032996 RECNO: PROP NO:
REQ BY: S.FIGUEROA C&P: WRITTEN: 032996 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 033096 APPROVED BY: ADD
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 90 120

JOB DETAILS: REMOVE ASBESTOS FROM STEAM FOR REPAIR WORK AND REINSULATE
AFTER WORK IS DONE.

DEL PHONE 2348
YTD TOTAL HRS: 12 YTD O/T: 0 YTD LAB\$: 346 YTD MAT\$: 305
IND: J CL YR: 96 DATE ENTR: 032996 LAST ACT: N DATE: 052196

PF3:RETURN

003548

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A71811 ORIG WR: A69994 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 008510 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 10 WCAT: RW CD: RW RS: DESC: SAMPLE INSULATION AT O2 UNIT
BLD/UNT: ASU AR: ES WK TP: 8 WANTED: 040496 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 032096 HWP: MTAG: SLIPBL:
SERV: 02-027 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 032796 APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 80 40

JOB DETAILS: PLEASE SAMPLE THE INSULATION MATERIALS ON THE N2 COMPRESSOR FOR
POSSIBLE (ACM) THANK YOU. SEE BOSCO FOR DETAILS AND LOCATIONS.

DEL PHONE 2617
YTD TOTAL HRS: 4 YTD O/T: 0 YTD LAB\$: 115 YTD MAT\$: 163
IND: I CL YR: 96 DATE ENTR: 032096 LAST ACT: N DATE: 052996

PF3:RETURN

003549

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A71538 ORIG WR: A71530 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148370 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 83 WCAT: SE RW CD: RW RS: DESC: G-1750 NITROGEN HEATER
BLD/UNT: L1R AR: L1 WK TP: 8 WANTED: 031596 RECNO: PROP NO:
REQ BY: V. SHRADER C&P: WRITTEN: 031596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 032096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 90

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS FROM TUBE SHEET, HEAD, AND HEATER SHELL

YTD TOTAL HRS: 9 YTD O/T: 9 YTD LAB\$: 287 YTD MAT\$: 279
IND: I CL YR: 96 DATE ENTR: 031596 LAST ACT: N DATE: 040296

PF3:RETURN

003550

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A71508 ORIG WR: A64790 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 333010 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 44 WCAT: SA RW CD: RW RS: DESC: ASBESTOS REMOVAL BLDG 13
BLD/UNT: BLD13 AR: GF WK TP: 8 WANTED: 031496 RECNO: PROP NO:
REQ BY: R. MAREK C&P: WRITTEN: 031496 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 032096 APPROVED BY: RNT
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 380 390

JOB DETAILS: PLEASE CLEAN ASBESTOS AROUND BLDG 13

YTD TOTAL HRS: 39 YTD O/T: 30 YTD LAB\$: 1216 YTD MAT\$: 667
IND: I CL YR: 96 DATE ENTR: 031496 LAST ACT: N DATE: 041296

PF3:RETURN

003551

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A70163 ORIG WR: 135115 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: ENCAPSULATE ASB INSUL ON FLNGS
BLD/UNT: BUTYL AR: CH WK TP: 8 WANTED: 032996 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 022396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 033096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 310 170

JOB DETAILS: SEVERAL FLANGES/ELL HAVE LOOSE ASBESTOS INSULATION. PLEASE SEAL OR
REPLACE. LOCATED ON 200# STEAM SUPPLY BATTERY LIMIT. SEE RED VOIGT
FOR EXACT LOCATION 5-733. THNX, ANN T. 5-401

DEL PHONE
YTD TOTAL HRS: 17 YTD O/T: 0 YTD LAB\$: 491 YTD MAT\$: 204
IND: J CL YR: 96 DATE ENTR: 022396 LAST ACT: N DATE: 040296

PF3:RETURN

003552

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A69603 ORIG WR: 147610 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 127300 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 85 WCAT: SA RW CD: RW RS: DESC: ASBESTOS MASTIC
BLD/UNT: REC AR: OX WK TP: 8 WANTED: 031596 RECNO: PROP NO:
REQ BY: MARTINEZ C&P: WRITTEN: 021396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 030596 APPROVED BY: BATES
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 240 00

JOB DETAILS: RVGC SUCTION PIPING HAS RIPPED INSULATION, PLEASE REMOVE
OR REPAIR INSULATION, SEE MARTY FOR LOCATION. 2253/5345.

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 110
IND: J CL YR: 96 DATE ENTR: 021396 LAST ACT: N DATE: 031696

PF3:RETURN

003553

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 9 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK	REQ	P	T	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
						T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
					<== SORT SELECTION LINE ==>								
	A68341		*J		G-1750 SOUR OIL POT/LINE INSUL	X	M0	8	2	SE	012596	031796	031596
	A58377		I		ENCAPSULATE ASBESTOS MATERIAL	X	M0	8	3		081695	053196	040196
	A57941		J		INSPECT B-100 MECH.ROOM HP-1	X	M0	8	3		080995	032296	031896
	A69451		I		REMOVE ASBESTOS #3 EXTRUDER	X	M0	8	1		021096	021096	021696
	A69341		J		SCRAPE GLUE OFF TOP TANK 601	X	M0	8	1	RP	020896	020896	022096
	A68878		I		REMOVE ASBESTOS INSULATION	X	M0	8	1		020296	020296	021196
	A68655		I		SEAL INSULATION OL-2 (SEP.)	X	M0	8	1		013096	013096	021196
	A68646		J		REMOVE ASBESTOS INSULATION	X	M0	8	2	SE	013096	021696	022096
	A65718		I		ASBESTOS INSUL. AT BOILER 22	X	M0	4	2		121395	022996	022896
	A57954		J		CHECK XYLENE RM.AT B-100 HP-1	X	M0	8	3		080995	022396	021096
	A68450		J		REMOVE INSULATION CO2 TURBINE	X	M0	8	3	US	012996	012996	012996
	A68350		I		REMOVE ASBES.INSUL.AT OL-2	X	M0	8	3		011196	013196	012996
	A67723		I		REMOVE ASBESTOS GASKET	X	M0	8	3		011696	013196	012596
	A67625		J		REMOVE ARC CHUTES	X	M0	8	3	EP	011696	013196	012596

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003554

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A68341 ORIG WR: 154514 PROCESS ID: G-1750 INSUL.
DIV/LOC: 500510 ACCOUNT: 148340 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 83 WCAT: SE RW CD: RW RS: DESC: G-1750 SOUR OIL POT/LINE INSUL
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 031796 RECNO: PROP NO:
REQ BY: DONNIE M. C&P: WRITTEN: 012596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 01 25 96
DATE COMPLETE: 031596 APPROVED BY: TOM T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 680 80

JOB DETAILS: REMOVE INSULATION PRIOR TO S/D, SOME OF THE INSULATION IS OR LOOKS
LIKE ASBESTOS.REINSULATE LINE BEFORE SCAFFOLD IS REMOVED.HAVE
SCAFFOLD BUILT AS NECESSARY.
SEE DONNIE MAREK FOR LOCATION OF INSULATION.

DEL B-343 PHONE 2396
YTD TOTAL HRS: 8 YTD O/T: 0 YTD LAB\$: 231 YTD MAT\$: 576
IND: J CL YR: 96 DATE ENTR: 012596 LAST ACT: N DATE: 033096

PF3:RETURN

003555

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58377 ORIG WR: A57290 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M6 WCAT: RW CD: RW RS: DESC: ENCAPSULATE ASBESTOS MATERIAL
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 053196 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 081695 HWP: MTAG: SLIPBL:
SERV: STEAM LINES DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 09 18 95
DATE COMPLETE: 040196 APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 950 920 00 00 95

JOB DETAILS: PLEASE ENCAPSULATE OR REMOVE ASBESTOS MATERIAL LOCATED IN THE WEST
PIPE RACK. SEE BOSCO FOR LOCATIONS, SOME SAFETY PRECAUTION WILL BE
NEEDED BEFORE WORK CAN BEING. CALL ME AT 2617 OR 5-608 THANK YOU :

DEL PHONE
YTD TOTAL HRS: 101 YTD O/T: 0 YTD LAB\$: 2892 YTD MAT\$: 563
IND: I CL YR: 95 DATE ENTR: 081695 LAST ACT: C DATE: 052496

PF3:RETURN

003556

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57941 ORIG WR: 367000 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 355090 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: INSPECT B-100 MECH.ROOM HP-1
BLD/UNT: 100 AR: H1 WK TP: 8 WANTED: 032296 RECNO: PROP NO:
REQ BY: W GIPSON C&P: WRITTEN: 080995 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 031896 APPROVED BY: WGG
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 240 120

JOB DETAILS: INSTALL SIGN FOR THE PRESENCE OF ASBESTOS IN ROOM 110. ALSO,
PERFORM VERIFICATION OF ASBESTOS REMOVAL FROM ROOM 110.
ATTN: FRED BERGER

YTD TOTAL HRS: 12 YTD O/T: 0 YTD LABS: 346 YTD MATS: 279
IND: J CL YR: 95 DATE ENTR: 080995 LAST ACT: N DATE: 040296

PF3:RETURN

003557

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A69451 ORIG WR: A66723 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS #3 EXTRUDER
BLD/UNT: LPPE1 AR: L1 WK TP: 8 WANTED: 021096 RECNO: PROP NO:
REQ BY: J.BURNS C&P: WRITTEN: 021096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER: PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 021696 APPROVED BY: FRO G.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: PLEASE REMOVE POSSIBLE ASBESTOS FROM STM.PIPING NEXT TO THE
#3 EXTRUDER.SEE OPERATIONS FOR LOCATION.ALSO INSTALL TEMPORARY
INSUL.FOR PERSONAL PROTECTION.SEE FRO GONZALES FOR APPROVAL.

DEL PHONE 2276
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 203
IND: I CL YR: 96 DATE ENTR: 021296 LAST ACT: N DATE: 031296

PF3:RETURN

003558

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A69341 ORIG WR: 290601 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 297020 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 89 WCAT: RP RW CD: RW RS: DESC: SCRAPE GLUE OFF TOP TANK 601
BLD/UNT: DOCSK AR: DI WK TP: 8 WANTED: 020896 RECNO: PROP NO:
REQ BY: N HANKE C&P: WRITTEN: 020896 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 022096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 950 00

JOB DETAILS: TO COVER COST OF REMOVING GLUE FROM TOP OF TANK 601. THIS GLUE HAS 1 % ASBESTOS IN IT AND WILL REQUIRE QUALIFIED PERSONAL TO REMOVE IT

DEL PHONE 5622
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 1221
IND: J CL YR: 96 DATE ENTR: 020896 LAST ACT: N DATE: 031596

PF3:RETURN

003559

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A68878 ORIG WR: A68341 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148340 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNT: LPPE1 AR: WK TP: 8 WANTED: 020296 RECNO: PROP NO:
REQ BY: D.MAREK C&P: WRITTEN: 020296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 021196 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 490 00

JOB DETAILS: PLEASE REMOVE POSSIBLE ASBESTOS FROM SOUR OIL POT LINE AT
THE G-1750 REACTOR.SEE DONNIE MAREK FOR LOCATION.REPAIRS
FOR FREEZE PROTECTION.

DEL PHONE 2832
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 522
IND: I CL YR: 96 DATE ENTR: 020296 LAST ACT: N DATE: 032896

PF3:RETURN

003560

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A68655 ORIG WR: A47976 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: WCAT: RW CD: RW RS: DESC: SEAL INSULATION OL-2 (SEP.)
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 013096 RECNO: PROP NO:
REQ BY: A.URESTE C&P: WRITTEN: 013096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 021196 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 670 00

JOB DETAILS: PLEASE ENCAPSULATE POSSIBLE ASBESTOS INSUL.IN OL-2 SEPERATIONS
AREA.THANK YOU.

DEL PHONE 2982
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LABS: 0 YTD MAT\$: 305
IND: I CL YR: 96 DATE ENTR: 013096 LAST ACT: N DATE: 021796

PF3:RETURN

003561

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A68646 ORIG WR: PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 22 WCAT: SE RW CD: OT RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 021696 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 013096 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 022096 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 290 00 00 00 30

JOB DETAILS: PLEASE REMOVE ASBESTOS INSULATION TO ASSIST IN LOCATING LEAK ON
LP CONDENSATE HEADER. NEED TO HAVE REPAIRS MADE NEXT WEEK & NEED
TO HAVE DE-INSULATED SO MATERIALS CAN BE ORDERED.
THNX, ANN T. 5-401

YTD TOTAL HRS: 3 YTD O/T: 0 YTD LAB\$: 75 YTD MAT\$: 226
IND: J CL YR: 96 DATE ENTR: 013096 LAST ACT: N DATE: 040396

PF3:RETURN

003562

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A65718 ORIG WR: A64754 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 004320 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: ASBESTOS INSUL. AT BOILER 22
BLD/UNT: ENSYS AR: ES WK TP: 4 WANTED: 022996 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 121395 HWP: MTAG: SLIPBL:
SERV: #22-008 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 02 19 96
DATE COMPLETE: 022896 APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 780 170

JOB DETAILS: PLEASE REMOVE THE ASBESTOS CONTAINING MATERIALS FROM THE HOT WATER
PIPING. SEE BOSCO FOR LOCATIONS. ALSO USE THIS CHARGE FOR ANY
ENCAPSULATION DONE TURNING THE FEB. T/A.

DEL PHONE 2617
YTD TOTAL HRS: 12 YTD O/T: 0 YTD LAB\$: 346 YTD MAT\$: 182
IND: I CL YR: 95 DATE ENTR: 121395 LAST ACT: N DATE: 051196

PF3:RETURN

003563

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57954 ORIG WR: 367000 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 355090 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: CHECK XYLENE RM.AT B-100 HP-1
BLD/UNT: 100 AR: H1 WK TP: 8 WANTED: 022396 RECNO: PROP NO:
REQ BY: W GIPSON C&P: WRITTEN: 080995 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 021096 APPROVED BY: WGG
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 370 00

JOB DETAILS: CHECK FOR THE PRESENCE OF ASBESTOS IN XYLENE TESTING ROOM
ON THE HOT WATER LINE.REMOVE INSUL.& CUT PIPE AS PER JIMMY
NIX 020596.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 258
IND: J CL YR: 95 DATE ENTR: 080995 LAST ACT: N DATE: 021796

PF3:RETURN

003564

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A68450 ORIG WR: 119919 PROCESS ID: E-008
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: US RW CD: RW RS: DESC: REMOVE INSULATION CO2 TURBINE
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 012996 RECNO: 004199 PROP NO: 610800046
REQ BY: WILLIAMS C&P: WRITTEN: 012996 HWP: MTAG: SLIPBL:
SERV: 200# STEAM DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 01 26 96
DATE COMPLETE: 012996 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: REMOVE INSULATION FROM CO2 STILL'S REFLUX STEAM TURBINE
SO IT CAN BE PULLED AND SENT TO REPAIR SHOP. MAY BE
ASBESTOS.

DEL PHONE 2965
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 197
IND: J CL YR: 96 DATE ENTR: 012696 LAST ACT: N DATE: 021396

PF3:RETURN

003565

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A68350 ORIG WR: A67877 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: REMOVE ASBES.INSUL.AT OL-2
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 013196 RECNO: PROP NO:
REQ BY: A.VASQUEZ C&P: WRITTEN: 011196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 012996 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 390 00

JOB DETAILS: PLEASE REMOVE ASBESTOS FROM E-LINE HEATER PIPING.R.CARTER
KNOWS LOCATION.PAGE 5-983 FOR ANY QUESTIONS.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 42
IND: I CL YR: 96 DATE ENTR: 012596 LAST ACT: N DATE: 022996
DEL PHONE 5983

PF3:RETURN

003566

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A67723 ORIG WR: A67017 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M7 WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET
BLD/UNT: 165 AR: WK TP: 8 WANTED: 013196 RECNO: PROP NO:
REQ BY: G.LANE C&P: WRITTEN: 011696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 012596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 180 00

JOB DETAILS: REMOVE ASBESTOS GASKET FROM VENT STACK.
THANKS FOR THE HELP GARY.

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 41
IND: I CL YR: 96 DATE ENTR: 011796 LAST ACT: N DATE: 022996

PF3:RETURN

003567

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A67625 ORIG WR: 108700 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 007350 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 03 WCAT: EP RW CD: RW RS: DESC: REMOVE ARC CHUTES
BLD/UNT: 163 AR: ES WK TP: 8 WANTED: 013196 RECNO: PROP NO:
REQ BY: G BELK C&P: WRITTEN: 011696 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 012596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 180 00

JOB DETAILS: PLEASE DISPOSE OF ASBESTOS LADEN ARC CHUTES WHICH
ARE LOCATED ON A PALLET ON THE NORTH END OF THE
CARBIDE ELECTRIC SHOP

THANKS GERROLD

DEL

PHONE 2606

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 96
IND: J CL YR: 96 DATE ENTR: 011696 LAST ACT: N DATE: 022996

PF3:RETURN

003568

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 10 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK	REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
						T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
					<== SORT SELECTION LINE ==>								
	A67537	J			SEAL OR REMOVE ASBESTOS INSUL	X	M0	8	3	SE	011596	012296	012296
	A67311	I			REMOVE INSULATION F/REPAIRS	X	M0	8	3	SC	011196	013196	012996
	A67302	J			REMOVE ASBESTOS AT OL-2 TRAY	X	M0	8	1	US	012296	012296	012996
	A66634	I			REMOVE ASBESTOS GASKETS	X	M0	8	2	SE	010396	010396	010596
	J70692	J			REMOVE GASKETS OL 2 TANK	X	M0	8	4		121395	013196	012596
	A63715	J			ASBESTOS SAMPLING ACE PIPING	X	M0	8	3	SE	110795	013196	012496
	A60303	J			REMOVE ASBESTOS AT LP-1 RXN.	X	M0	8	3	SE	091495	123195	010396
	A57733	J			ASBESTOS INSPECTION BLDG.2	X	M0	8	3	CT	080795	011596	011396
	A65594	J			REMOVE ASBESTOS GASKET.	X	M0	8	1	US	121195	121195	121395
	A65359	I			REMOVE ASBESTOS GASKET	X	M0	8	3	SE	120795	121395	121395
	A65247	I			BARREL ZONES	X	M0	8	3	RP	120695	121895	121395
	J70691	J			REMOVE ASBESTOS SEALANT	X	M0	8	3		113095	122295	122295
	A64786	I			REMOVE ASBESTOS WRAPPING	X	M0	8	2		112895	113095	120695
	J61914	J			ASBESTOS REMOVAL	X	M0	8	3		112795	122495	122295

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003569

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A67537 ORIG WR: PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: SEAL OR REMOVE ASBESTOS INSUL
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 012296 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 011596 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 012296 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: ASBESTOS INSULATION NEEDS TO BE EITHER REMOVED OR ENCAPSULATED.
LOCATED ON 2ND LEVEL AT GEU ON NORTH END ON EAST SIDE.

THNX, ANN T.

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 237
IND: J CL YR: 95 DATE ENTR: 011596 LAST ACT: N DATE: 022996

PF3:RETURN

003570

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A67311 ORIG WR: A66557 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 342320 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 31 WCAT: SC RW CD: RW RS: DESC: REMOVE INSULATION F/REPAIRS
BLD/UNT: MMD AR: MM WK TP: 8 WANTED: 013196 RECNO: PROP NO:
REQ BY: A.VASQUEZ C&P: WRITTEN: 011196 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 012996 APPROVED BY: GOHLKE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 490 00

JOB DETAILS: PRIOR TO REMOVING INSULATION PLEASE HAVE GARY KLASSEN CHECK
INSULATION FOR ASBESTOS, SAMPLE IF NECESSARY. THANKS ANDREW
5-983 THIS JOB IS ABOVE THE OFFICES AT STORES. CONTACT ANDREW
WHEN ALL THE ABOVE IS COMPLETE SO REPAIRS CAN BE COMPLETED.

DEL PHONE 5983
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 158
IND: I CL YR: 96 DATE ENTR: 011296 LAST ACT: N DATE: 022396

PF3:RETURN

003571

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A67302 ORIG WR: 119997 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 82 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS AT OL-2 TRAY
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 012296 RECNO: PROP NO:
REQ BY: A.URESTE C&P: WRITTEN: 012296 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 012996 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 640 00

JOB DETAILS: REMOVE ASBESTOS LOCATED NORTH OF BLDG 503 IN PIPERACK ON
CABLETRAY.

DEL PHONE 2965
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 188
IND: J CL YR: 96 DATE ENTR: 011296 LAST ACT: N DATE: 022996

PF3:RETURN

003572

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A66634 ORIG WR: A64731 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 09 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 010396 RECNO: PROP NO:
REQ BY: OSCAR LEAL C&P: WRITTEN: 010396 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 01 03 96
DATE COMPLETE: 010596 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 140 00

JOB DETAILS: ATTENTION GARY CLASSEN: PLEASE STRIP ASBESTOS GASKETS FOR OSCAR
LEAL TO ALLOW PUMP INSTALLATION. CALL J. RAMIREZ AT 5-801 FOR
FURTHER INFO. THANKYOU.

DEL PHONE 3589
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 189
IND: I CL YR: 96 DATE ENTR: 010396 LAST ACT: N DATE: 022996

PF3:RETURN

003573

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J70692 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 838000 INDX: 92 1ST ORDER: 00006118 2ND ORD: 05900
PR: 4 OR: WCAT: RW CD: RW RS: DESC: REMOVE GASKETS OL 2 TANK
BLD/UNT: AR: WK TP: 8 WANTED: 013196 RECNO: PROP NO:
REQ BY: CORONADO C&P: WRITTEN: 121395 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 012596 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: REMOVE ASBESTOS GASKETS FROM DIRTY OIL TANK PIPING.

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 121395 LAST ACT: N DATE: 012696

PF3:RETURN

003574

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63715 ORIG WR: 138514 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071300 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: ASBESTOS SAMPLING ACE PIPING
BLD/UNT: ACE AR: CH WK TP: 8 WANTED: 013196 RECNO: 064377 PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 110795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 012496 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 70

JOB DETAILS: CHARGE LINE TO/FROM TANKS 3713/3715 MAY HAVE ASBESTOS IN SEVERAL
AREAS. SIMON HAS MARKED LOCATION ON DRAWINGS. WE NEED SAMPLING DONE
TO VERIFY BEFORE WE MAKE ANY DECISION ON HOW WE WILL APPROACH THIS
SEE ANN FOR MARKED DRAWINGS. THNX, ANN T. 5-401

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 40
IND: J CL YR: 95 DATE ENTR: 110795 LAST ACT: N DATE: 022996

PF3:RETURN

003575

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A60303 ORIG WR: 153912 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148250 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 83 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS AT LP-1 RXN.
BLD/UNT: LP1R AR: L1 WK TP: 8 WANTED: 123195 RECNO: PROP NO:
REQ BY: BOEHM C&P: WRITTEN: 091495 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 010396 APPROVED BY: T.T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1510 945

JOB DETAILS: REMOVE ASBESTOS FROM JUNCTION BOXES & CONDUIT LINES IN PIPERACK
EAST OF THE REACTION CONTROL RM.GARY K.KNOWS LOCATION.

DEL 343 PHONE 2832
YTD TOTAL HRS: 94 YTD O/T: 0 YTD LAB\$: 2651 YTD MAT\$: 221
IND: J CL YR: 95 DATE ENTR: 091495 LAST ACT: N DATE: 010496

PF3:RETURN

003576

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57733 ORIG WR: 366873 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 355080 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: TE WCAT: CT RW CD: RW RS: DESC: ASBESTOS INSPECTION BLDG.2
BLD/UNT: BLD2 AR: LA WK TP: 8 WANTED: 011596 RECNO: PROP NO:
REQ BY: T ESCOBEDO C&P: WRITTEN: 080795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 011396 APPROVED BY: ADD
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 420 210

JOB DETAILS: ATTN FRED BERGER

PLEASE POST ASBESTOS SIGN ON DOOR TO ROOM 105 AND ON DOOR TO PENT-
HOUSE PER OSHA REGULATIONS.

ALSO PERFORM THE VERIFICATION STEP.

DEL

PHONE 2544

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 178
IND: J CL YR: 95 DATE ENTR: 080795 LAST ACT: N DATE: 012596

PF3:RETURN

003577

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A65594 ORIG WR: 125713 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 039020 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 16 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET.
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 121195 RECNO: PROP NO:
REQ BY: W. CARLOCK C&P: WRITTEN: 121195 HWP: MTAG: SLIPBL:
SERV: C2CH4 LINE DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 12 11 95
DATE COMPLETE: 121195 APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 25

JOB DETAILS: PLEASE REMOVE A ASBESTOS GASKET FROM A 6" FLANGE FOR ROBERT
GOSSETT AT CONFUSION CORNER. IT IS IN THE PIPE RACK. WILL
REQUIRE OVERTIME TO DO IT TODAY WHILE OXIDE IS DOWN.

THANKS BB DEL COGEN PHONE 2592
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 263
IND: J CL YR: 96 DATE ENTR: 121195 LAST ACT: N DATE: 013096

PF3:RETURN

003578

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A65359 ORIG WR: A65126 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148750 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 31 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET
BLD/UNT: LP2 AR: L2 WK TP: 8 WANTED: 121395 RECNO: PROP NO:
REQ BY: CONTRERAS C&P: WRITTEN: 120795 HWP: MTAG: SLIPBL:
SERV: BARREL ZONES DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 121395 APPROVED BY: DWJ(JC)
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 300 00

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS FROM TWO MIXER / EXTRUDER BARREL
ZONES REMOVED FROM P1 MIXER / EXTRUDER IN LP2. BARREL ZONES ARE
LOCATED ON PAD SOUTHEAST OF PROCESS SAFETY SHOP. CALL OR PAGE
WHEN COMPLETE. JOE CONTRERAS 5-221

DEL CALL OR PAGE PHONE 3009
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 120795 LAST ACT: N DATE: 122895

PF3:RETURN

003579

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A65247 ORIG WR: A65126 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148750 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 09 WCAT: RP RW CD: RW RS: DESC: BARREL ZONES
BLD/UNT: LP2 AR: WK TP: 8 WANTED: 121895 RECNO: PROP NO:
REQ BY: A.RIVERA C&P: WRITTEN: 120695 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 121395 APPROVED BY: TS{AR}
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 40

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKET FROM BARREL ZONES, LOCATE SOUTH
CF BUILDING 140 ON CONCRETE PAD.

YTD TOTAL HRS: 0 YTD O/T: 0 DEL YTD LAB\$: 0 PHONE
IND: I CL YR: 95 DATE ENTR: 120695 LAST ACT: N DATE: 121595 YTD MAT\$: 0

PF3:RETURN

003580

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J70691 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 838000 INDX: 92 1ST ORDER: 00006110 2ND ORD: 07300
PR: 3 OR: WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS SEALANT
BLD/UNT: HP2 AR: WK TP: 8 WANTED: 122295 RECNO: PROP NO:
REQ BY: CORONADO C&P: WRITTEN: 113095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 122295 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 650 265

JOB DETAILS: TO REMOVE ASBESTOS SEALANT ABOVE PELLET SEPARATOR ROOM.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 2
IND: J CL YR: 95 DATE ENTR: 113095 LAST ACT: N DATE: 011996

PF3:RETURN

003581

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A64786 ORIG WR: A63123 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS WRAPPING
BLD/UNT: OL2 AR: OL WK TP: 8 WANTED: 113095 RECNO: PROP NO:
REQ BY: R.FLORES C&P: WRITTEN: 112895 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 120695 APPROVED BY: URESTI
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 410 180

JOB DETAILS: PLEASE REMOVE ASBESTOS WRAPPING FROM INST.TUBING IN SEPERATIONS
AND REPLACE WITH NEW WRAPPING FOR FREEZE PROTECTION.

DEL PHONE 2982
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 2
IND: I CL YR: 95 DATE ENTR: 112895 LAST ACT: N DATE: 011296

PF3:RETURN

003582

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J61914 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006408 2ND ORD: 73000
PR: 3 OR: 99 WCAT: RW CD: RW RS: DESC: ASBESTOS REMOVAL
BLD/UNT: HP2 AR: WK TP: 8 WANTED: 122495 RECNO: PROP NO:
REQ BY: P BETHANY C&P: WRITTEN: 112795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: MC PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 122295 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 1620 1455

JOB DETAILS: REMOVE FLOOR TILE WITH ASBESTOS FROM INTEC 400 ROOM IN BLDG. 561.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 18
IND: J CL YR: 95 DATE ENTR: 112795 LAST ACT: N DATE: 011296

PF3:RETURN

003583

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 11 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
					T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
	FP			<== SORT SELECTION LINE ==>								

A62789	I			STRIP TUBING/PIPING AS NEEDED	X	M0	8	3	SE	102495	122895	121895
A64682	I			REMOVE ASBESTOS INSULATION #9	X	M0	8	2	SD	112295	113095	112895
A64472	J			REMOVE ASBESTOS GASKETS	X	M0	8	1	US	112195	112195	112295
A64374	J			DE-INSULATE LINE	X	M0	8	1	US	112095	112095	112195
A64208	J			ASBES.REMOVAL ON CSAC AT ODU	X	M0	4	2	SD	111595	111695	112295
A63711	J			ASBESTOS SERVICES PER LIST	X	M0	8	3	SE	110795	112195	111395
A63704	I			ENCAPSULATE ACM,NEAR VENTSAC	X	M0	4	2		110795	111395	111395
A63676	J			REMOVE ASBESTOS INSUL-STM TRCN	X	M0	8	1	SE	110695	111105	110995
A63483	J			REMOVE ASBESTOS BLDG 1	X	M0	8	3	SC	110395	113095	111595
A63294	I			REMOVE ASBESTOS GASKETS (GEU)	X	M0	8	3		110195	110895	110995
A62987	J			INSULATION SAMPLES	X	M0	8	3	SE	102695	112795	111395
A62846	I			REMOVE INSUL.IN CABLE PIT	X	M0		3		102495	112795	112895
A62708	I			CHECK FOR ASBESTOS ISOMER COL.	X	M0	8	3		102395	111095	110995
A62689	I			MANPOWER FOR CRIBBING	X	M0	4	2	TA	102395	112095	111395

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003584

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62789 ORIG WR: A62110 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 31 WCAT: SE RW CD: RW RS: DESC: STRIP TUBING/PIPING AS NEEDED
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 122895 RECNO: PROP NO:
REQ BY: C FANELLI C&P: WRITTEN: 102495 HWP: MTAG: SLIPBL:
SERV: FREEZE PROTECTI DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 121895 APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 850 580

JOB DETAILS: PLEASE STRIP TUBING AND HARD PIPING AT VARIOUS LOCATIONS FOR
TRACING PURPOSES AND DISSASSEMBLY. SOME TUBING HAS ASBESTOS WRAP.
JOB IS LOCATED AT #1 STEAM PLANT.

DEL PHONE 3589
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 102495 LAST ACT: C DATE: 121895

PF3:RETURN

003585

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A64682 ORIG WR: A64315 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 82 WCAT: SD RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION #9
BLD/UNT: OLCOM AR: OL WK TP: 8 WANTED: 113095 RECNO: PROP NO:
REQ BY: REYNA C&P: WRITTEN: 112295 HWP: MTAG: SLIPBL:
SERV: PROPANE DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 11 27 95
DATE COMPLETE: 112895 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 260

JOB DETAILS: REMOVE ASBESTOS INSULATION FROM #9 COMPRESSOR 50# SUCTION
HEADER TO 2ND STG SUCTION BOTTLE.

DEL PHONE 2272
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 77
IND: I CL YR: 95 DATE ENTR: 112795 LAST ACT: N DATE: 011696

PF3:RETURN

003586

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A64472 ORIG WR: 119997 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 82 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 112195 RECNO: PROP NO:
REQ BY: WEST C&P: WRITTEN: 112195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 112295 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 100 60

JOB DETAILS: REMOVE ASBESTOS GASKETS FROM PSV'S AT T&I SHOP.

DEL PHONE 2982
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 112195 LAST ACT: N DATE: 120195

PF3:RETURN

003587

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A64374 ORIG WR: 123025 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 34 WCAT: US RW CD: RW RS: DESC: DE-INSULATE LINE
BLD/UNT: HPPE2 AR: H2 WK TP: 8 WANTED: 112095 RECNO: PROP NO:
REQ BY: BRUNNER C&P: WRITTEN: 112095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 112195 APPROVED BY: E.MEYER
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 210 40

JOB DETAILS: PLEASE PROVIDE INSULATERS TO DE-INSULATE #2 REACTOR POST PRODUCT
VALVE COOLING WATER PUMP. UNIT NOT SURE OF INSULATION TYPE.
NEED THIS DONE AS SOON AS POSSIBLE. THANK YOU.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 112095 LAST ACT: N DATE: 120595

PF3:RETURN

003588

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A64208 ORIG WR: 138514 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071300 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 22 WCAT: SD RW CD: RW RS: DESC: ASBES.REMOVAL ON CSAC AT ODU
BLD/UNT: ACE AR: CH WK TP: 4 WANTED: 111695 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 111595 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 112295 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 220 105

JOB DETAILS: NEED ASBESTOS REMOVAL ON CSAC COLUMN. WILL HAVE SCAFFOLD READY.
ERNEST HAS LOOKED AT THIS JOB. RUDY CAN HELP HIM WITH THIS.
THIS IS FOR A ONE DAY OUTAGE.
THNX, ANN T. 5-401

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 111595 LAST ACT: N DATE: 113095

PF3:RETURN

003589

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63711 ORIG WR: 135115 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071200 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: ASBESTOS SERVICES PER LIST
BLD/UNT: ODU AR: CH WK TP: 8 WANTED: 112195 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 110795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 111395 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 200

JOB DETAILS: PER LIST BY RUDY, WE HAVE SEVERAL INSULATION JOBS THAT EITHER HAVE
ASBESTOS OR WE SUSPECT IS ASBESTOS. STOP BY & SEE ANN OR RUDY FOR
LIST AND DETAILS.
THNX, ANN T. 5-401

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 2
IND: J CL YR: 95 DATE ENTR: 110795 LAST ACT: N DATE: 011296

PF3:RETURN

003590

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63704 ORIG WR: A61793 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: WCAT: RW CD: RW RS: DESC: ENCAPSULATE ACM, NEAR VENTSAC
BLD/UNT: HPPE2 AR: H2 WK TP: 4 WANTED: 111395 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 110795 HWP: MTAG: SLIPBL:
SERV: HP2-2-11 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: RB PLAN CD: RAM ASIS/ENGR: EST START: 11 10 95
DATE COMPLETE: 111395 APPROVED BY: E. MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 380 300

JOB DETAILS: PLEASE ENCAPSULATE ANY ASBESTOS CONTAINING MATERIAL AROUND THE #2
VENT STACK. THE AREA OF CONCERN IS ON THE INLET PELLETER. SEE
BOSCO FOR LOCATION IF NEEDED. THANK YOU

DEL PHONE 2617
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 110795 LAST ACT: N DATE: 120695

PF3: RETURN

003591

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63676 ORIG WR: 138815 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071420 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 22 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS INSUL-STM TRCN
BLD/UNT: SURF AR: CH WK TP: 8 WANTED: 111105 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 110695 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 11 07 95
DATE COMPLETE: 110995 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 240 80

JOB DETAILS: NEED ASBESTOS INSULATION REMOVED FROM STEAM TRACING/TUBING AT SURF
UNIT. SEE BILL WADE OR BOBBY BAREFIELD FOR LOCATION.
THNX, ANN T. 5-401

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 3
IND: J CL YR: 95 DATE ENTR: 110795 LAST ACT: N DATE: 011296

PF3:RETURN

003592

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63483 ORIG WR: 337112 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 333010 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 44 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS BLDG 1
BLD/UNT: BLDG1 AR: GF WK TP: 8 WANTED: 113095 RECNO: PROP NO:
REQ BY: R. MAREK C&P: WRITTEN: 110395 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 111595 APPROVED BY: RNT
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 165

JOB DETAILS: PLEASE REMOVE ASBESTOS INSULATION FROM LINE IN STORAGE ROOM BLDG 1

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 110395 LAST ACT: N DATE: 112995

PF3:RETURN

003593

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63294 ORIG WR: A62417 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 220010 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 31 WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS (GEU)
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 110895 RECNO: PROP NO:
REQ BY: J. RAMIREZ C&P: WRITTEN: 110195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 110995 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 240 320

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS OFF THE SPOOL AND VALVE ON THE
SOUTH SIDE OF GEU BLOCK. JUAN (5-801) WILL SHOW WHERE SPOOL AND
VALVE ARE LOCATED. THANKS.

DEL SOUTH SIDE (GEU) PHONE 3583
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 110195 LAST ACT: N DATE: 111795

PF3:RETURN

003594

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62987 ORIG WR: 135625 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 22 WCAT: SE RW CD: RW RS: DESC: INSULATION SAMPLES
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 112795 RECNO: PROP NO:
REQ BY: KRAUSE/AT C&P: WRITTEN: 102695 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 111395 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 170 200

JOB DETAILS: PER VERBAL ANN/GARY: TO COVER THE COST OF INSULATION SAMPLES TAKEN
AT GEU ON ALCOHOL COLUMN EACH CAN SECTION. VIVIAN HAS WRITTEN WOR
FOR SAMPLING DONE ON ISOMER COLUMN.
THNX, ANN T. 5-401

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 102695 LAST ACT: N DATE: 111795

PF3:RETURN

003595

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62846 ORIG WR: A61779 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 094760 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: M1 WCAT: RW CD: RW RS: DESC: REMOVE INSUL.IN CABLE PIT
BLD/UNT: ES AR: ES WK TP: WANTED: 112795 RECNO: PROP NO:
REQ BY: HOWELL C&P: WRITTEN: 102495 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 112895 APPROVED BY: JANAK
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 400 220

JOB DETAILS: REMOVE INSULATION ON CABLE IN CABLE PITS ON EXISTING CABLE
CONTACT ROBERT HOWELL FOR MORE INFORMATION.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 102495 LAST ACT: N DATE: 121395

PF3:RETURN

003596

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62708 ORIG WR: A61296 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: CHECK FOR ASBESTOS ISOMER COL.
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 111095 RECNO: PROP NO:
REQ BY: SPRAGUE C&P: WRITTEN: 102395 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 110995 APPROVED BY: DCB
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 180 140

JOB DETAILS: PLEASE CHECK FOR ASBESTOS ON ISOMER COLUMN PIPING.
THANKS VIVIAN

DEL PHONE 3479
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 102395 LAST ACT: N DATE: 112895

PF3:RETURN

003597

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62689 ORIG WR: A62579 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148750 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: TA RW CD: RW RS: DESC: MANPOWER FOR CRIBBING
BLD/UNT: LP-2 AR: L2 WK TP: 4 WANTED: 112095 RECNO: PROP NO:
REQ BY: S SANDERS C&P: WRITTEN: 102395 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 111395 APPROVED BY: DWJ
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 680 570

JOB DETAILS: PLEASE FURNISH MANPOWER TO CRIB UP ABOUT 4' HIGH X 7' TO EAST SIDE
OF LP2 P1 MIXER GEARBOX. ALSO NEED TO EXTEND CRIBBING TO NORTH OF
GEARBOX ABOUT 14' X 4' HIGH ALSO. FOR INFOR CALL MIKE ADKINS

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 102395 LAST ACT: N DATE: 111495

PF3:RETURN

003598

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 12 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK	REQ	P	T	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
						T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
					<== SORT SELECTION LINE ==>								
	A61847	J			REMOVE ASBESTOS INSULATION	X	M0	8	3	SC	101095	112095	110995
	A61390	J			CONDS DRAIN LINE ASBESTOS REMO	X	M0	8	3	SC	100295	111795	110795
	A63062	I			REMOVE (ACM) GASKETS FOR LP2	X	M0	4	2		102795	103095	103095
	A63055	J			REMOVE ASBESTOS FROM #4 PC	X	M0	8	3	SC	102795	110395	103095
	A63019	J			REMOVE ASBESTOS GASKET #6 COM	X	M0	8	1		102695	102695	103095
	A62717	I			STRIP ASBESTOS GSKT. (PFO)	X	M0	8	3		102395	103095	102595
	A62684	J			REMOVE INS. & MASTIC	X	M0	8	3	RA	102395	110695	103095
	A62627	J			REMOVE ASBESTOS INSULATION #4	X	M0	8	1		102095	102095	102395
	A62526	J			SILO 205 REPAIR	X	M0	8	1	SE	101995	103195	102795
	A62406	I			ASBESTOS GASKET COVERAGE	X	M0	4	2		101795	102095	102095
	A62397	J			REMOVE INSULATION	X	M0	8	1	SC	101795	102495	102395
	A61901	I			ENCAPSULATE SUSPECT ASBESTOS	X	M0	8	1	SD	101095	101095	101395
	A61868	J			PLEASE PROVIDE ASBESTOS REMOVA	X	M0	8	1	RP	101095	101095	101195
	A61327	I			REMOVE FILTER DUST	X	M0	4	2		092995	100395	100395

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003599

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A61847 ORIG WR: 113609 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009210 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 16 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNT: COGEN AR: ES WK TP: 8 WANTED: 112095 RECNO: PROP NO:
REQ BY: CARLOCK C&P: WRITTEN: 101095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 10 12 95
DATE COMPLETE: 110995 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 260 780

JOB DETAILS: REMOVE ASBESTOS INSULATION AT CONFUSION CORNER PIPE RACK
SO STEAM TRACING CAN BE RUN. CONTACT ROBERT GOSSETT FOR
DETAILS. (2963)

DEL PHONE 2592
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 101095 LAST ACT: N DATE: 111895

PF3:RETURN

003600

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A61390 ORIG WR: 119997 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: SC RW CD: RW RS: DESC: CONDS DRAIN LINE ASBESTOS REMO
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 111795 RECNO: PROP NO:
REQ BY: WARZECHA C&P: WRITTEN: 100295 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 110795 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 560 600

JOB DETAILS: REMOVE ASBESTOS FROM CONDENSATE LINE WEST OF EKL TANK AND
REINSULATE. CONTACT OPERATOR FOR LOCATION.

DEL PHONE 2442
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 100295 LAST ACT: N DATE: 111795

PF3:RETURN

003601

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63062 ORIG WR: A48584 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148750 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: M6 WCAT: RW CD: RW RS: DESC: REMOVE (ACM) GASKETS FOR LP2
BLD/UNT: LP2 AR: L2 WK TP: 4 WANTED: 103095 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 102795 HWP: MTAG: SLIPBL:
SERV: P1-024 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 10 29 95
DATE COMPLETE: 103095 APPROVED BY: DWJ
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 460 145

JOB DETAILS: PLEASE PROVIDE MANPOWER COVERAGE FOR ASBESTOS GASKET REMOVAL AS
NEEDED. ALSO INSULATION REMOVAL IF REQUIRED BY MAINTENANCE PERSON-
NEL. THANK YOU (TURNAROUND WORK) SEE BOSCO FOR DETAILS.

DEL PHONE 2617
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 102795 LAST ACT: N DATE: 112995

PF3:RETURN

003602

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63055 ORIG WR: 116414 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS FROM #4 PC
BLD/UNT: OLCOM AR: OL WK TP: 8 WANTED: 110395 RECNO: PROP NO:
REQ BY: YAKLIN C&P: WRITTEN: 102795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 103095 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 190 00

JOB DETAILS: REMOVE ASBESTOS GASKETS FROM #4 COMPRESSOR 1R POWER CYLINDER.
CYLINDER IS IN BLDG 500 BAY.

DEL PHONE 2965
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 102795 LAST ACT: N DATE: 120195

PF3:RETURN

003603

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A63019 ORIG WR: 116446 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 82 WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET #6 COM
BLD/UNT: OLCOM AR: OL WK TP: 8 WANTED: 102695 RECNO: PROP NO:
REQ BY: YAKLIN C&P: WRITTEN: 102695 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 103095 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 140

JOB DETAILS: REMOVE ASBESTOS GASKET FROM #6 COMPRESSOR POWER CYLINDER HEAD.

DEL PHONE 2965
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 102695 LAST ACT: N DATE: 120195

PF3:RETURN

003604

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62717 ORIG WR: A62445 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 039290 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 09 WCAT: RW CD: RW RS: DESC: STRIP ASBESTOS GSKT. (PFO)
BLD/UNT: OLPFO AR: OL WK TP: 8 WANTED: 103095 RECNO: PROP NO:
REQ BY: J. RAMIREZ C&P: WRITTEN: 102395 HWP: MTAG: SLIPBL:
SERV: OXIDE TAILS DWG ATTCH: SPECS: FAC CHG: Y RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 10 24 95
DATE COMPLETE: 102595 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 120

JOB DETAILS: PLEASE STRIP ASBESTOS GASKETS OFF THE 3" SPOOL AND THE GATE
VALVE. JUAN WILL SHOW WHERE THE SPOOL AND VALVE IS LOCATED. THANKS
JUAN 5-801.

DEL PFO UNIT PHONE 3583
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 102395 LAST ACT: N DATE: 110395

PF3:RETURN

003605

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62684 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 838000 INDX: 92 1ST ORDER: 00006120 2ND ORD: 05700
PR: 3 OR: TM WCAT: RA RW CD: RW RS: DESC: REMOVE INS. & MASTIC
BLD/UNT: BL543 AR: GS WK TP: 8 WANTED: 110695 RECNO: PROP NO:
REQ BY: T. MUNIZ C&P: WRITTEN: 102395 HWP: Y MTAG: N SLIPBL: N
SERV: DRINKING WATER DWG ATTCH: N SPECS: FAC CHG: N RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 103095 APPROVED BY: EISENMA
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 320 155

JOB DETAILS: REMOVE ASBESTOS AND MASTIC ON DRINKING WATER LINES INTO KITCHEN TO
FACILITATE BOTTLE PROJECT REARRANGEMENT OF BLOW MOLDING MACHINE.
CONTACT T. MUNIZ FOR FIELD INSTRUCTIONS.

DEL PHONE 2566
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 102395 LAST ACT: N DATE: 110495

PF3:RETURN

003606

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62627 ORIG WR: 116414 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 82 WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION #4
BLD/UNT: OLCOM AR: OL WK TP: 8 WANTED: 102095 RECNO: PROP NO:
REQ BY: YAKLIN C&P: WRITTEN: 102095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 102395 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 210 60

JOB DETAILS: REMOVE ASBESTOS INSULATION FROM #4 COMP POWER CYLINDER

DEL PHONE 2965
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 102095 LAST ACT: N DATE: 110495

PF3:RETURN

003607

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62526 ORIG WR: 154421 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148310 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 83 WCAT: SE RW CD: RW RS: DESC: SILO 205 REPAIR
BLD/UNT: LP1R AR: L1 WK TP: 8 WANTED: 103195 RECNO: PROP NO:
REQ BY: D. BOHEM C&P: WRITTEN: 101995 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 102795 APPROVED BY: T.T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 440 400

JOB DETAILS: PLEASE CHECK SILO 205 ON CONE SECTION FOR ASBESTOS IN SEAM CAULKIN
G

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 101995 LAST ACT: N DATE: 111895

PF3:RETURN

003608

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62406 ORIG WR: A57593 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: WCAT: RW CD: RW RS: DESC: ASBESTOS GASKET COVERAGE
BLD/UNT: HP-2 AR: WK TP: 4 WANTED: 102095 RECNO: PROP NO:
REQ BY: BOSCO C&P: WRITTEN: 101795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 102095 APPROVED BY: E.MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 400 220

JOB DETAILS: TO COVER THE COST OF ASBESTOS GASKET REMOVAL DURING THE HP-2
TURNAROUNDS.

DEL PHONE 2617
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 101795 LAST ACT: N DATE: 110395

PF3:RETURN

003609

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A62397 ORIG WR: 122971 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 34 WCAT: SC RW CD: RW RS: DESC: REMOVE INSULATION
BLD/UNT: HPPE2 AR: H2 WK TP: 8 WANTED: 102495 RECNO: PROP NO:
REQ BY: SELBY C&P: WRITTEN: 101795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 102395 APPROVED BY: E.MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 180 90

JOB DETAILS: PLEASE REMOVE INSULATION ON THE REACTION WATER PUMP.REPLACE WHEN P
UMP IS CHANGED OUT.

DEL 566 PHONE 3527
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 101795 LAST ACT: N DATE: 112995

PF3:RETURN

003610

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A61901 ORIG WR: A61872 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 22 WCAT: SD RW CD: RW RS: DESC: ENCAPSULATE SUSPECT ASBESTOS
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 101095 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 101095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101395 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 180 120

JOB DETAILS: PLEASE ENCAPSULATE SUSPECTED ASBESTOS INSULATION ON ARC COL.
THNX, ANN T. 5-401

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 101095 LAST ACT: N DATE: 112995

PF3:RETURN

003611

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A61868 ORIG WR: 152946 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 139900 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 75 WCAT: RP RW CD: RW RS: DESC: PLEASE PROVIDE ASBESTOS REMOVA
BLD/UNT: PPU AR: P1 WK TP: 8 WANTED: 101095 RECNO: PROP NO:
REQ BY: JIM NIX C&P: WRITTEN: 101095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101195 APPROVED BY: CHOV
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 180 100

JOB DETAILS: PLEASE PROVIDE AN ASBESTOS REMOVAL PERSON TO REMOVE A COUPLE OF
ASBESTOS GASKETS AT THE P1 PELLETER JIM NIX 3090 5-727

DEL 101 PHONE 2983
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 101095 LAST ACT: N DATE: 110395

PF3:RETURN

003612

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A61327 ORIG WR: A44638 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 333010 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: WCAT: RW CD: RW RS: DESC: REMOVE FILTER DUST
BLD/UNT: 163 S AR: WK TP: 4 WANTED: 100395 RECNO: PROP NO:
REQ BY: P TOMPKINS C&P: WRITTEN: 092995 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 100395 APPROVED BY: SUMMERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 300 120

JOB DETAILS: PLEASE REMOVE DUST FROM BULB CRUSHER AREA MONDAY. OCT. 0295.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 092995 LAST ACT: N DATE: 110395

PF3:RETURN

003613

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 13 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
FP					T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
				<== SORT SELECTION LINE ==>								
	A61260	I		REMOVE ASBESTOS GASKET,ON FLG	X	M0	8	2	US	092895	100795	101195
	A61160	I		REMOVE ASBESTOS GASKET	X	M0	4	2	RP	092795	101895	100395
	J62897	J		ASBESTOS TESTING	X	M0	8	3		092595	102095	101895
	A60774	J		TEST INSULATION	X	M0	8	3	SC	092195	100695	100395
	J62890	J		ASBESTOS GASKET REMOVAL	X	M0		2	NC	091295	103095	101895
	A60100	I		MNPWR TO BLOCK UP	X	M0	4	2	TA	091295	100695	100395
	A59723	J		ROOFING CORE SAMPLES & REMOVAL	X	M0	8	3		090695	110695	110195
	A59720	J		ROOFING CORE SAMPLES & REMOVAL	X	M0	8	3		090695	110695	101895
	A59404	I		STRIP ASBESTOS GASKETS {2}	X	M0	8	3	SE	083195	090595	090795
	A58434	J		REMOVE INSULATION/GASKETS	X	M0	8	3	RP	081795	093095	090795
	A59308	I		REMOVE ASBESTOS GASKETS	X	M0	8	1	TA	083095	083095	083195
	A58740	J		REMOVE ASBESTOS FLANGE	X	M0	8	1		082295	082295	083095
	A58594	J		INSPECT TILE AT ENSYS FOR ASB	X	M0	8	3		082195	083195	083195
	A58549	I		REMOVE ASBESTOS/DRYER BOTTOM	X	M0	8	2	SC	081895	082195	082495

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003614

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A61260 ORIG WR: A61166 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 09 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET, ON FLG
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 100795 RECNO: PROP NO:
REQ BY: A.VASQUEZ C&P: WRITTEN: 092895 HWP: MTAG: SLIPBL:
SERV: CH4 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 09 29 95
DATE COMPLETE: 101195 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 320 490

JOB DETAILS: WE ARE REMOVING A SPOOL FOR REVISIONS ON THIS DATES 09-29-95 FRI.
AND ON 10-02-95 MONDAY, 10-04-95 WEDNESDAY AND 10-07-95 FRIDAY
WE ARE ASSUMING THEY ARE ASBESTOS, WE WILL NOTIFIED OTHER WISE.
FLANGES WILL BE ON THE PIPE RACK AT #2 GAS FURNACES THANKS ANDREW

5-983 DEL PHONE 3581
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 092995 LAST ACT: N DATE: 101895

PF3:RETURN

003615

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A61160 ORIG WR: A56776 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 094100 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 26 WCAT: RP RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET
BLD/UNT: W/S AR: SH WK TP: 4 WANTED: 101895 RECNO: PROP NO:
REQ BY: HENDERSON C&P: WRITTEN: 092795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 100395 APPROVED BY: HERRON
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 180 60

JOB DETAILS: PLEASE HAVE B & R ASBESTOS CREW REMOVE GASKET OFF SKIMMER
FLG LOCATED AT WELD SHOP S-SIDE ON 9-28-95 A.M.

DEL 163-S PHONE 2493
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 092795 LAST ACT: N DATE: 101895

PF3:RETURN

003616

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J62897 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 838000 INDX: 92 1ST ORDER: 00006114 2ND ORD: 07300
PR: 3 OR: 99 WCAT: RW CD: RW RS: DESC: ASBESTOS TESTING
BLD/UNT: HP11 AR: WK TP: 8 WANTED: 102095 RECNO: PROP NO:
REQ BY: P BETHANY C&P: WRITTEN: 092595 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: KAV ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101895 APPROVED BY: BETHANY
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 250 200

JOB DETAILS: PLEASE TEST THE FLOOR TILE IN THE PELLET SORTER ROOM AT HP-II FOR
ASBESTOS. CONTACT ME FOR ADDITIONAL INFO @ PAGER 5-511.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 092595 LAST ACT: N DATE: 110395

PF3:RETURN

003617

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A60774 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 880000 INDX: 80 1ST ORDER: 00004830 2ND ORD: 00101
PR: 3 OR: MM WCAT: SC RW CD: RW RS: DESC: TEST INSULATION
BLD/UNT: MMD AR: MM WK TP: 8 WANTED: 100695 RECNO: PROP NO:
REQ BY: S.WIEST C&P: WRITTEN: 092195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 100395 APPROVED BY: S.WIEST
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 170 500

JOB DETAILS: HEAT EXCHANGERS LOCATED ON THE SOUTH SIDE OF #1 GAS NEED TO BE
TESTED FOR ASBESTOS CONTENT. SEE SAM WIEST FOR LOCATION
EXT. 2290 OR PAGER 5-644

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 092195 LAST ACT: N DATE: 111795

PF3:RETURN

003618

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: J62890 ORIG WR: PROCESS ID:
DIV/LOC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006310 2ND ORD: 73000
PR: 2 OR: PB WCAT: NC RW CD: RW RS: DESC: ASBESTOS GASKET REMOVAL
BLD/UNT: AR: WK TP: WANTED: 103095 RECNO: PROP NO:
REQ BY: P BETHANY C&P: WRITTEN: 091295 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101895 APPROVED BY: BETHANY
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 610 40

JOB DETAILS: REMOVE ASBESTOS GASKETS DURING THE HP-1 SHUTDOWN.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 091295 LAST ACT: C DATE: 102395

PF3:RETURN

003619

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A60100 ORIG WR: A59787 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: TA RW CD: RW RS: DESC: MNPWR TO BLOCK UP
BLD/UNT: LP1F AR: L1 WK TP: 4 WANTED: 100695 RECNO: PROP NO:
REQ BY: S.SANDERS C&P: WRITTEN: 091295 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 100395 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 870 1200

JOB DETAILS: PLEASE FURNISH 2 MEN TO WORK WITH UCC RIGGERS TO SHORE UP
FOR REMOVAL OF HC5 GEAR BOX AND MOTOR.WILL ALSO NEED TO SHORE UP
FOR REINSTALLATION OF SAME (ON OR ABOUT OCTOBER 4TH).

DEL PHONE 5298
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 091295 LAST ACT: N DATE: 101895

PF3:RETURN

003620

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A59723 ORIG WR: 141117 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 094100 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: ROOFING CORE SAMPLES & REMOVAL
BLD/UNT: HP1 AR: H1 WK TP: 8 WANTED: 110695 RECNO: PROP NO:
REQ BY: J LEFTWICH C&P: WRITTEN: 090695 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: Y SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: M0 ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 110195 APPROVED BY: JJL
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 380 630

JOB DETAILS: TAKE ROOFING CORE SAMPLES AND ANALYZE FOR BLDG. 101. PREPARE COST
ESTIMATE FOR ROOFING MEMBRANE REMOVALS, ABANDON PIPING & MISC. ST
RUCTURAL REMOVALS & DISPOSAL FOR BUILDING 101. SEE JIM LEFTWICH EX
TENSION 2821 FOR COMPLETE INSTRUCTIONS AND DWGS. BEFORE STARING JOB
DEL D.R.BROWN/C.WELFEL PHONE 3610

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 090795 LAST ACT: N DATE: 112895

PF3:RETURN

003621

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A59720 ORIG WR: PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: ROOFING CORE SAMPLES & REMOVAL
BLD/UNT: LP1 AR: WK TP: 8 WANTED: 110695 RECNO: PROP NO:
REQ BY: J LEFTWICH C&P: WRITTEN: 090695 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: Y SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 101895 APPROVED BY: JJL
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 660 510

JOB DETAILS: TAKE ROOFING CORE SAMPLES AND ANALYZE FOR BLDG. 341. PREPARE COST
ESTIMATE FOR ROOFING MEMBRANE REMOVALS, ABANDON PIPING & MISC. ST
RUCTURAL REMOVALS & DISPOSAL FOR BUILDING 341. SEE JIM LEFTWICH EX
TENSION 2821 FOR COMPLETE INSTRUCTIONS AND DWGS. BEFORE STARING JOB
DEL D.R.BROWN/C.WELFEL PHONE 3610
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 090795 LAST ACT: N DATE: 110195

PF3:RETURN

003622

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A59404 ORIG WR: A54852 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 009760 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 31 WCAT: SE RW CD: RW RS: DESC: STRIP ASBESTOS GASKETS {2}
BLD/UNT: LP-1 AR: WK TP: 8 WANTED: 090595 RECNO: PROP NO:
REQ BY: C FANELLI C&P: WRITTEN: 083195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 090795 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 120 80

JOB DETAILS: PLEASE STRIP ALL ASBESTOS GASKETS OFF OF ABANDONED PIPE LOCATED
ON EAST SIDE OF LP-1. ASK FANELLI FOR ADDITIONAL INFO AT 5-802.

DEL PHONE 3649
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 083195 LAST ACT: N DATE: 101095

PF3:RETURN

003623

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58434 ORIG WR: 237812 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 220530 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RP RW CD: RW RS: DESC: REMOVE INSULATION/GASKETS
BLD/UNT: BD AR: WK TP: 8 WANTED: 093095 RECNO: PROP NO:
REQ BY: JAN SIMON C&P: WRITTEN: 081795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 090795 APPROVED BY: JAN
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 480 420

JOB DETAILS: REMOVE THE INSULATION MATERIAL AND REMAINING GASKETS FROM THE TWO
SURPLUS TANKS AT MARINE TERMINAL. UNIT UFT GUYS WILL REMOVE FLANGES
FROM THE TANK. SEE JAN OR NORMAN IF YOU HAVE ANY QUESTIONS.

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 081795 LAST ACT: N DATE: 102495

PF3:RETURN

003624

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A59308 ORIG WR: A58948 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 22 WCAT: TA RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: GEU AR: CH WK TP: 8 WANTED: 083095 RECNO: PROP NO:
REQ BY: ANN T. C&P: WRITTEN: 083095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 083195 APPROVED BY: ANN T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 150 160

JOB DETAILS: TO COVER THE COST OF REMOVING ASBESTOS GASKETS. THERE ARE 2 JOBS
WORKING: 1. WELD REPAIRS ON SMALL TANK, & 2. REPLACE 7 VALVES IN
TK FARM.
THNX, ANN T. 5-401

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 083095 LAST ACT: N DATE: 091395

PF3:RETURN

003625

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58740 ORIG WR: 104460 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 004320 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS FLANGE
BLD/UNT: B-420 AR: ES WK TP: 8 WANTED: 082295 RECNO: PROP NO:
REQ BY: R.GOSSETT C&P: WRITTEN: 082295 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 083095 APPROVED BY: SIMMS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 110 90

JOB DETAILS: PLEASE REMOVE SUSPECTED ASBESTOS FROM PIPING AT #22 BOILER.
SEE R. GOSSETT FOR LOCATION.

DEL PHONE 2562
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 082295 LAST ACT: N DATE: 083195

PF3:RETURN

003626

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58594 ORIG WR: 104412 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 004320 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: WCAT: RW CD: RW RS: DESC: INSPECT TILE AT ENSYS FOR ASB
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 083195 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 082195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: 29 PLAN CD: RAM ASIS/ENGR: EST START: 08 28 95
DATE COMPLETE: 083195 APPROVED BY: RED SIM
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 670 780 PL 10 00

JOB DETAILS: PLEASE, SAMPLE FLOOR TILES & GLUE WERE THE OLD CONTROL ROOM WAS
THE TILES OR GLUE MAY CONTAIN ASBESTOS MATERIALS. THIS JOB IS
LOCATED ON THE WEST SIDE OF ENERGY SYSTEMS. SEE BOSCO FOR MORE
INFORMATION IF NEEDED. PAGER 5-608 OR 2617 THANK YOU

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 082195 LAST ACT: N DATE: 100495

PF3:RETURN

003627

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58549 ORIG WR: A56859 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 31 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS/DRYER BOTTOM
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 082195 RECNO: PROP NO:
REQ BY: A.VASQUEZ C&P: WRITTEN: 081895 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 082495 APPROVED BY: URESTI
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 250 240

JOB DETAILS: PLEASE REMOVE ASBESTOS FROM THE BOTTOM OF #5 FURNACE DRYER.
PRIOR TO SANDBLASTING PLEASE CONTACT ANDY URESTI 5-113
WHEN COMPLETE. ARRANGEMENTS FOR HAULING CAN BE MADE THEN.
THANKS ANDREW VASQUEZ 5-983

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 081895 LAST ACT: N DATE: 091395

PF3:RETURN

003628

WLCLIST

*** WORK REQUEST LISTING ***

PAGE 14 OF 14

DATE: 11/22/96

RESPCODE=M0,DATEWRIT FR 080195 TO 110196

X	WK REQ	T	P	JOB DESCRIPTION	S	RE	W	WK	-----	DATES	-----	
	FP				T	SP	T	PR	CAT	WRITN	WANTED	CLOSED
				<== SORT SELECTION LINE ==>								
	A58469	J		REMOVE ASBESTOS GASKETS	X	M0	8	2		081795	081895	082495
	A58216	J		DE-INSULATE ABESTOSES	X	M0	8	3	SA	081495	082195	082495
	A58053	J		REMOVE ASBESTOS INSUL-TK3800	X	M0	8	3	SE	081095	082195	082495
	A58051	I		REMOVE AREAS OF ASBESTOS	X	M0	8	1		081095	081095	081595
	A57791	I		RMV ASBESTOS GASKETS-JOY A/CMP	X	M0	3	1	TA	080795	080895	081495
	A57680	I		CONTRACT TO REMOVE OLD GASKET	X	M0	3	2		080495	081195	081495
	A57475	I		REMOVE ASBESTOS GASKEST THURS.	X	M0	8	1	SC	080295	080395	081095
	A57460	J		REMOVE ASBESTOS GASKETS	X	M0	8	3	SC	080195	080995	081095
	A57459	J		ASBESTOS REMOVAL-LP-1 JB'S	X	M0	8	3	SE	080195	093095	083195
	A57414	I		REMOVE ASBESTOS GASKEST 304	X	M0	3	2	OS	080195	080195	081095
	A56955	J		REMOVE ASBESTOS INSULATION	X	M0	8	3		080195	072595	080495

2 IDR 3 RTN 4 DETL 5 SRT 6 PLN 7 UP 8 DN 9 PAR 10 F/LST 11 HIST 12 PRT

003629

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58469 ORIG WR: 119553 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 82 WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 081895 RECNO: PROP NO:
REQ BY: YAKLIN C&P: WRITTEN: 081795 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 082495 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 100 160

JOB DETAILS: REMOVE ASBESTOS GASKETS FROM #2 HOT WATER PUMP AND PIPING
SO REBUILT PUMP CAN BE INSTALLED.

DEL PHONE 2965
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 081795 LAST ACT: N DATE: 083195

PF3:RETURN

003630

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58216 ORIG WR: 147700 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 127300 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 21 WCAT: SA RW CD: RW RS: DESC: DE-INSULATE ABESTOSES
BLD/UNT: OXIDE AR: CH WK TP: 8 WANTED: 082195 RECNO: PROP NO:
REQ BY: DF MOBLEY C&P: WRITTEN: 081495 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 082495 APPROVED BY: TRIPP
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 260 380

JOB DETAILS: PLEASE DE-INSULATE ABESTOSES LINE CONTACT DARREN FOR LOCATION
THANKS DARREN

DEL 120S PHONE 2250
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 081495 LAST ACT: N DATE: 091495

PF3:RETURN

003631

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58053 ORIG WR: 293800 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 293220 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 89 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS INSUL-TK3800
BLD/UNT: NF AR: CH WK TP: 8 WANTED: 082195 RECNO: PROP NO:
REQ BY: S. CURRY C&P: WRITTEN: 081095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 082495 APPROVED BY:
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 400 400

JOB DETAILS: PLEASE REMOVE THE ASBESTOS INSULATION FROM THE PIPING COMING FROM
TANK 3800. START WITH THE PIPING GOING THRU THE DIKE WALL SO T&I
CAN INSPECT IT AND WE CAN BEGIN WRAPPING. THANKS, STEVE CURRY
X2712.

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 081095 LAST ACT: N DATE: 082995

PF3:RETURN

003632

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A58051 ORIG WR: A56241 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: WCAT: RW CD: RW RS: DESC: REMOVE AREAS OF ASBESTOS
BLD/UNT: HP2 AR: WK TP: 8 WANTED: 081095 RECNO: PROP NO:
REQ BY: V.SPRAGUE C&P: WRITTEN: 081095 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: 29 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 081595 APPROVED BY: E.MYERS
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 455

JOB DETAILS: PLEASE PROVIDE MANPOWER TO REMOVE ASBESTOS

THANKS VIVIAN

DEL PHONE 3479
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 081095 LAST ACT: N DATE: 081895

PF3:RETURN

003633

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57791 ORIG WR: A56960 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 008510 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 10 WCAT: TA RW CD: RW RS: DESC: RMV ASBESTOS GASKETS-JOY A/CMP
BLD/UNT: BL-17 AR: ES WK TP: 3 WANTED: 080895 RECNO: PROP NO:
REQ BY: CONTRERAS C&P: WRITTEN: 080795 HWP: MTAG: SLIPBL:
SERV: AIR COMPRESSOR DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER: 29 PLAN CD: RAM ASIS/ENGR: EST START: 08 07 95
DATE COMPLETE: 081495 APPROVED BY: DWJ(JC)
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 00

JOB DETAILS: REMOVE ASBESTOS GASKETS FROM FLANGES ON JOY AIR COMPRESSOR AT
O2 UNIT.

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 080795 LAST ACT: N DATE: 082995
JOE CONTRERAS 5-221
DEL BL17, O2 UNIT PHONE 3009

PF3:RETURN

003634

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57680 ORIG WR: A54181 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 094100 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: 10 WCAT: RW CD: RW RS: DESC: CONTRACT TO REMOVE OLD GASKET
BLD/UNT: HP1 AR: H1 WK TP: 3 WANTED: 081195 RECNO: PROP NO:
REQ BY: R. BOSCO C&P: WRITTEN: 080495 HWP: MTAG: SLIPBL:
SERV: HP1-03 DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: 29 PLAN CD: RAM ASIS/ENGR: EST START: 08 08 95
DATE COMPLETE: 081495 APPROVED BY: MCCUTCH
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 300 400 PL 20 00

JOB DETAILS: PLEASE PROVIDE ASBESTOS PERSONNEL TO REMOVE OLD GASKET MATERIAL,
DURING THE HP1 TURNAROUND. FOR MORE INFORMATION CONTACT BOSCO AT
2617 OR 5-608. THERE WILL BE APPROX. 26 VALVES THAT WILL BE DONE.
THANK YOU GARY.

DEL PHONE
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 080495 LAST ACT: N DATE: 081695

PF3:RETURN

003635

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57475 ORIG WR: A57471 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 008170 INDX: 1ST ORDER: 2ND ORD:
PR: 1 OR: 16 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS GASKEST THURS.
BLD/UNT: ENSYS AR: ES WK TP: 8 WANTED: 080395 RECNO: PROP NO:
REQ BY: RED SIMMS C&P: WRITTEN: 080295 HWP: MTAG: SLIPBL:
SERV: AIR PIPING DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: 29 PLAN CD: RAM ASIS/ENGR: EST START: 08 03 95
DATE COMPLETE: 081095 APPROVED BY: B.B.B.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 80

JOB DETAILS: PLEASE HAVE ONE INSULATOR TO REMOVE ASBESTOS GASKETS OFF 4"
FLANGES BEFORE WE SEND PIPE TO WELD SHOP THURSDAY MORNING.
PLEASE HAVE INSULATOR AT BLDG 121 SOUTH (AIN BLDG.) AT 8:00 AM
SO WE CAN GET THE PIPE TO THE SHOP. ROBERT GOSSETT WILL BE THERE.
THANKS BB DEL AIR BLDG. 121 SOUTH PHONE 2592
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 080295 LAST ACT: N DATE: 081195

PF3:RETURN

003636

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57460 ORIG WR: PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNT: OLFUR AR: OL WK TP: 8 WANTED: 080995 RECNO: PROP NO:
REQ BY: OSPINA C&P: WRITTEN: 080195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: 29 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 081095 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 100

JOB DETAILS: REMOVE ASBESTOS INSULATION (GASKETS) FROM PIPING AT A&B
WASH PAD.

DEL PHONE 2608
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 080195 LAST ACT: N DATE: 081195

PF3:RETURN

003637

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57459 ORIG WR: 155512 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 148400 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 83 WCAT: SE RW CD: RW RS: DESC: ASBESTOS REMOVAL-LP-1 JB'S
BLD/UNT: LP1 AR: L1 WK TP: 8 WANTED: 093095 RECNO: PROP NO:
REQ BY: TOM T. C&P: WRITTEN: 080195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: M0 PLAN CD: RAM ASIS/ENGR: EST START: 08 01 95
DATE COMPLETE: 083195 APPROVED BY: TOM T.
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 3750 1620

JOB DETAILS: REMOVE ASBESTOS FROM J-BOXES IN FIELD AT HOT COMPOUNDING, B-341
AREA.

DEL B-341 PHONE 2832
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 080195 LAST ACT: N DATE: 090695

PF3:RETURN

003638

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A57414 ORIG WR: A56075 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 071300 INDX: 1ST ORDER: 2ND ORD:
PR: 2 OR: M5 WCAT: OS RW CD: RW RS: DESC: REMOVE ASBESTOS GASKEST 304
BLD/UNT: 304 AR: SH WK TP: 3 WANTED: 080195 RECNO: PROP NO:
REQ BY: K.HOLLAND C&P: WRITTEN: 080195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER: PLAN CD: ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 081095 APPROVED BY: HOLLAND
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 200 100

JOB DETAILS: PLEASE REMOVE ASBESTOS GASKETS OF DUMP TANK COOLER FROM
ODU LOCATED AT 304 WASH PAD.

DEL PHONE 3575
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 95 DATE ENTR: 080195 LAST ACT: N DATE: 091295

PF3:RETURN

003639

WLCDETS *** SEADRIFT WORK REQUEST *** *** SHOW ONLY ***

WORK REQ NO: A56955 ORIG WR: 116432 PROCESS ID:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: 3 OR: 82 WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNT: OLSEP AR: OL WK TP: 8 WANTED: 072595 RECNO: PROP NO:
REQ BY: HODDE C&P: WRITTEN: 080195 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER: 29 PLAN CD: RAM ASIS/ENGR: EST START: 00 00 00
DATE COMPLETE: 080495 APPROVED BY: URESTE
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 320

JOB DETAILS: REMOVE ASBESTOS INSULATION FROM #12 COMP MOTOR OIL COOLER

DEL PHONE 2982
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 95 DATE ENTR: 072495 LAST ACT: N DATE: 080995

PF3:RETURN

003640

WK	REQ	R	I D T	P	JOB DESCRIPTION	S T	RE SP	-----TOTAL S/T	TO DATE O/T	----- TOTAL
H14727			J		PICKUP ASBESTOS INSUALTION	X	MO	101	0	101
H14739			J		REMOVE INSULATION FROM CND.HDR	X	MO	0	2	2
H15153			I		REMOVE INSULATION	X	MO	10	0	10
H16117			J		REMOVE INSULATION ON VALVE	X	MO	75	0	75
H16147			J		REMOVE ASBESTOS ON C2H2 STILL	X	MO	4	0	4
H16404			J		STRIP ASB. ON STEAM LINE	X	MO	4	0	4
H16416			J		SCRAP ASB. GAST AT 304	X	MO	6	0	6
H16508			J		STRIP ASB. #13 COMP STM LINE	X	MO	82	21	103
H16544			I		REMOVE GASKET FROM CYL	X	MO	34	6	40
H17112			J		REMOVE ASBESTOS INSULATION	X	MO	17	0	17
H18369			J		STRIP INSULATION	X	MO	4	0	4
H19591			J		REMOVE ASBESTOS GASKET	X	MO	4	0	4
H19863			I		REMOVE GASKETS	X	MO	6	5	11
H20623			J		MAKE LISTING OF ALL ASBESTOS	X	MO	63	0	63
H20645			J		REMOVE ASBESTOS INS. OFF COLUM	X	MO	36	0	36
H20812			J		REMOVE ASBESTOS GASKETS	X	MO	18	0	18
H20822			J		REMOVE ASBESTOS INSULATION	X	MO	18	0	18
H20839			J		COVER EXPOSED INSULATION	X	MO	7	0	7
H21018			J		REMOVE ASBESTOS	X	MO	8	0	8
H21177			I		REMOVE ASBESTOS GASKETS	X	MO	24	0	24
H21405			J		REMOVE INSULATION	X	MO	2	12	14
H21507			J		REMOVE INSULATION (ASBESTOS)	X	MO	46	0	46
H21518			J		REMOVE INSULATION	X	MO	33	10	43
H21544			I		REMOVE GASKET (ASBESTOS)	X	MO	6	0	6
H21632			J		REMOVE ASBESTOS INSULATION	X	MO	0	10	10
H21648			J		REMOVE ASBESTOS	X	MO	2	0	2
H21738			J		IDENTIFY INSULATION ON TANKS	X	MO	6	0	6
H21741			J			X	MO	29	0	29
H21865			I		STRIP ASBESTOS GASKETS	X	MO	0	0	0
H21899			I		STRIP GASKETS ON OX 1 & 2	X	MO	13	0	13
H21945			I		STRIP ASBESTOS GASKETS	X	MO	24	0	24
H22079			J		REMOVE INSULATION FROM ACETIC	X	MO	80	41	121
H22183			I		REMOVE INSULATION	X	MO	34	4	38
H22200			J		REMOVE GASKET FROM VALVE	X	MO	2	0	2
H22302			I		STIP ASBESTOS NO. 2	X	MO	21	18	39
H22799			J		SAMPLE #1 GAS C2H4 COL	X	MO	28	0	28
H23244			J		REMOVE ASBESTOS	X	MO	30	0	30
H23490			I		REMOVE ASBESTOS GASKETS	X	MO	6	0	6
H23792 *			J		REMOVE ASBESTOS SIDING	X	MO	223	0	223
H23983			J		CLEAN GASKETS ON TKS. 904,903	X	MO	2	0	2
H24201 *			J		BULK PRIMARY BINS	X	MO	8	6	14
H25368			J		REMOVE ASBESTOS GASKETS	X	MO	6	0	6
H25369			J		REMOVE ASBESTOS GASKETS	X	MO	12	0	12
H25435			I		ASBESTOS GASKET REMOVAL	X	MO	4	0	4
H26917			J		SCRAPE ASBESTOS GASKET	X	MO	11	0	11
H27001			J		REMOVE ASBESTOS INSUL. ON S/G	X	MO	8	34	42
H27031			J		CK VALVE VD UNIT	X	MO	4	0	4
H27068			J		ASBESTOS REMOVAL FLARE TOWER	X	MO	6	0	6
H27088			J		REMOVE ASBESTOS GASKETS	X	MO	6	0	6
H28056			I		REMOVE ASBESTOS GAXKETS	X	MO	8	0	8
H28059			I		REMOVE INSULATION	X	MO	8	0	8
H28204			J		REMOVE ASBESTOS GASKETS	X	MO	0	1	1

005505

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H14727 ORIG WR: 00203000 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 220040 INDX: 1ST ORDER: 2ND ORD:
PR: A DR: C3 WCAT: SE RW CD: RW RS: DESC: PICKUP ASBESTOS INSUALTION
BLD/UNIT: N.FLD AR: CH WK TP: 8 WANTED: 090589 RECNO: PROPNO:
REQ BY: BITTERLY C&P: WRITTEN: 090589 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 091989

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	1010									

JOB DETAIL: PICK UP ASBESTOS INSULATION IN PIPE RACK AND ROADWAY
ENTRANCE TO NORTH FIELD.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 091189 LAST ACT: N DATE: 100489

005506

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H14739 ORIG WR: 00203000 APPROVED BY: R.GECK
DIV/LDC: 500510 ACCOUNT: 220040 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: C3 WCAT: SE RW CD: RW RS: DESC: REMOVE INSULATION FROM CND.HDR
BLD/UNIT: NF AR: WK TP: 8 WANTED: 101889 RECNO: PROPNO:
REQ BY: BITTERLY C&P: WRITTEN: 101789 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 103089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	20									

JOB DETAIL: REMOVE THE INSULATION FROM A SECTION OF RACK 2 CONDENSATE HEADER.
SAMPLES HAVE BEEN PULLED BUT HAVE NOT RECEIVED RESULTS. WILL
TREAT THIS AS ASBESTOS.

DELIVER TO: PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 102489 LAST ACT: N DATE: 110389

005507

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H15153 ORIG WR: 00H04110 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: D OR: 10 WCAT: SC RW CD: RW RS: DESC: REMOVE INSULATION
BLD/UNIT: 501N AR: WK TP: 8 WANTED: 083189 RECNO: PROPNO:
REQ BY: STEVENS C&P: WRITTEN: 081189 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 092589

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	100									

JOB DETAIL: REMOVE INSULATION ON 6" ACETYLENE LINE LINE IN #2 GAS PIPE RACK
ACROSS STREET LINE IS OPEN ENDED

DELIVER TO: PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 081189 LAST ACT: N DATE: 092989

005508

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H16117 ORIG WR: 00119587 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: A OR: JB WCAT: US RW CD: RW RS: DESC: REMOVE INSULATION ON VALVE
BLD/UNIT: AR: WK TP: 8 WANTED: 080889 RECNO: PROPNO:
REQ BY: BAUER C&P: WRITTEN: 080789 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 082389

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	750									

JOB DETAIL: REMOVE ASBESTOS INSULATION FROM STEAM VALVES
ON #12 FURNACE TO REMOVE 0 PLATES

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 080989 LAST ACT: N DATE: 082489

005509

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H16147 ORIG WR: 00119907 APPROVED BY:
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: A OR: 82 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS ON C2H2 STILL
BLD/UNIT: 0L-2 AR: WK TP: 3 WANTED: 062289 RECNO: PROPNQ:
REQ BY: ELMO C&P: WRITTEN: 062289 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 063089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	40									

JOB DETAIL: PLEASE REMOVE ASBESTOS ON C2H2 STILL D/P LINE (4" X 2' LINE)

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 062389 LAST ACT: N DATE: 070189

005510

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H16404 ORIG WR: 00119910 APPROVED BY: DAN
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: SC RW CD: RW RS: DESC: STRIP ASB. ON STEAM LINE
BLD/UNIT: OL-SE AR: OL WK TP: 4 WANTED: 062289 RECNO: PROPNO:
REQ BY: DE HOYOS C&P: WRITTEN: 062189 HWP: Y MTAG: SLIPBL:
SERV: STEAM 75# DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 063089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	40									

JOB DETAIL:

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 062389 LAST ACT: N DATE: 070189

005511

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H16416 ORIG WR: 00128510 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 039290 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: 18 WCAT: SC RW CD: RW RS: DESC: SCRAP ASB. GAST AT 304
BLD/UNIT: 304 AR: WK TP: 4 WANTED: 063089 RECNO: PROPNO:
REQ BY: DEHOYOS C&P: WRITTEN: 063089 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 080289

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	60									

JOB DETAIL:

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 070589 LAST ACT: N DATE: 080389

005512

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H16508 ORIG WR: 00116433 APPROVED BY:
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: SD RW CD: RW RS: DESC: STRIP ASB. #13 COMP STM LINE
BLD/UNIT: OL-2 AR: WK TP: 4 WANTED: 062289 RECNO: PROPNO:
REQ BY: E GARCIA C&P: WRITTEN: 052389 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 062689

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	1035									

JOB DETAIL: PLEASE STRIP ASBESTOS FROM #13 COMPRESSOR STEAM & CONDENSATE
PIPING DURING 6-19-89 SHUTDOWN. CHECK WITH ERNEST GARCIA
FOR LOCATION AND SCHEDULING. WRAP WITH TEMPORARY INSULATION UNTIL
PERMANENT CAN BE INSTALLED. EXT 2439/5-609
S/D.....

DELIVER TO: PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 052489 LAST ACT: N DATE: 062889

005513

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H16544 ORIG WR: 00G86335 APPROVED BY:
DIV/LDC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: SC RW CD: RW RS: DESC: REMOVE GASKET FROM CYL
BLD/UNIT: #2GAS AR: WK TP: 4 WANTED: 052389 RECNO: PROPNO:
REQ BY: HARTMAN C&P: WRITTEN: 052389 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 053089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	400									

JOB DETAIL: REMOVE ASBESTOS GASKET FROM CYL.

ASB.....

DELIVER TO: PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 052489 LAST ACT: N DATE: 060189

005514

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H17112 ORIG WR: 00119587 APPROVED BY: ACHIERN
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: NB WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNIT: FURN. AR: DL WK TP: 3 WANTED: 061489 RECNO: PROPNO:
REQ BY: BEDEE C&P: WRITTEN: 061289 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 063089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	170									

JOB DETAIL: REMOVE INSULATION FROM NO. 12 FURNACE / NO. 17 FURNACE
ASBESTOS.....

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 061689 LAST ACT: N DATE: 070189

005515

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H18369 ORIG WR: 00272600 APPROVED BY: R.GECK
DIV/LOC: 500510 ACCOUNT: 260940 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: C3 WCAT: SE RW CD: RW RS: DESC: STRIP INSULATION
BLD/UNIT: RK2-A AR: CH WK TP: 8 WANTED: 012990 RECNO: PROPNO:
REQ BY: AUTRY C&P: WRITTEN: 012990 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 013190

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	40									

JOB DETAIL: STRIP ASBESTOS INSULATION ON RACK 2-A SPOT 2.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 013090 LAST ACT: N DATE: 020390

005516

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H19591 ORIG WR: 00135607 APPROVED BY: KNEBEL

DIV/LDC: 500510 ACCOUNT: 071250 INDX: 1ST ORDER: 2ND ORD:

PR: D OR: WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS GASKET

BLD/UNIT: 163-S AR: SH WK TP: 8 WANTED: 111089 RECNO: PROPNO:

REQ BY: KNEBEL C&P: WRITTEN: 110889 HWP: MTAG: SLIPBL:

SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO

STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000

DATE COMPLETE: 112089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	40									

JOB DETAIL: REMOVE WHAT APPEARS TO BE ASBESTOS GASKET FROM A-MOT VALVE LOCATED
AT INST. SHOP NORTH DOOR.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0

IND: J CL YR: 89 DATE ENTR: 111089 LAST ACT: N DATE: 112189

005517

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H19863 ORIG WR: 00H27556 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: C OR: 05 WCAT: SC RW CD: RW RS: DESC: REMOVE GASKETS
BLD/UNIT: 163-S AR: SH WK TP: 8 WANTED: 103089 RECNO: PROPNO:
REQ BY: WISE C&P: WRITTEN: 103089 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 110689

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	115									

JOB DETAIL: REMOVE ASBESTOS GASKETS FROM VALVE BODY.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 103189 LAST ACT: N DATE: 110789

005518

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H20623 ORIG WR: 00153411 APPROVED BY: WTH
DIV/LDC: 500510 ACCOUNT: 148150 INDX: 1ST ORDER: 2ND ORD:
PR: D DR: CE WCAT: SA RW CD: RW RS: DESC: MAKE LISTING OF ALL ASBESTOS
BLD/UNIT: LP1RX AR: PL WK TP: 8 WANTED: 021790 RECNO: PROPNO:
REQ BY: C.ENGELS C&P: WRITTEN: 011590 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 022190

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	400	630									

JOB DETAIL: MAKE LISTING OF ALL THE ASBESTOS INSULATION IN THE LP1 REACTION A-
REA. INCLUDING PURIFICATION CATALYST, G-5 AND G-17 AREAS.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 011790 LAST ACT: N DATE: 022890

005519

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H20645 ORIG WR: 00153411 APPROVED BY: D.CANO
DIV/LOC: 500510 ACCOUNT: 148150 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: CE WCAT: SA RW CD: RW RS: DESC: REMOVE ASBESTOS INS. OFF COLUM
BLD/UNIT: LP1RX AR: PL WK TP: 8 WANTED: 031090 RECND: PROPNO:
REQ BY: C.ENGELS C&P: WRITTEN: 011190 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 031490

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	365									

JOB DETAIL: REMOVE THE ASBESTOS INSULATION FORM THE ISOPENTANE COLUMN.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 011690 LAST ACT: N DATE: 032290

005520

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H20812 ORIG WR: 00289914 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 290000 INDX: 1ST ORDER: 2ND ORD:
PR: A OR: WCAT: RP RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNIT: DIST AR: CH WK TP: 8 WANTED: 073189 RECNO: PROPNO:
REQ BY: PORTER C&P: WRITTEN: 073189 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 082389

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	180									

JOB DETAIL: PLEASE REMOVE ASBESTOS GASKETS ON PIPE PLANES ON THE DISCHARGE
MOTOR VALVE ON THE STRENGTH SEWER PUMPS

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 080889 LAST ACT: N DATE: 082489

005521

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H20822 ORIG WR: 00246511 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 237440 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: JP WCAT: RP RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNIT: DIST AR: CH WK TP: 4 WANTED: 081089 RECNO: PROPNO:
REQ BY: PORTER C&P: WRITTEN: 080989 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 082389

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	180									

JOB DETAIL: STRIP ASBESTOS INSULATION FOR LINE REPAIR

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD D/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 081689 LAST ACT: N DATE: 110389

005522

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H20839 ORIG WR: 00262517 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 221940 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: JP WCAT: SA RW CD: RW RS: DESC: COVER EXPOSED INSULATION
BLD/UNIT: DIST AR: CH WK TP: 8 WANTED: 082589 RECNO: PROPNO:
REQ BY: PORTER C&P: WRITTEN: 081889 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 091989
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTH
IS 160 70

JOB DETAIL: COVER THE EXPOSED ASBESTOS INSULATION ON THE STEAM HEADER
LOCATED ON THE WEST END OF LOADING RACK 3.

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LABS: 0 YTD MATS: 0
IND: J CL YR: 89 DATE ENTR: 083189 LAST ACT: N DATE: 092089

005523

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21018 ORIG WR: 00138559 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 071300 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 22 WCAT: RW CD: RW RS: DESC: REMOVE ASBESTOS
BLD/UNIT: ACETA AR: CH WK TP: 8 WANTED: 081089 RECNO: PROPNO:
REQ BY: BROWNING C&P: WRITTEN: 080889 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 082389

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	80									

JOB DETAIL: PLEASE REMOVE APPROX 6' OF ASBESTOS INSULATION FROM TANK 3625
CIRCULATING LINE IN BUTYLS T.SK FARM AT ODU LINE IS GROUND LEVEL
AND A 2" LINE NEED TO REMOVE ASBESTOS SO WE CAN REPLACE A LINE

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 081089 LAST ACT: N DATE: 082489

005524

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21177 ORIG WR: 00H35766 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 071100 INDX: 1ST ORDER: 2ND ORD:
PR: D OR: 22 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNIT: AMINE AR: CH WK TP: 8 WANTED: 111789 RECNO: PROPNO:
REQ BY: WILLIAMS C&P: WRITTEN: 111589 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 112989

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	240									

JOB DETAIL: PLEASE REMOVE ASBESTOS GASKETS FROM VALVES ON PALLET AT 360 WEST.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD D/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 111689 LAST ACT: N DATE: 113089

005525

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21405 ORIG WR: 00119921 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: US RW CD: RW RS: DESC: REMOVE INSULATION
BLD/UNIT: DL-2 AR: DL WK TP: 4 WANTED: 070689 RECNO: PROPNO:
REQ BY: NEILL C&P: WRITTEN: 070689 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 080289

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	140									

JOB DETAIL: PLEASE REMOVE INSULATION FROM #1C2A2 STILL KETTLE
REPLACE AFTER LEAKS ARE PLUGGED

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 070789 LAST ACT: N DATE: 080389

005526

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21507 ORIG WR: 00128500 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 039290 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: SC RW CD: RW RS: DESC: REMOVE INSULATION (ASBESTOS)
BLD/UNIT: #1GAS AR: OL WK TP: 8 WANTED: 081889 RECNO: PROPNO:
REQ BY: DEHOYOS C&P: WRITTEN: 081889 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 083089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	460									

JOB DETAIL: REMOVE ASBESTOS FROM SCRAP INSTRUMENT TUBIGN LOCATED AT 201
WEST (NEXT TO ROAD SIDE)

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 082389 LAST ACT: N DATE: 090789

005527

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21518 ORIG WR: 00119928 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: US RW CD: RW RS: DESC: REMOVE INSULATION
BLD/UNIT: B-501 AR: OL WK TP: 8 WANTED: 090189 RECNO: PROPNO:
REQ BY: DELGADO C&P: WRITTEN: 082289 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 091989

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	435									

JOB DETAIL: REMOVE ASBESTOS INSULATION FROM OUT OF SERVICE STEAM LINES.
SEE ME FOR DETAILS. JERRY D. 2965

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 082889 LAST ACT: N DATE: 092089

005528

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21544 ORIG WR: 00H17011 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: 18 WCAT: SC RW CD: RW RS: DESC: REMOVE GASKET (ASBESTOS)
BLD/UNIT: #2GAS AR: DL WK TP: 4 WANTED: 083089 RECNO: PROPN0:
REQ BY: HODGES C&P: WRITTEN: 083089 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 091989

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	60									

JOB DETAIL: REMOVE GASKETS ON FILTER CASING FOR PREVENTIVE MAINTENANCE.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 090189 LAST ACT: N DATE: 092089

005529

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21632 ORIG WR: 00119923 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS INSULATION
BLD/UNIT: OL-2 AR: OL WK TP: 8 WANTED: 080889 RECNO: PROPNO:
REQ BY: GARCIA C&P: WRITTEN: 080789 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 082389

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	105									

JOB DETAIL: PLEASE REMOVE ASBESTOS INSULATION AND GASKETS FROM C2 KETTLE
PIPING
WILL BE READY FOR MAINT 080889

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 081089 LAST ACT: N DATE: 082489

005530

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REG NO: 00H21648 ORIG WR: 00119587 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: JB WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS
BLD/UNIT: DL-II AR: DL WK TP: 8 WANTED: 091589 RECNO: PROPNO:
REQ BY: BAUER C&P: WRITTEN: 083189 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 091989

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	20									

JOB DETAIL: REMOVE ASBESTOS FROM 1/2" STEAM LINE IN SOUTH CORNER
OF BUILDING 400 - FURNACE SHOP.

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 090589 LAST ACT: N DATE: 092989

005531

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21738 ORIG WR: 00237852 APPROVED BY: R.GECK
DIV/LOC: 500510 ACCOUNT: 220530 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: DH WCAT: SC RW CD: RW RS: DESC: IDENTIFY INSULATION ON TANKS
BLD/UNIT: DOCKS AR: CH WK TP: 8 WANTED: 032790 RECNO: PROPNO:
REQ BY: HANKE C&P: WRITTEN: 032090 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 041090

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	60									

JOB DETAIL: IDENTIFY TYPE OF INSULATION THAT IS ON THE HOT WATER TANKS.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 032890 LAST ACT: N DATE: 052590

005532

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21741 ORIG WR:

APPROVED BY: R.GECK

DIV/LDC: 500511 ACCOUNT: 930000 INDX: 93 1ST ORDER: 00006017 2ND ORD: 04000

PR: B OR: NH WCAT: SC RW CD: RW RS: DESC:

BLD/UNIT: W.FLD AR: CH WK TP: 9 WANTED: 061190 RECNO:

PROPNO:

REQ BY: HANKE

C&P:

WRITTEN: 050390

HWP:

MTAG:

SLIPBL:

SERV:

DWG ATTCH:

SPECS:

FAC CHG:

RESP CD: M0

STATUS: X PLANNER

PLAN CD

ASIS/ENGR:

EST START: 000000

DATE COMPLETE: 053090

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
----	-------	-------	----	-------	-------	----	-------	-------	----	-------	------

IS	350	290									
----	-----	-----	--	--	--	--	--	--	--	--	--

JOB DETAIL: CHECK INSULATION ON ABANDONED PIPE TO BE REMOVED TO SEE IF IT IS
ASBESTOS. SEE N.E. HANKE FOR LINE ID.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0

IND: J CL YR: 90 DATE ENTR: 050890 LAST ACT: N DATE: 060290

005533

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21865 ORIG WR: 00A02115 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: A DR: M2 WCAT: SD RW CD: RW RS: DESC: STRIP ASBESTOS GASKETS
BLD/UNIT: HP-II AR: PL WK TP: 3 WANTED: 081789 RECNO: PROPNO:
REQ BY: R.C.ROSS C&P: WRITTEN: 081789 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 083089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	00									

JOB DETAIL: PLEASE PROVIDE MANPOWER TO STRIP ASBESTOS GASKETS
AS NEEDED.
SHUTDOWN.....

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 082389 LAST ACT: N DATE: 083189

005534

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21899 ORIG WR: 00G79970 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 127200 INDX: 1ST ORDER: 2ND ORD:
PR: D DR: M2 WCAT: SC RW CD: RW RS: DESC: STRIP GASKETS ON OX 1 & 2
BLD/UNIT: OX-II AR: CH WK TP: 8 WANTED: 082989 RECNO: PROPNO:
REQ BY: MIDDLEAUGH C&P: WRITTEN: 082989 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 091989

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	130									

JOB DETAIL: PLEASE SUPPLY MANPOWER TO STRIP ASBESTOS GASKETS ON OXIDE
PIPING TEAROUT.

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 083089 LAST ACT: N DATE: 092089

005535

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H21945 ORIG WR: 00H04121 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 148340 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: M2 WCAT: SD RW CD: RW RS: DESC: STRIP ASBESTOS GASKETS
BLD/UNIT: LPR-1 AR: PL WK TP: 8 WANTED: 091189 RECNO: PROPNO:
REQ BY: R.C.ROSS C&P: WRITTEN: 091189 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 091989
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 240

JOB DETAIL: STRIP ASBESTOS GASKETS AS NEEDED G-1750

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD D/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 091289 LAST ACT: N DATE: 092189

005536

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H22079 ORIG WR: 00237841 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 220530 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: WCAT: RP RW CD: RW RS: DESC: REMOVE INSULATION FROM ACETIC
BLD/UNIT: BARGE AR: CH WK TP: 8 WANTED: 080789 RECNO: PROPNO:
REQ BY: LOWMAN C&P: WRITTEN: 080389 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 082389

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	00	1215	RS	160	00						

JOB DETAIL: PLEASE REMOVE INSULATION FROM AROUND ACETIC ACID UNLOADING POT
ON THE SOUTH EAST CORNER OF THE BARGE DOCKFRONT

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 080889 LAST ACT: N DATE: 100589

005537

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REG NO: 00H22183 ORIG WR: 00H22181 APPROVED BY: BEATTY
DIV/LOC: 500510 ACCOUNT: 008170 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 16 WCAT: RW CD: RA RW RS: DESC: REMOVE INSULATION
BLD/UNIT: ENSYS AR: DL WK TP: 8 WANTED: 010490 RECNO: PROPNO:
REQ BY: D.SIMONS C&P: WRITTEN: 010490 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 011690
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTH
IS 160 385

JOB DETAIL: REMOVE INSULATION ON EXHAUST HEADER ON #7 A/C AT BLDG. 121

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 90 DATE ENTR: 010890 LAST ACT: N DATE: 011890

005538

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H22200 DRIG WR: 00110299 APPROVED BY: GBEATTY

DIV/LOC: 500510 ACCOUNT: 008170 INDX: 1ST ORDER: 2ND ORD:

PR: B DR: 16 WCAT: RW CD: RW RS: DESC: REMOVE GASKET FROM VALVE

BLD/UNIT: ENSYS AR: DL WK TP: 8 WANTED: 040590 RECNO: PROPNO:

REQ BY: D.SIMONS C&P: WRITTEN: 040590 HWP: MTAG: SLIPBL:

SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO

STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000

DATE COMPLETE: 041090

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	20									

JOB DETAIL: REMOVE ASBESTOS GASKET FROM VALVE.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0

IND: J CL YR: 90 DATE ENTR: 040690 LAST ACT: N DATE: 041190

005539

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H22302 ORIG WR: 00H22400 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: A OR: 35 WCAT: US RW CD: RW RS: DESC: STIP ASBESTOS NO. 2
BLD/UNIT: HPR-2 AR: PL WK TP: 8 WANTED: 122889 RECNO: PROPNO:
REQ BY: THOMPSON C&P: WRITTEN: 122889 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 013090

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	395									

JOB DETAIL: NO ENTRY IN THIS SECTION OF ORIGINAL WORK REQUEST.....

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 90 DATE ENTR: 012390 LAST ACT: N DATE: 013190

005540

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H22799 ORIG WR: 00130811 APPROVED BY: J.MOORE
DIV/LOC: 500510 ACCOUNT: 039520 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: NB WCAT: US RW CD: RW RS: DESC: SAMPLE #1 GAS C2H4 COL
BLD/UNIT: OL-I AR: OL WK TP: 8 WANTED: 100290 RECNO: PROPNO:
REQ BY: BEDEE C&P: WRITTEN: 100290 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 100990
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTH:
IS 160 280

JOB DETAIL: SAMPLE INSULATION ON #1 GAS ETHYLENE COLUMN AND PIPING FOR ASBES-
TOS.

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 100390 LAST ACT: N DATE: 102790

005541

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H23244 ORIG WR: 00324100 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 327260 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: M7 WCAT: SE RW CD: RW RS: DESC: REMOVE ASBESTOS
BLD/UNIT: 165 AR: SH WK TP: 8 WANTED: 122889 RECNO: PROPNO:
REQ BY: J.MOLINA C&P: WRITTEN: 122789 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 010390

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	300									

JOB DETAIL: REMOVE ASBESTOS AT 165.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 122889 LAST ACT: N DATE: 010590

005542

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H23490 ORIG WR: 00H74852 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 037220 INDX: 1ST ORDER: 2ND ORD:
PR: A OR: BB WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNIT: HP-II AR: PL WK TP: 8 WANTED: 101290 RECNO: PROPNO:
REQ BY: BLAKE C&P: WRITTEN: 101290 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 101990
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 60

JOB DETAIL:

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 90 DATE ENTR: 101990 LAST ACT: N DATE: 102490

005543

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H23792 ORIG WR: 00272619 APPROVED BY: R.GECK
DIV/LOC: 500510 ACCOUNT: 260940 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: WCAT: SC RW CD: RW RS: DESC: REMOVE ASBESTOS SIDING
BLD/UNIT: WFLD. AR: CH WK TP: 8 WANTED: 053090 RECNO: PROPNO:
REQ BY: LOWMAN C&P: WRITTEN: 010990 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 052190

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	2190	2230									

JOB DETAIL: REMOVE THE TRANSITE SIDING ON THE GLYCOL LOADING RACK SHELTER ON RACK #1, AND ON THE OPERATORS' SHELTER ON THE GROUND NEAR THE LOW PIPE RACK. PLEASE CO-ORDINATE WITH THE CARPENTER'S SHOP SO THAT RE-SIDING WILL OCCUR IMMEDIATELY AFTER OLD SIDING IS REMOVED.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 011090 LAST ACT: N DATE: 061690

005544

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H23983 ORIG WR: 00290904 APPROVED BY: R.GECK
DIV/LOC: 500510 ACCOUNT: 292700 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: 55 WCAT: RW CD: RW RS: DESC: CLEAN GASKETS ON TKS. 904,903
BLD/UNIT: WFLD. AR: CH WK TP: 8 WANTED: 041690 RECNO: PROPNO:
REQ BY: J.MCADAMS C&P: WRITTEN: 041690 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 043090

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	20									

JOB DETAIL: PLEASE CLEAN GASKETS ON MANWAYS TANK 904 & 903.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LABS: 0 YTD MATS: 0
IND: J CL YR: 90 DATE ENTR: 041790 LAST ACT: N DATE: 050190

005545

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H24201 ORIG WR: 00141013 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 094100 INDX: 1ST ORDER: 2ND ORD:
PR: D OR: DS WCAT: RP RW CD: RW RS: DESC: BULK PRIMARY BINS
BLD/UNIT: HPF-1 AR: PL WK TP: 8 WANTED: 053190 RECNO: PROPNO:
REQ BY: D.SHAIN C&P: WRITTEN: 113089 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 051190

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	1800	80	TD	00	60						

JOB DETAIL: FURNISH SCAFFOLDING, EQUIPMENT, LABOR, SUPERVISION & SAFETY INSPEC-
TION TO: DEMOLISH GYPSUM/ASBESTOS/BUILT-UP ROOF DECKING AROUND BASE
OF BINS PER ATTACHED SKETCHES. USES DOUBLE-WRAP POLY BAGS FOR ASB
ESTOS. S/B BIN BASE RING, STIFFENERS, STRUCTURAL STEEL BEAM AND
GUSSETS TO FACILITATE INSPECTION. RECOAT BL

DELIVER TO: ASTED AREAS PCM 201. PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 121289 LAST ACT: N DATE: 070490

005546

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H25368 ORIG WR: 00119500 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: JB WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNIT: OLFUR AR: OL WK TP: 8 WANTED: 090690 RECNO: PROPNO:
REQ BY: J.BAUER C&P: WRITTEN: 090590 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 091290
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 60

JOB DETAIL: REMOVE ASBESTOS GASKETS

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD D/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 090690 LAST ACT: N DATE: 091490

005547

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H25369 ORIG WR: 00119587 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: JB WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNIT: OLFUR AR: OL WK TP: 8 WANTED: 092190 RECNO: PROPNO:
REQ BY: J.BAUER C&P: WRITTEN: 091890 HWP: Y MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 092490

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	120									

JOB DETAIL: REMOVE ASBESTOS GASKETS

DELIVER TO: PHONE :

YTD TOTAL HRS: 0 YTD D/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 091990 LAST ACT: N DATE: 092790

005548

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H25435 ORIG WR: 00H24067 APPROVED BY: TESCH
DIV/LDC: 500510 ACCOUNT: 008170 INDX: 1ST ORDER: 2ND ORD:
PR: A DR: 08 WCAT: EP RW CD: RW RS: DESC: ASBESTOS GASKET REMOVAL
BLD/UNIT: 147 AR: SH WK TP: 8 WANTED: 092989 RECNO: PROPNO:
REQ BY: FOLMAR C&P: WRITTEN: 101089 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 103089
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTH:
IS 160 40

JOB DETAIL: PLEASE REMOVE ASBESTOS GSKET FROM OUTLET FLANGE OF SAFETY VALVE.

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 101089 LAST ACT: N DATE: 103189

005549

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H26917 ORIG WR: 00116400 APPROVED BY: WTH
DIV/LDC: 500510 ACCOUNT: 025100 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: US RW CD: RW RS: DESC: SCRAPE ASBESTOS GASKET
BLD/UNIT: B-500 AR: OL WK TP: 4 WANTED: 113089 RECNO: PROPNO:
REQ BY: NEILL C&P: WRITTEN: 112889 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 112989

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	110									

JOB DETAIL: NO ENTRY

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 112989 LAST ACT: N DATE: 120589

005550

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H27001 ORIG WR: 00119900 APPROVED BY: JMOORE
DIV/LOC: 500510 ACCOUNT: 025500 INDX: 1ST ORDER: 2ND ORD:
PR: A OR: 18 WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS INSUL. ON S/G
BLD/UNIT: #2GAS AR: OL WK TP: 8 WANTED: 121389 RECNO: PROPNO:
REQ BY: HODGES C&P: WRITTEN: 121389 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 122089

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	80	PA	00	340						

JOB DETAIL: REMOVE ASBESOTS INSULATION ON SIGHT GLASS.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 121489 LAST ACT: N DATE: 122189

005551

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H27031 ORIG WR: 00119500 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: C OR: 18 WCAT: US RW CD: RW RS: DESC: CK VALVE VD UNIT
BLD/UNIT: #2GAS AR: OL WK TP: 8 WANTED: 122989 RECNO: PROPNO:
REQ BY: HODGES C&P: WRITTEN: 122989 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 010390

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	40									

JOB DETAIL: SCRAPE ASBESTOS GASKET 3" CK VALVE

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 122989 LAST ACT: N DATE: 010590

005552

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H27068 ORIG WR: 00130970 APPROVED BY: JMOORE
DIV/LDC: 500510 ACCOUNT: 039520 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 18 WCAT: US RW CD: RW RS: DESC: ASBESTOS REMOVAL FLARE TOWER
BLD/UNIT: #1GAS AR: OL WK TP: 8 WANTED: 011090 RECNO: PROPNO:
REQ BY: HODGES C&P: WRITTEN: 010990 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: M0
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 011690

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	60									

JOB DETAIL: REMOVE ASBESTOS INSULATION FROM PIPE & FLARE TOWER.

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 011090 LAST ACT: N DATE: 011890

005553

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H27088 ORIG WR: 00119537 APPROVED BY:
DIV/LDC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: JB WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNIT: OLFUR AR: OL WK TP: 8 WANTED: 030890 RECNO: PROPNO:
REQ BY: J.BAUER C&P: WRITTEN: 030890 HWP: Y MTAG: N SLIPBL: Y
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 031490

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTH
IS	160	60									

JOB DETAIL: REMOVE ASBESTOS GASKET FROM PIPE.

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 90 DATE ENTR: 031090 LAST ACT: N DATE: 031590

005554

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H28056 ORIG WR: 00H39722 APPROVED BY: WTH
DIV/LOC: 500510 ACCOUNT: 220040 INDX: 1ST ORDER: 2ND ORD:
PR: B DR: M2 WCAT: RP RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNIT: NF AR: WK TP: 8 WANTED: 122889 RECNO: PROPNO:
REQ BY: MIDDLEAUGH C&P: WRITTEN: 122889 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 010390

RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR	RC	ESTHR	ACTHR
IS	160	80									

JOB DETAIL: PLEASE REMOVE ASBESTOS GASKETS ON 3" DRINKING WATER LINE

DELIVER TO:

PHONE :

YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 89 DATE ENTR: 122889 LAST ACT: N DATE: 010590

005555

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H28059 ORIG WR: 00H25582 APPROVED BY: DAN
DIV/LOC: 500510 ACCOUNT: 004310 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: 29 WCAT: SC RW CD: RW RS: DESC: REMOVE INSULATION
BLD/UNIT: ENSYS AR: OL WK TP: 4 WANTED: 011290 RECNO: PROPNO:
REQ BY: HAIRELL C&P: WRITTEN: 011090 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 011690
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 80

JOB DETAIL: REMOVE INSULATION

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD O/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: I CL YR: 90 DATE ENTR: 011090 LAST ACT: N DATE: 011890

005556

NAME: _____ NUMBER: _____ PAGER: _____

*** WORK REQUEST ***

WORK REQ NO: 00H28204 ORIG WR: 00119528 APPROVED BY:
DIV/LOC: 500510 ACCOUNT: 025200 INDX: 1ST ORDER: 2ND ORD:
PR: B OR: KB WCAT: US RW CD: RW RS: DESC: REMOVE ASBESTOS GASKETS
BLD/UNIT: AR: DL WK TP: 8 WANTED: 092589 RECNO: PROPNO:
REQ BY: J.BAUER C&P: WRITTEN: 092589 HWP: MTAG: SLIPBL:
SERV: DWG ATTCH: SPECS: FAC CHG: RESP CD: MO
STATUS: X PLANNER PLAN CD ASIS/ENGR: EST START: 000000
DATE COMPLETE: 100389
RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR RC ESTHR ACTHR
IS 160 15

JOB DETAIL: REMOVE ASBESTOS GASKETS #8 FURNACE.

DELIVER TO: PHONE :
YTD TOTAL HRS: 0 YTD D/T: 0 YTD LAB\$: 0 YTD MAT\$: 0
IND: J CL YR: 89 DATE ENTR: 092789 LAST ACT: N DATE: 100689

005557