

Match Master.

Part of sand system to
collector - part to roof fans.
Several conveyors not hooked
or routed through.

Pick off man cooler overhanging
coll. hood which vents to atm.

Moldmaster

Many sand syst. panels removed
Shakeout not efficient - pick off
men out of cage.

pouring hoods in wrong position
- well after pour ends.



10/9/91

~~Harold~~ Tapp
Harold
Wayne

Bob Wilson
John Wilson

North Plant

Core Runs a problem —
direct exh.

Open Alcohol Dip

PRF Wheel a typical problem

LD Blow Out enclosure
too open — hand grinder
works inside enclosure,
Manual blow off

All safety items — labels, air block
off, needles, signs, etc., etc.
Text box labels,

Send:

- ① Maint. Pgm — To JM
- ② Database Info. — to CK
- ③ Core Info to CK
- ④ Iniboflow

G 00479