

J. J. McClellan

COM (NAME & LOCATION)

J. J. McClellan - O-11

DATE October 22, 1981 T. Ozarchuk
 SUBJECT Minutes of the Hourly Safety Committee M. Riddle
 Meeting - September 29, 1981 PMSB
 SHAC

REFERENCE

Present 10/27/81
 ✓ W. E. Bean (Chairman) - SS-4
 ✓ J. M. Burkhalter - SS-10
 ✓ L. E. Derrick - AB
 Lawrence Elbert - 35F
 ✓ Clarence Jackson - 51D
 James H. Martin - 2PD
 ✓ Ruby Mosley - SS-22
 ✓ Carl Richardson - 19D
 R. L. Sartain - SS-12

George Danner, Superintendent, Plant Services, talked to the group about procedures. Briefly, he emphasized how everyone has a responsibility in helping establish safe procedures as well as seeing that those already established are followed. In the general discussion that followed, the AVIP program and a new video tape for training contractors were discussed.

UNFINISHED BUSINESS

HCN Alarms

- The HCN alarm and blue lights near the HCN storage tanks are not being observed by traffic as emergency lights.

This problem is recognized by unit supervision and corrective action is being planned.

changed test alarm to Monday @ 1:00pm.

Dock 1 TV - Remote Operated Gate

- The remote operated gate of dock 1 was reported to be a hazard.

This discussion was postponed due to the absence of M. Riddle.
(Firetruck access to Dock 1 through gates?)

Warehouse A

- The pipe storage and overhead crane represent hazards.

Warehouse A supervision reported that they did not know why this was a hazard. This discussion was postponed due to the absence of J. M. Burkhalter, the originator of the safety hazard statement.

NEW BUSINESS

LAM014211

Fresh Air Masks - Glasses

- The use of fresh air masks without glasses was brought up as a problem.

A. Glass stated that glasses that will fit in the masks can be obtained through Safety Supply.

(your supervisor)

SC

12994

SHOW VIDEOTAPE NEXT MTG.

MB

- 45° ANGLE FOR PIPE RACK AT W.W.S.E. A
- LOADING OF PIPE

NEW BUSINESS:

→ 15' & pipe not let off for BBQ
North WOB @ 51 - leak - "pinnet"

SC

12995

LAM014212

Tarps - Welding

- Tarps used to catch sparks are resulting in fires.

This is recognized as a plant problem. Fireproof tarps are being investigated. In the meantime, all tarps used to catch sparks should be wet down before leaving.


Safety Meetings

- The HSC was going to develop a list of suggestions for improving safety meetings.

This was postponed due to the absence of W. E. Bean.

The next HSC meeting will be held October 27, 1981, at 1:30 p.m. in the Personnel Building Conference Room 2.

The guest speaker will be S. G. Pappas.


J. J. McClellan

SC

12996

LAM014213

#SC

9/29/81
@ 1330

G. DANNER
PLANT PROCEDURES - TALK, COMMENTS
TANK INSPECTION PROGRAM

NEW } Mosley OPER. CARRYING KCN SAMPLES WITHOUT A 5 MIN. ASK
BUSINESS } Mosley HAVE A PART TIME JANITOR IN CONT. LAB. (CANS IN
HOODS FILLED TO TOP, EXCESS DIRTY GLASSWARE ON
CARTS)

DANNER - MEMBERS SHOULD SELL SAFETY TO OTHERS
ON A ONE TO ONE BASIS

DERRICK CAMERA AT GATE AT DOCK #1

&
SARTAIN GATE CLOSED ON BIKE GET SARTAIN & DERRICK
TO GO WITH RIDDLE AND VIEW
PROBLEM

RICHARDSON - READ A LETTER FROM A SURVEY IN HIS UNIT
ON HOW TO IMPROVE SAFETY MEETINGS AND
THE PROBLEMS WITH THE CURRENT MEETINGS.

SC

12997

LAM014214