

**SECTION VII - Precautions for Safe Handling and Use****Steps to Be Taken in Case Material is Released or Spilled**

Grinding, drilling, milling, etc. can result in the release of airborne dust. Measures as outlined in Section VIII should be followed if this occurs.

**Waste Disposal Method**

Asbestos: Per 40 CFR, Part 61, 29 CFR, Part 1910.1001.

Other Hazardous Ingredients: Per 40 CFR, Part 261, 262 and applicable State and Local regulations.

**Other Precautions**

Pre-employment screening for allergies and histories of skin sensitivities may be beneficial in determining persons sensitive to cashew materials.

**SECTION VIII - Control Measures**

**Respiratory Protection (Specify Type)** NIOSH approved for pneumoconiosis - fibrosis producing dusts and dusts with TLV not less than 0.05 mg/M<sup>3</sup>.

|                    |                             |                                                                  |
|--------------------|-----------------------------|------------------------------------------------------------------|
| <b>Ventilation</b> | <b>Local Exhaust</b>        | For dust exposures exceeding TLV.                                |
|                    | <b>Mechanical (General)</b> | Not recommended for dust exposures.                              |
|                    | <b>Special</b>              | NK                                                               |
|                    | <b>Other</b>                | Barrier creams for persons with skin sensitive to cashew resins. |

**Protective Gloves**

Recommended for persons with skin sensitive to cashew resins.

**Eye Protection**

Should not be needed for normal handling of product. Eye protection is good practice where dust is propelled by grinding or drilling activities.

**Other Protective Clothing or Equipment**

Long sleeved shirts or other protective clothing may be beneficial to prevent skin contact of persons sensitive to cashew resins.

**Work/Hygienic Practices**

Employees should be properly instructed in the use of control measures as indicated above when there is a need for it. If dust from this product is produced, unnecessary exposures should be avoided by using a vacuum in place of dry brooming. Use wet method of cleaning for other surfaces. Proper and adequate personal hygiene should be practiced by exposed workers.

NA - Not Available

NK - Not Known